

Effective: 23/01/2023 to 23/01/2024

Asset Number: 1000.00 to 1999.00

Display Action Officer: No

Site: LINDSEY STREET (13800788)

Site: LINDSEY STREET (13800788)

Locality: EPPING TOWN, EPPING, ESSEX

Area: Epping

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	13800788_1000 - B181	Feature Type:	PR2 Road		Area: Epping	
Batch:	7002422 - Inspection Batch			Route:	adhoc route			Date: 17/11/2023
3758553	RA 16=4x4. C/w defect/p/h approx 1m x 1.2m x 150mm in places	17/11/2023	Approx 70m before Bury Lane/Epping Road junction	HW: carriageway defect	Internal		Committed	2357962
Batch:	6994752 - Inspection Batch			Route:	Area 17 Jan/Apr/Jul/Oct Driven			Date: 13/10/2023
3748875	RANSA4 = 1 X 4 chevron sign damaged and facing the wrong way	13/10/2023	As mapped	HW: roadsign damaged	Internal		Action Required	
3748876	RANSA4 = 1 X 4 Road sign leaning over by 45%	13/10/2023	As mapped	HW: roadsign damaged	Internal		Action Required	
Batch:	6976367 - Inspection Batch			Route:	Area 17 Jan/Apr/Jul/Oct Driven			Date: 28/07/2023
	No actionable defects found							
Batch:	6974903 - Inspection Batch			Route:	adhoc route			Date: 24/07/2023
3727423	Ra4 1x4 overgrown veg 25m x 1.8m x 0.5m on a 1.5m fwy	24/07/2023	Os2	HW: overgrown vegetation (our)	Internal		Action Required	
Batch:	6966889 - Inspection Batch			Route:	Area 17 Annual Sep Driven			Date: 19/06/2023
	No actionable defects found							
Batch:	6951794 - Inspection Batch			Route:	adhoc route			Date: 23/04/2023
3704206	Nsra cover stivking up passed to gang dv23041045	23/04/2023	On hill	HW: surface cover mis-aligned	Internal		Committed	2346622
Batch:	6946940 - Inspection Batch			Route:	adhoc route			Date: 03/04/2023
3698664	Ra9 3x4 cway defect 1m x 0.5m x 120mm nsmm	03/04/2023	Os 169	HW: carriageway defect	Internal		Committed	2345636
Batch:	6934507 - Ad Hoc Inspection Batch			Route:	adhoc route			Date: 01/02/2023
3684119	Member led pothole project, 1 x c/w defect around gully & replace 1 x broken c/w gully	01/02/2023	Opposite give way sign just before bend	HW: carriageway defect	Internal		Committed	2342312

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1,000.00	Asset - Locn.:	13800788_1000 - B181	Feature Type:	PR2 Road		Area: Epping
2296665	Ra1=1x1 10m x 1m x 100mm (HW: verge damaged)	Opp the pump house	HW: Street S4	job raised	08/04/2020		
2297743	Gateway Feature & Sigange	B181 Lindsey Street	HW: Capital Scheme	job raised	29/04/2020		
2342312	Member led pothole project, 1 x c/w defect around gully & replace 1 x broken c/w gully (HW: carriageway defect)	Opposite give way sign just before bend. W3W location - armed.tools.oiled	HW: Street S3	Quality audit passed	01/02/2023	10/05/2023	Act. EH/1657093
2345636	Ra9 3x4 cway defect 1m x 0.5m x 120mm nsmm (HW: carriageway defect)	Os 169	HW: Street S2 PR1/2	works completed	03/04/2023	04/04/2023	Act. EH/1657356

Effective: 23/01/2023 to 23/01/2024

Asset Number: 1000.00 to 1999.00

Display Action Officer: No

Site: LINDSEY STREET (13800788)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: 13800788_1000 - B181		Feature Type: PR2 Road		Area: Epping	
2346622	Nsra cover stivking up passed to gang dv23041045 (HW: surface cover mis-aligned)	On hill	HW: Street S1	works completed	23/04/2023	23/04/2023	Act. EH/1658324
2357962	RA 16=4x4. C/w defect/p/h approx 1m x 1.2m x 150mm in places (HW: carriageway defect)	Approx 70m before Bury Lane/Epping Road junction	HW: Street S1	works completed	17/11/2023	17/11/2023	Act. EH/1666843