

19/04/2024

Enquiry Trace Form

Enquiry:	2914038	Logged by: CRM Connector	on 18/04/2024 15:44										
Service:	Public Rights of Way	Classification: enforcement											
Subject:	obstruction of PRow												
Desc.:	Customer Selection=Muddy or boggy,footpath both sides of the lower part of Marsh Farm Road, though only one is designated a footpath, that of no 53												
Site: footpath 53 South Woodham Ferrers (FP 53 298), Query, Essex Site Address: Location: This footpath has deteriorated to the level it uneven and impassable according to reports from residents. They are being made to use the road, and someone has been knocked down by a car as a result. Reported to SWF Town Council by residents Site Notes: SMO2 - Chelmsford //													
Current Status: <table border="1"> <thead> <tr> <th>No.</th> <th>Effective</th> <th>Status</th> <th>Officer</th> <th>Follow up Date</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>18/04/2024 16:27:36</td> <td>not at investigatory level</td> <td>Redacted</td> <td></td> </tr> </tbody> </table> Notes: Surveyed by LJD 18.4.24. Surface of footpath is in suitable condition use with no section's meeting investigatory levels.				No.	Effective	Status	Officer	Follow up Date	2	18/04/2024 16:27:36	not at investigatory level	Redacted	
No.	Effective	Status	Officer	Follow up Date									
2	18/04/2024 16:27:36	not at investigatory level	Redacted										
Status history: <table border="1"> <thead> <tr> <th>No.</th> <th>Effective</th> <th>Status</th> <th>Officer</th> <th>Notes</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>18/04/2024 15:44:44</td> <td>awaiting inspection</td> <td>Redacted</td> <td></td> </tr> </tbody> </table>				No.	Effective	Status	Officer	Notes	1	18/04/2024 15:44:44	awaiting inspection	Redacted	
No.	Effective	Status	Officer	Notes									
1	18/04/2024 15:44:44	awaiting inspection	Redacted										
Attributes: <table border="1"> <thead> <tr> <th>Parameter</th> <th>Value</th> </tr> </thead> <tbody> <tr> <td>Feedback to Customer</td> <td>This issue has now been inspected. The surface of footpath is in a suitable condition for use with no sections meeting investigatory levels.</td> </tr> </tbody> </table>				Parameter	Value	Feedback to Customer	This issue has now been inspected. The surface of footpath is in a suitable condition for use with no sections meeting investigatory levels.						
Parameter	Value												
Feedback to Customer	This issue has now been inspected. The surface of footpath is in a suitable condition for use with no sections meeting investigatory levels.												

Revised Status:

Name : Signed : Date : Time :