

Effective: 22/04/2019 to 24/05/2023

Asset Number: 1000.00 to 1999.00

Display Action Officer: No

Site: KETTLEBURY WAY (13800737)

Site: KETTLEBURY WAY (13800737)

Locality: ONGAR TOWN, ONGAR, ESSEX

Area: Ongar

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	13800737_1000 - ZU20662	Feature Type:	Local Road		Area: Ongar	
Batch:	6961878 - Inspection Batch			Route:	Area 17 Annual May Walked			Date: 24/05/2023
3714408	Ra3 3x1 misaligned kerb 0.9m x0.0120m x 40mm nsmm	24/05/2023	Os23	HW: kerb mis-aligned	Internal		Action Required	
3714407	Ra3 3x1 misaligned kerb 0.9m x0.0120m x 25m nsmm	24/05/2023	Os 15	HW: kerb mis-aligned	Internal		Action Required	
3714405	Ra3 3x1 misaligned kerb 0.9m x0.0120m x 25m nsmm	24/05/2023	Jw woodland wayb	HW: kerb mis-aligned	Internal		Action Required	
3714409	Ra6 3x2 misaligned kerb 0.9m x0.0120m x 25m nsmm	24/05/2023	Os 62	HW: kerb mis-aligned	Internal		Action Required	
3714406	Ra4 1x4 sign dirty	24/05/2023	Post 13	HW: roadsign damaged	Internal		Action Required	
3714410	Ra6 3x2 misaligned kerb 0.9m x0.0120m x 25m nsmm	24/05/2023	Os62	HW: kerb mis-aligned	Internal		Action Required	
3714411	Ra2 2x1 misaligned gully 0.5m x 0.5m x 27mm nsmm	24/05/2023	Os9m	HW: surface cover mis-aligned	Internal		Action Required	
Batch:	6880590 - Inspection Batch			Route:	Area 17 Annual May Walked			Date: 17/06/2022
	No actionable defects found							
Batch:	6799303 - adhoc route			Route:	adhoc route			Date: 22/10/2019
3547276	Blocked Connection	22/10/2019	Carriageway	HW: blocked gully connection	Internal		Action Required	
Batch:	6797594 - Inspection Batch			Route:	Area 36 Annual May Walked			Date: 12/05/2021
	No actionable defects found							
Batch:	6711989 - Inspection Batch			Route:	Area 36 Annual May Walked			Date: 07/05/2020
	No actionable defects found							
Batch:	6623379 - Inspection Batch			Route:	Area 36 Annual May Walked			Date: 03/05/2019
3363861	Ra4 2x2 misaligned gully cover and frame 20mmupstand	01/05/2019	Oppo 36	HW: surface cover mis-aligned	Internal		Committed	2300036
3363868	Ra9 3x3 misaligned kerbs 1.9mts	01/05/2019	Os18	HW: kerb mis-aligned	Internal		Committed	2277294
3365419	Ra6 2x3 cway defect 400mmx800mmx55mm nsmm	01/05/2019	Oppo 10	HW: carriageway defect	Internal		Action Required	

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1,000.00	Asset - Locn.:	13800737_1000 - ZU20662	Feature Type:	Local Road		Area: Ongar
2277294	misaligned kerbs (Make safe)	Os18	HW: Street S2	works completed	02/05/2019	09/05/2019	Act. EH/1603114
2300036	Replace Kerb Inlet Gully Cover and Frame	Oppo 36	HW: Street S3	works completed	12/06/2020	09/07/2020	Act. EH/1620930