Effective: 20/11/2022 to 21/11/2023

Service: Maintenance Category: Apparatus

Site: CARTERS HILL (41400209)

Asset Number: 1000.00 to 1000.00

Subject: defective surface cover (COV)

Display Action Officer: No

Site: CARTERS HILL (41400209) Locality: MANUDEN, ESSEX Area: Manuden

Defect No: Description Log Date Location **Defect Type** Class. Organisation **Status** Job No. 1,000.00 Asset - Locn.: 41400209 1000 - ZC10056 // From The Street to o/s 41 Feature Type: PR2 Road Area: Manuden Asset: Batch: 6967061 - Inspection Batch Date: 20/06/2023 3719250 RA16 = 4 x 4 eroded surface affected area 20/06/2023 Os entrance to farm and opposite 21 HW: carriageway defect Internal Committed 2350675 approx 1.1 x 2.5 x 102mms centrally Batch: 6947273 - Inspection Batch Route: adhoc route Date: 04/04/2023 3698980 RA16 = 4 x 4 C/W P/H 1.2m x 0.5m x 04/04/2023 Outside Manuden Primary School HW: carriageway defect Internal Committed 2345772 10mm at the deepest point

3698979 RA16 = 4 x 4 C/W P/H 1.2m x 1m x 10mm 04/04/2023Outside no 11 HW: carriageway defect Internal Committed 2345771

Route: adhoc route

at the deepest point

Batch: 6947272 - Inspection Batch

Batch: 6937355 - Inspection Batch Route: Area 07 Feb/May/Aug/Nov Walke Date: 14/02/2023 3686952 Ra4 = 1x4 erosion 0.75m x 0.3m x 50mm 14/02/2023 Outside no 12 next to the school Internal No Action Required HW: carriageway defect 3686953 RESOLVED 14/02/2023 Opp entrance to farm. HW: blocked gully Internal No Action Required

Batch: 6929466 - Inspection Batch Route: adhoc route Date: 06/01/2023 $3678680 \text{ RA}16 = 4 \times 4 \text{ eroded surface pothole } 1.4 \times 06/01/2023 \text{ O s } 11$ HW: carriageway defect Internal Committed 2340824

0.9 x 162mms in parts. Has a cone in it.

Batch: 6927452 - Ad Hoc Inspection Batch Route: adhoc route Date: 19/12/2022 3677008 RANSA - Carriageway Pothole around 19/12/2022 Outside School HW: carriageway defect Internal Committed 2340824

gully - 1.0 x 1.0 x 100mm Batch: 6923769 - Inspection Batch Route: Area 07 Feb/May/Aug/Nov Walke

3674417 RA2 =1x2 Opposite 11 The Street, CM23 1DE, 01/12/2022 Footway eroding on front edge ge

3m x 0.3m x upto 20mm

England, United Kingdom

HW: footway defect

Internal

Action Required

Date: 04/04/2023

Date: 01/12/2022

Customer Services

Condition Survey

Logged by: CRM Connector on: 20/11/2023 12:55 **Enquiry No.: 2879982** Subject: defective surface cover Classification: fault reports Service: Maintenance

Desc.: RM CALLER STATES: Postman has fallen down open manhole cover - has tried to put it back but its too heavy - completely open, opposite driveway to 22-24 Carters Hill, INJURIES SUSTAINED.

Location: **150** Opp 22-24 Cartes Hill, Manuden, Uttelsford - on the green opposite the Contact:

driveway for 22/24 Carters Hill.

Maintenance Management

| Job No. | Descriptio | n | Location | Priority | Job Status | Entered | Completion | Works Order |
|---------|-------------|----------------------|---|---------------------------|------------------------|------------|----------------|--------------|
| | Asset: | 1,000.00 | Asset - Locn.: 41400209_1000 - ZC10056 // | From The Street to o/s 41 | Feature Type: PR2 Road | | Area: Manuden | |
| 234017 | 5 Members L | ed Pothole Project - | - Opposite School (Outside house | HW: Street S3 | works completed | 19/12/2022 | 30/06/2023 Act | . EH/1653415 |

Carriageway Patching x 1 -

no 11)

100mm Depth - 10mm DBM -Total area = 4.56m2

Effective: 20/11/2022 to 21/11/2023

Asset Number: 1000.00 to 1000.00

Subject: defective surface cover (COV)

Category: Apparatus

Service: Maintenance

Display Action Officer: No

Site: CARTERS HILL (41400209)

| Mainten | ance Ma | ınagement | | | | | | | |
|---|-------------|---|--|------------------------|---|------------|-----------------|--|--|
| Job No. | Descripti | on | Location | Priority | Job Status | Entered | Completion | Works Order | |
| | Asset: | 1,000.00 | Asset - Locn.: 41400209_1000 - ZC10056 // From | n The Street to o/s 41 | Feature Type: PR2 Road | | Area: Manuden | | |
| 2340824 | pothole 1. | x 4 eroded surface 4 x 0.9 x 162mms in s a cone in it. (HW: ay defect) | O s 11 | HW: Street S1 | works completed | 06/01/2023 | 06/01/2023 Act. | EH/1653266 | |
| 2345771 | 1m x 10m | x 4 C/W P/H 1.2m x m at the deepest poi iageway defect) | Outside no 11 nt | HW: Street S1 | works completed | 04/04/2023 | 04/04/2023 Act. | EH/1657458 | |
| 2345772 | 0.5m x 10 | x 4 C/W P/H 1.2m x mm at the deepest : carriageway defect) | Outside Manuden Primary School | HW: Street S1 | works completed | 04/04/2023 | 04/04/2023 Act. | EH/1657459 | |
| 2350675 | affected a | x 4 eroded surface rea approx 1.1 x 2.5 centrally (HW: ay defect) | O s entrance to farm and opposite 21 | HW: Street S1 | made safe | 20/06/2023 | 20/06/2023 Act. | EH/1660835 | |
| Street V | Vorks Ins | spections | | | | | | | |
| Organisa | ation: Esse | ex County Council - W | /ork Promoter (1585201) (ESSEX COUNTY COUN | CIL - HIGHWAY AUTH) | | | | | |
| Works | Ref: PS2 | 0112023145032 | | | | | | | |
| Group No: 1 Site No: 1 Category: Apparatus Defect Notif. No: 633652 | | paratus | Street Authority: Essex County Council - Work Promoter Outcome: Failed (Higher Risk/Dangerous) Defect No: 633652 Tel: 01279 642500 | | Inspected: 20/11/2023 14:50:32 Sampled: No Site Informed: Yes Site Location: On verge o s 22 Carters Hill | | • | Sampled Site No: a./Guard. Inadequacy: No | |
| • | Notes: | | | | Position: Carriageway | | Site Post | Code: | |
| Works | Ref: PS2 | 0112023150044 | | | | | | | |
| Group No: 1 Site No: 1 Category: Apparatus Defect Notif. No: 633655 | | paratus | Street Authority: Essex County Council - Work Promoter Outcome: Failed (Higher Risk/Dangerous) Defect No: 633655 Tel: 01279 642500 | | Inspected: 20/11/2023 15:00: Sampled: No Site Informed: Yes Site Location: On verge opposite | Sign./Li | | quacy: No | |
| • | Notes: | | | | Position: Carriageway | | Site Post | Code: | |