

Batch: 7126819 to 7126819

Report Type: Assessment

Site: WORKERS ROAD (13802633)

Area: Matching

Asset No: 1,000.00

Asset Id - Location: 13802633\_1000 - For further history see USRN 13802608

Feature Type: PR2 Road

District: Epping Forest

Batch: 7126819 - Inspection Batch

Route: Area 18 Jan/Apr/Jul/Oct Driven

Officer: [REDACTED]

Date: 11/04/2025

Observation Type	Code	Grade	Score	Notes
Carriageway Excellent	CWQE	0%	.0000	
Carriageway Good	CWQG	20%	.0000	
Carriageway Fair	CWQF	50%	.0000	
Carriageway Requires Improvement	CWQS	30%	.0000	
cycleway condition	CYCN	Not Applicable	.0000	
surface state	SSTT	dry	.0000	Driven 10/04/25 Reviewed 11/04/25 By [REDACTED]
Footway Presence	FWPC	none present	.0000	
Footway Excellent	FFQE	0%	.0000	
Footway Good	FFQG	0%	.0000	
Footway Fair	FFQF	0%	.0000	
Footway Requires Improvement	FFQS	0%	.0000	
Reduced inspection	RI	Assessed	.0000	
Re-inspection required	RR	Not Applicable	.0000	

Defect No.	Description	Log Date	Location	Type	Organisation	Status
3889311	RANSA 9 = 3 x 3, cw eroded approx 3.5m x 1.5m x >90mm	11/04/2025	opp church farm	CWDF		Committed
3889310	RANSA 2 = 2 x 1, cw eroded at edge 1500mm x 600mm x >50mm	11/04/2025	LON: 0.20473849773406982, LAT: 51.75864791870117; DETAILS: approx 100m from church farm	CWDF		Unactioned