

Effective: 16/04/2024 to 16/04/2025
Site: WORKERS ROAD (13802633)

Display Action Officer: No

Site: WORKERS ROAD (13802633)	Locality: HIGH LAVER, ONGAR, ESSEX	Area: Matching
-------------------------------	------------------------------------	----------------

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	13802633_1000 - For further history see USRN 13802608		Feature Type: PR2 Road		Area: Matching	
Batch: 7126819 - Inspection Batch			Route: Area 18 Jan/Apr/Jul/Oct Driven				Date: 11/04/2025	
3889311	RANSA 9 = 3 x 3, cw eroded approx 3.5m x 1.5m x >90mm	11/04/2025	opp church farm	HW: carriageway defect	Internal		Committed	2387920
3889310	RANSA 2 = 2 x 1, cw eroded at edge 1500mm x 600mm x >50mm	11/04/2025	LON: 0.20473849773406982, LAT: 51.75864791870117; DETAILS: approx 100m from church farm	HW: carriageway defect	Internal		Action Required	
Batch: 7107321 - Inspection Batch			Route: Area 18 Jan/Apr/Jul/Oct Driven				Date: 22/01/2025	
No actionable defects found								
Batch: 7081846 - Inspection Batch			Route: Area 18 Jan/Apr/Jul/Oct Driven				Date: 11/10/2024	
3843269	RANSA 4 = 1 x 4, 60 % obscured. give way warning sign obscured by veg	11/10/2024	LON: 0.2096825, LAT: 51.755806; DETAILS: at jw matching rd	HW: roadsign obscured or dirty	Internal		Action Required	
Batch: 7056388 - Inspection Batch			Route: Area 18 Jan/Apr/Jul/Oct Driven				Date: 25/07/2024	
3815579	RANSA 4 = 1 x 4, 95 % missing. centre white lining worn 95%	25/07/2024	opp tilegate farm	HW: worn or missing road mark	Internal		Action Required	
3815571	RANSA 6 = 2 x 3, >3.5m x >1m x >50mm	25/07/2024	opp church farm	HW: carriageway defect	Internal		No Action Required	
3815747	Ra4 = 1x4 junction rd markings worn 95%	25/07/2024	Jw high laver x rds	HW: worn or missing road mark	Internal		Action Required	

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1,000.00	Asset - Locn.:	13802633_1000 - For further history see USRN 13802608		Feature Type: PR2 Road		Area: Matching
2387920	RANSA 9 = 3 x 3, cw eroded approx 3.5m x 1.5m x >90mm (HW: carriageway defect)	opp church farm	HW: Street S2 PR1/2	made safe	11/04/2025	15/04/2025	Act. EH/1692158