

Effective: 27/05/2024 to 27/05/2025

Display Action Officer: No

Site: SHEERING LOWER ROAD (13801217)

Site: SHEERING LOWER ROAD (13801217)			Locality: SHEERING, HARLOW, ESSEX			Area: Sheering		
Condition Survey								
Defect No: Description		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: 13801217_1000 - ZU10469		Feature Type: Local Road		Area: Sheering		
Batch: 7130370 - Inspection Batch			Route: adhoc route			Date: 29/04/2025		
3892929	RA 8 = 2 x 4, cw eroded beside edgeline. Approx 0.9m x 0.5m x 80mm. Defect is filled with sewer water from a blocked manhole. Thames Water are attending site this Tuesday 29th to resolve ref - 01103721.	29/04/2025	Opp s/o 5	HW: carriageway defect	Internal		Committed	2388615
Batch: 7105169 - Inspection Batch			Route: adhoc route			Date: 09/01/2025		
3867461	RANSA 4 = 1 x 4 vegetation encroaching carriageway, obscuring warning sign >90%	09/01/2025	From new house farm to the chevron sign where the road narrows (approx 100m) heading toward harlow	HW: overgrown vegetation (ext)	Internal		Action Required	
Batch: 7105167 - Inspection Batch			Route: adhoc route			Date: 09/01/2025		
3867459	RANSA 4 = 1 x 4 1 no entry sign obscured by veg >90%	09/01/2025	at one-way road connecting sawbridgeworth road onto lower sheering road	HW: roadsign obscured or dirty	Internal		Action Required	
Batch: 7077399 - Inspection Batch			Route: adhoc route			Date: 30/09/2024		
3838474	RANSA 4 = 2 x 2, cw eroded at edge , 20m x 400mm x >50mm	30/09/2024	LON: 0.1601818, LAT: 51.8033638; DETAILS: just after giveway bit, approaching harlow	HW: carriageway defect	Internal		Action Required	
Batch: 7077398 - Inspection Batch			Route: adhoc route			Date: 30/09/2024		
3838473	RANSA 4 = 2 x 2, cw eroded at edge , 2000mm x 400mm x >50mm	30/09/2024	LON: 0.1601818, LAT: 51.8033638; DETAILS: just after giveway bit, approaching harlow	HW: carriageway defect	Internal		No Action Required	
Batch: 7068914 - Inspection Batch			Route: Area 17 Annual Aug Walked			Date: 19/09/2024		
3835201	RANSA 4 = 1 x 4, % obscured. Road narrowing sign obscured approx 50% by overgrown vegetation. , 0mm x 0mm	19/09/2024	LON: 0.1607722, LAT: 51.8038979; DETAILS: Adj Newhouse Farm	HW: roadsign obscured or dirty	Internal		Action Required	
3828453	RA9 = 3 x 3, 2 x FW erosion on kerbside, approx 1.1 x 0.6m x 70 mm at deepest.	30/08/2024	O/s 130 & 132	HW: footway defect	Internal		Committed	2374262
3828323	RA 4 = 1 x 4, Hatching, Double/Single junction & centre line markings faded by approx 90%.	30/08/2024	Jw Hallingbury Rd	HW: worn or missing road mark	Internal		Action Required	
3835218	RANSA 4 = 2 x 2, CW eroded at the edge., 400mm x 200mm x >50mm	19/09/2024	LON: 0.1585524, LAT: 51.7952805; DETAILS: Adj access to Aylmers Farm	HW: carriageway defect	Internal		Action Required	
3834795	RA 8 = 4 x 2, 2 x cw deep erosion at edge, approx 1m x 0.5m x 100mm deep. NSMM.	18/09/2024	Btn Newhouse Farm and Allbrook House	HW: carriageway defect	Internal		Committed	2375237
3834793	RA 8 = 4 x 2, cw deep erosion at edge, approx 2m x 0.7m x 150mm deep. NSMM.	18/09/2024	Adj Newhouse Farm	HW: carriageway defect	Internal		Committed	2375235
3834797	RA 8 = 4 x 2, Multiple cw deep erosion at edge, approx average 1m x 0.5m x 120mm at deepest. NSMM.	18/09/2024	Adj Allbrook House	HW: carriageway defect	Internal		Committed	2375239

Effective: 27/05/2024 to 27/05/2025

Display Action Officer: No

Site: SHEERING LOWER ROAD (13801217)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	13801217_1000 - ZU10469	Feature Type:	Local Road	Area:	Sheering	
Batch:	7068914 - Inspection Batch	Route:	Area 17 Annual Aug Walked	Date:	19/09/2024			
3835232	RANSA 4 = 1 x 4, 50 % obscured. 40mph rd sign obscured by overhanging hedges., 0mm x 0mm	19/09/2024	LON: 0.1586967, LAT: 51.7932663; DETAILS: Adj jw Sheering Rd.	HW: roadsign obscured or dirty	Internal		Action Required	
3834796	RA 8 = 4 x 2, Multiple cw deep erosion at edge, approx average 1m x 0.5m x 120mm at deepest. NSMM.	18/09/2024	Half way btn Newhouse Farm and Allbrook House	HW: carriageway defect	Internal		Committed	2375238
3834664	RA 8 = 4 x 2, cw erosion near the edge, approx 1.2m x 0.7m x 120mm NSMM.	18/09/2024	Adj jw Hallingbury Rd	HW: carriageway defect	Internal		Committed	2375212
3834794	RA 8 = 4 x 2, 2 x cw deep erosion at edge, approx 0.9m x 0.6m x 100mm deep. NSMM.	18/09/2024	Approx 700km from Newhouse Farm	HW: carriageway defect	Internal		Committed	2375236
Batch:	7065689 - Inspection Batch	Route:	adhoc route	Date:	20/08/2024			
3825252	RANSA 16 = 4 x 4 A farm vehicle has churned up the asphalt along the road creating a dangerous situation. To be assessed/made safe. CMB 20.08.24 19:21	20/08/2024	About 40 yards from Rosina Court to Sawbridgeworth Road junction.	HW: carriageway defect	Internal		Committed	2373783

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1,000.00	Asset - Locn.:	13801217_1000 - ZU10469	Feature Type:	Local Road	Area:	Sheering
2329152	Carriageway repairs	Sheering lower road	HW: Street S3	job raised	25/03/2022		
2366157	c/way patching	Os 24 / 26	HW: S Follow up	works completed	16/04/2024	24/07/2024	Act. EH/1676984
2368128	Ra4 =1x4 4.0m x 0.6m x deepest point 50mm breaking up (HW: carriageway defect)	Junction of Sheering lower road	HW: Street S3	works completed	23/05/2024	27/11/2024	Act. EH/1676366
2371937	RA 8 = 4 x 2, CW erosion at the edge, approx 1.5m x 0.5m x 140mm deep (HW: carriageway defect)	Adj Allbrook House	HW: Street S2 Local	works completed	26/07/2024	02/08/2024	Act. EH/1678940
2371938	RA 8 = 4 x 2, CW erosion beside gulley cover approx 0.9m x 0.4m x 100mm deep NSMM (HW: carriageway defect)	Adj to Allbrook House	HW: Street S2 Local	works completed	26/07/2024	02/08/2024	Act. EH/1678941
2371939	RA 8 = 4 x 2, 2 x CW erosion at the edge adj to each other approx 1m x 0.5m x 140mm deep (HW: carriageway defect)	Approx 500 yards from Allbrook House	HW: Street S2 Local	works completed	26/07/2024	02/08/2024	Act. EH/1678942

Effective: 27/05/2024 to 27/05/2025

Display Action Officer: No

Site: SHEERING LOWER ROAD (13801217)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1,000.00	<b>Asset - Locn.:</b> 13801217_1000 - ZU10469		<b>Feature Type:</b> Local Road		<b>Area:</b> Sheering	
2373783	RANSA 16 = 4 x 4 A farm vehicle has churned up the asphalt along the road creating a dangerous situation. To be assessed/made safe. CMB 20.08.24 19:21 (HW: carriageway defect)	About 40 yards from Rosina Court to Sawbridgeworth Road junction.	HW: Street S1	works completed	20/08/2024	20/08/2024	Act. EH/1680385
2374262	RA9 = 3 x 3, 2 x FW erosion on kerbside, approx 1.1 x 0.6m x 70 mm at deepest. (HW: footway defect)	O/s 130 & 132	HW: Street S2 Local	works completed	30/08/2024	03/09/2024	Act. EH/1680751
2375212	RA 8 = 4 x 2, cw erosion near the edge, approx 1.2m x 0.7m x 120mm NSMM. (HW: carriageway defect)	Adj jw Hallingbury Rd	HW: Street S2 Local	works completed	18/09/2024	19/09/2024	Act. EH/1681593
2375235	RA 8 = 4 x 2, cw deep erosion at edge, approx 2m x 0.7m x 150mm deep. NSMM. (HW: carriageway defect)	Adj Newhouse Farm	HW: Street S2 Local	works completed	18/09/2024	19/09/2024	Act. EH/1681628
2375236	RA 8 = 4 x 2, 2 x cw deep erosion at edge, approx 0.9m x 0.6m x 100mm deep. NSMM. (HW: carriageway defect)	Approx 700km from Newhouse Farm	HW: Street S2 Local	works completed	18/09/2024	25/09/2024	Act. EH/1681632
2375237	RA 8 = 4 x 2, 2 x cw deep erosion at edge, approx 1m x 0.5m x 100mm deep. NSMM. (HW: carriageway defect)	Btn Newhouse Farm and Allbrook House	HW: Street S2 Local	works completed	18/09/2024	19/09/2024	Act. EH/1681634
2375238	RA 8 = 4 x 2, Multiple cw deep erosion at edge, approx average 1m x 0.5m x 120mm at deepest. NSMM. (HW: carriageway defect)	Half way btn Newhouse Farm and Allbrook House	HW: Street S2 Local	works completed	18/09/2024	19/09/2024	Act. EH/1681635
2375239	RA 8 = 4 x 2, Multiple cw deep erosion at edge, approx average 1m x 0.5m x 120mm at deepest. NSMM. (HW: carriageway defect)	Adj Allbrook House	HW: Street S2 Local	works completed	18/09/2024	19/09/2024	Act. EH/1681636
2379777	RA4 = 1 x 4 C/W P/H 1.4m x 0.6m x 60mm (HW: carriageway defect)	Outside no 11	HW: Street S3	job raised	27/11/2024		
2379778	Ra4 = 1x4 4.0m x 0.6m x deepest point 50mm breaking up (HW: carriageway defect)	Junction of Sheering lower road	HW: Street S3	job raised	27/11/2024		

Effective: 27/05/2024 to 27/05/2025

Display Action Officer: No

Site: SHEERING LOWER ROAD (13801217)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: 13801217_1000 - ZU10469		Feature Type: Local Road		Area: Sheering	
2386201	Installation of physical width restriction, traffic signs and road markings for experimental Traffic Regulation Order: 2.0m/6'-6" width restriction.	Sheering Lower Road, near junction with B183 Sheering Road.	HW: Capital Scheme	job raised	13/03/2025		
2388615	RA 8 = 2 x 4, cw eroded beside edgeline. Approx 0.9m x 0.5m x 80mm. Defect is filled with sewer water from a blocked manhole. Thames Water are attending site this Tuesday 29th to resolve ref - 01103721. (HW: carriageway defect)	Opp s/o 5	HW: Street S2 Local	works completed	29/04/2025	01/05/2025	Act. EH/1692762
2389336	RA 8 = 2 x 4, cw eroded beside edgeline. Approx 0.9m x 0.5m x 80mm. Defect is filled with sewer water from a blocked manhole. Thames Water are attending site this Tuesday 29th to resolve ref - 01103721. (HW: carriageway defect)	Opp s/o 5	HW: Street S2 Local	made safe	16/05/2025	19/05/2025	Act. EH/1693447