

Enquiry_Trace

Enquiry Number 2770719
Enquiry Classification Description fault reports
Enquiry Subject Name footway defects
Enquiry Subject Type Of Service Description Maintenance
Description Title=More than 2cm,resident fell on footpath
Address **MEMBER ENQUIRIES** between the BP garage and the bathstore
Central Site Address NETHER MAYNE
Central Site Notes
 SMO3 - Basildon // South Area // added as NSG update 7_7_2004; TRB // for further history see USRN 2002563, 2002063, 2000901
Central Site Area Description Basildon
Central Site Ward Name Basildon Westley Heights
Enquiry Customer Links

Customer Number 20553902
Enquiry Customer Enquiry Method Description website

Current Status Log

Defectdefect Number 3724126
Defectlogged Date 11 Jul 2023 11:45
Defect Defect Type Name HW: footway defect
Defect Description

Ra6=2x3 fw cracked, sunken, uneven and undulating 5.0mx6.0mx 150mm at its deepest point, upstand against ESW SV cover is 40mm

Defect Location Rear L/c 12, adj electric vehicle chargers in BP garage
Supersededdefect Number 3495730
Supersededlogged Date 17 Aug 2020 10:38
Superseded Defect Type Name HW: footway defect
Superseded Description RA 6 = 2 x 3 Depression in tarmac Footway Patch 5.0 x 2.5 x 150mm at its deepest point
Superseded Location Rear L/c 12
Superseded Supersedes Defect Number 3416275

Defect Photos

Uri



Document Date 10 Sep 2019 12:24

Url



Document Date

10 Sep 2019 12:24

Url



Document Date

17 Aug 2020 10:44

Uri



Document Date

17 Aug 2020 10:44

Uri



Document Date

11 Jul 2023 11:49

Url



Document Date

11 Jul 2023 11:49

Url



Document Date

11 Jul 2023 11:49

Url



Document Date

11 Jul 2023 11:49

Defect Priority Name
Enquiry Link Plot Number
Status Logs

HW: Street S3
1004

Log Number	Effective Date	Enquiry Status Code	Enquiry Status Name	Notes
1	28 Mar 2022 09:23	100	awaiting inspection	
4	05 Apr 2022 07:24	210	defect raised	A sunken footpath defect has already been raised
2	28 Mar 2022 09:24	100A	awaiting inspection (M)	
3	28 Mar 2022 14:44	100A	awaiting inspection (M)	

Attributes

Parameter Type Name

Feedback to Customer

Param String Value

A damaged and sunken path defect has already been raised at this location