

Effective: 20/03/2023 to 20/03/2025

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: footway defects (FWDF)

Site: MAIN ROAD (6601084)

Site: MAIN ROAD (6601084)

Locality: BROOMFIELD, CHELMSFORD, ESSEX

Area: Broomfield

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	6601084_1000 - B1008 //	Feature Type:	PR1 Road		Area:	Broomfield
Batch:	7116872 - Inspection Batch			Route:	Area 08 Monthly Driven		Date:	03/03/2025
3879830	RANSA 4 = 1 x 4, 300mm x 300mm x >50mm	03/03/2025	LON: 0.472759, LAT: 51.764563; DETAILS: os 243	HW: carriageway defect	Internal		No Action Required	
3879895	RANSA 4 = 1 x 4, cw eroded and gully sunk 450mm x 700mm x >50mm	03/03/2025	LON: 0.4734539, LAT: 51.7707863; DETAILS: at end of bus stop	HW: carriageway defect	Internal		No Action Required	
Batch:	7109689 - Inspection Batch			Route:	Area 08 Monthly Driven		Date:	03/02/2025
3872436	RANSA 2 = 1 x 2, cw cracked and eroded 3000mm x 200mm x >50mm	03/02/2025	LON: 0.4730807, LAT: 51.7630119; DETAILS: opp 178	HW: carriageway defect	Internal		Action Required	
3872475	RANSA 4 = 1 x 4, keep left bollard dirty > 50%	03/02/2025	LON: 0.4729026, LAT: 51.7690926; DETAILS: opp no347	HW: bollard damaged	Internal		Action Required	
3872497	RANSA 8 = 2 x 4 keep left bollard missing	03/02/2025	opp jw Roselawn Fields	HW: bollard missing	Internal		Committed	2383822
3872438	RANSA 4 = 1 x 4, cw eroded around cover 400mm x 450mm x >50mm	03/02/2025	LON: 0.4727247, LAT: 51.7645454; DETAILS: os no243	HW: carriageway defect	Internal		Action Required	
Batch:	7105215 - Inspection Batch			Route:	adhoc route		Date:	10/01/2025
3867513	RA3=1x3, vegetation encroaching fw 110.0m x up to 0.5m, remaining available fw 0.5m RESOLVED	10/01/2025	bet jubilee avenue & bus shelter	HW: overgrown vegetation (ext)	Internal		No Action Required	
Batch:	7105212 - Inspection Batch			Route:	adhoc route		Date:	10/01/2025
3867505	RA3=1x3, hedge overhanging fw 33.0m x 0.7m remaining available fw 0.7m	10/01/2025	OS bridgemash residential care home	HW: overgrown vegetation (ext)	Internal		Action Required	
Batch:	7105210 - Inspection Batch			Route:	adhoc route		Date:	10/01/2025
3867497	RA3 = 1 x 3, vegetation overhanging fw 55.0m x up to 1.1m remaining available fw 0.4m	10/01/2025	Opp tyres pro tyre shop	HW: overgrown vegetation (ext)	Internal		Action Required	
Batch:	7103504 - Inspection Batch			Route:	Area 08 Monthly Driven		Date:	03/01/2025
	No actionable defects found							
Batch:	7102280 - Inspection Batch			Route:	adhoc route		Date:	23/12/2024
3864826	RANSA 16 = 4 x 4 cw eroded 1.2m x 500mm x 150mm	23/12/2024	LON: 0.47349°, LAT: 51.75553° at jw gutters lane	HW: carriageway defect	Internal		Committed	2381613
Batch:	7096350 - Inspection Batch			Route:	Area 08 Monthly Driven		Date:	02/12/2024
	No actionable defects found							
Batch:	7093932 - Inspection Batch			Route:	adhoc route		Date:	22/11/2024
3856649	Ra 4 = 1 x 4 zebra crossing markings faded > 50%	22/11/2024	os no70	HW: worn or missing road mark	Internal		Action Required	
Batch:	7091951 - Inspection Batch			Route:	adhoc route		Date:	14/11/2024
3854326	Non investigatory defect, edge of footway broken up	14/11/2024	Entrance to village hall	HW: footway defect	Internal		Committed	2379105

Effective: 20/03/2023 to 20/03/2025

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: footway defects (FWDF)

Site: MAIN ROAD (6601084)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	6601084_1000 - B1008 //	Feature Type:	PR1 Road		Area:	Broomfield
Batch:	7088004 - Inspection Batch			Route:	Area 08 Monthly Driven		Date:	01/11/2024
3850482	RANSA 4 = 1 x 4, 70 % missing. hatchings markings faded	01/11/2024	LON: 0.4737036, LAT: 51.7571373; DETAILS: os petrol station	HW: worn or missing road mark	Internal		No Action Required	
3850484	RANSA 4 = 1 x 4, 70 % missing. hatchings markings faded	01/11/2024	LON: 0.4736687, LAT: 51.7596245; DETAILS: from Roselawn Field to the angel pub	HW: worn or missing road mark	Internal		Action Required	
3850487	RANSA 4 = 1 x 4, 50 % missing. bus stop markings faded	01/11/2024	LON: 0.4727813, LAT: 51.7644424; DETAILS: os new road	HW: worn or missing road mark	Internal		Action Required	
3850486	RANSA 4 = 1 x 4, 60 % missing. bus stop markings faded	01/11/2024	LON: 0.4735024, LAT: 51.7603531; DETAILS: os 151	HW: worn or missing road mark	Internal		Action Required	
3850478	RANSA 4 = 1 x 4, 70 % missing. hatchings markings faded	01/11/2024	LON: 0.4737036, LAT: 51.7571373; DETAILS: os petrol station	HW: worn or missing road mark	Internal		Action Required	
Batch:	7077568 - Inspection Batch			Route:	adhoc route		Date:	01/10/2024
3838679	RA3=1x3, vegetation encroaching fw 110.0m x up to 0.5m, remaining available fw 0.5m	01/10/2024	bet jubilee avenue & bus shelter	HW: overgrown vegetation (ext)	Internal		No Action Required	
Batch:	7077466 - Inspection Batch			Route:	Area 08 Monthly Driven		Date:	01/10/2024
3838579	RANSA 4 = 1 x 4, 50 % missing. bus stop markings faded	01/10/2024	LON: 0.473135, LAT: 51.7627411; DETAILS: opp 174	HW: worn or missing road mark	Internal		Action Required	
Batch:	7076790 - Inspection Batch			Route:	adhoc route		Date:	27/09/2024
3837774	non investigatory defect	27/09/2024		HW: carriageway defect	Internal		Committed	2365345
Batch:	7076789 - Inspection Batch			Route:	adhoc route		Date:	27/09/2024
3837773	non investigatory defect	27/09/2024		HW: carriageway defect	Internal		Committed	2365345
Batch:	7074440 - Inspection Batch			Route:	Area 08 Annual Sep Driven		Date:	18/09/2024
3834700	FW eroded by kerb RA2 = 2 X 1 700mm x 150mm x 40mm at deepest	18/09/2024	Os 136	HW: footway defect	Internal		Action Required	
3834715	Fw eroded ra3 = 1 x 3 600mm x 200mm x 20mm	18/09/2024	Os Hong kong express	HW: footway defect	Internal		Action Required	
3834713	Fw sunken around gully ra2 = 2 x 1	18/09/2024	Os335	HW: footway defect	Internal		Action Required	
3834696	Fw sunken Ra4 = 2 x 2 100mm x 500mm x 20mm	18/09/2024	Os 80	HW: footway defect	Internal		Action Required	
3834694	FW eroded by kerb RA2 = 2 X 1 500mm x 200mm x 20mm	18/09/2024	Os 28	HW: footway defect	Internal		Action Required	
3834702	RA4 = 2 X 2 1m x 700mm x 60mm at deepest	18/09/2024	Jc of Broomfield village hall	HW: footway defect	Internal		Committed	2379105
3834701	Fw sunken RA2 = 2 X 1 400mm x 300mm x 20mm	18/09/2024	Os 146	HW: footway defect	Internal		Action Required	

Effective: 20/03/2023 to 20/03/2025

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: footway defects (FWDF)

Site: MAIN ROAD (6601084)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	6601084_1000 - B1008 //	Feature Type:	PR1 Road		Area:	Broomfield
Batch:	7074440 - Inspection Batch			Route:	Area 08 Annual Sep Driven		Date:	18/09/2024
3834711	Fw eroded and sunken uneven RA4= 2 x 2 2m x 1.6m x 20mm at deepest	18/09/2024		HW: footway defect	Internal		Action Required	
3834695	FW eroded by kerb RA2 = 2 X 1 300mm x 100mm x 20mm	18/09/2024	Os 42	HW: footway defect	Internal		Action Required	
3834706	Fw eroded and sunken uneven RA6= 2 x 3 6.6m x 1.6m x 60mm at deepest	18/09/2024	Os 258	HW: footway defect	Internal		Action Required	
3834712	Fw sunken ra3 = 1 x 3	18/09/2024	Os 286	HW: footway defect	Internal		Action Required	
3834708	Fw eroded and sunken uneven RA4= 2 x 2 5m x 1.6m x 30mm at deepest	18/09/2024	Os 280	HW: footway defect	Internal		Action Required	
3834704	Fw edge eroded by kerb Ra2 = 2 x 1 2m x 400mm x 20mm	18/09/2024	Os 216	HW: footway defect	Internal		Action Required	
3834705	Surface cover sunken RA2 = 1 X 2	18/09/2024	Opp 281	HW: footway defect	Internal		Action Required	
3834697	Fw sunken Ra4 = 2 x 2 100mm x 500mm x 20mm	18/09/2024	Os 84	HW: footway defect	Internal		Action Required	
3834714	Fw sunken and eroded RA2 = 1 x 2 500mm x 300mm x 20mm	18/09/2024	Os premier shop	HW: footway defect	Internal		Action Required	
3834709	Fw cracked and risen Ra2 = 2 x 1	18/09/2024	Os 280	HW: footway defect	Internal		Action Required	
3834710	Fw sunken around surface covers Ra4 = 2 x 2	18/09/2024	By 40mph sign by 280	HW: footway defect	Internal		Action Required	
3834698	FW eroded by kerb RA4= 2 X 2 4m x 200mm x 30mm at deepest point	18/09/2024	Os tyre pros	HW: footway defect	Internal		Action Required	
3834707	Fw sunken around surface covers Ra4 = 2 x 2	18/09/2024	Os 270	HW: footway defect	Internal		Action Required	
3834699	FW eroded by kerb RA4= 2 X 2 4m x 300mm x 40mm at deepest point	18/09/2024	On jc of post office rd	HW: footway defect	Internal		Committed	2401727
3834703	Fw eroded and uneven Ra2 = 1 x 2 7m x 1.1m x 20mm	18/09/2024	Os 212	HW: footway defect	Internal		Action Required	
3834716	Fw eroded by kerb RA2 = 2 X 1 1.8m x 200mm x 20mm	18/09/2024	Os 22	HW: footway defect	Internal		Action Required	

Effective: 20/03/2023 to 20/03/2025

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: footway defects (FWDF)

Site: MAIN ROAD (6601084)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	6601084_1000 - B1008 //	Feature Type:	PR1 Road		Area:	Broomfield
Batch:	7069828 - Inspection Batch			Route:	adhoc route			Date: 03/09/2024
3829296	Non Investigatory Defect	03/09/2024		HW: carriageway defect	Internal		Committed	2319507
Batch:	7069757 - Inspection Batch			Route:	Area 08 Monthly Driven			Date: 03/09/2024
	No actionable defects found							
Batch:	7058469 - Inspection Batch			Route:	Area 08 Monthly Driven			Date: 01/08/2024
	No actionable defects found							
Batch:	7049251 - Inspection Batch			Route:	Area 08 Monthly Driven			Date: 01/07/2024
3807191	RANSA 4 = 1 x 4 speed camera warning sign faded >50%	01/07/2024	LON: 0.47265°, LAT: 51.76471° opposite mill lane	HW: roadsign damaged	Internal		Action Required	
3807189	RANSA 4 = 1 x 4 no lorries sign faded >80%	01/07/2024	LON: 0.47350°, LAT: 51.77365° by roundabout	HW: roadsign damaged	Internal		Action Required	
3807188	RANSA 4 = 1 x 4 keep left road sign bent and twisted wrong way	01/07/2024	LON: 0.47331°, LAT: 51.77285° on island between court road and hospital approach	HW: roadsign damaged	Internal		Action Required	
3807187	RANSA 4 = 1 x 4 sharp right warning sign faded >50%	01/07/2024	LON: 0.47229°, LAT: 51.76537° at junction with williams road	HW: roadsign damaged	Internal		Action Required	
3807190	RANSA 4 = 1 x 4 30mph sign dirty > 50%	01/07/2024	LON: 0.47229°, LAT: 51.76799° outside 286	HW: roadsign obscured or dirty	Internal		Action Required	
Batch:	7041147 - Inspection Batch			Route:	Area 08 Monthly Driven			Date: 03/06/2024
3797778	RANSA 4 = 1 x 4 bus stop post struck and leaning	03/06/2024	LON: 0.47348°, LAT: 51.76039° by bus stop	HW: roadsign damaged	Internal		Action Required	
Batch:	7036795 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793472	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036793 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793470	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036792 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793469	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036789 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793465	Map16 asset risk level: Very Low	13/05/2024		HW: gully cover stuck	Internal		Action Required	
Batch:	7036788 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793464	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036787 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793463	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036786 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793462	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036785 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793461	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	

Effective: 20/03/2023 to 20/03/2025

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: footway defects (FWDF)

Site: MAIN ROAD (6601084)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	6601084_1000 - B1008 //	Feature Type:	PR1 Road		Area:	Broomfield
Batch:	7036784 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793460	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036782 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793454	Map16 asset risk level:	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036768 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793352	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036767 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793351	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036766 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793350	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036765 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793349	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036743 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793333	Map16 asset risk level: Low	13/05/2024		HW: gully cover stuck	Internal		Action Required	
Batch:	7036742 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793332	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036741 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793331	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036739 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793329	Map16 asset risk level: Low	13/05/2024		HW: surface cover damaged	Internal		Action Required	
Batch:	7036738 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793328	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036737 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793327	Map16 asset risk level: Low	13/05/2024		HW: blocked gully connection	Internal		Committed	2365345
Batch:	7036735 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793322	Map16 asset risk level: Low	13/05/2024		HW: surface cover damaged	Internal		Action Required	
Batch:	7036733 - Inspection Batch			Route:	adhoc route			Date: 13/05/2024
3793320	Map16 asset risk level:	13/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036477 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793094	Map16 asset risk level: Low	10/05/2024		HW: gully cover stuck	Internal		Action Required	
Batch:	7036476 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793093	Map16 asset risk level: Low	10/05/2024		HW: gully cover stuck	Internal		Action Required	
Batch:	7036475 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793092	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	

Effective: 20/03/2023 to 20/03/2025

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: footway defects (FWDF)

Site: MAIN ROAD (6601084)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	6601084_1000 - B1008 //	Feature Type:	PR1 Road		Area:	Broomfield
Batch:	7036474 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793091	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036473 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793090	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036471 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793082	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036470 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793081	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036468 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793080	Map16 asset risk level: Very Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036467 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793079	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036466 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793078	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036440 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793040	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036436 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793035	Map16 asset risk level: Low	10/05/2024		HW: gully cover stuck	Internal		Action Required	
Batch:	7036435 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793033	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036433 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3793031	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036418 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3792987	Map16 asset risk level: Low	10/05/2024		HW: gully cover stuck	Internal		Action Required	
Batch:	7036417 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3792986	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036411 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3792977	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7036410 - Inspection Batch			Route:	adhoc route			Date: 10/05/2024
3792976	Map16 asset risk level: Low	10/05/2024		HW: blocked gully connection	Internal		Action Required	
Batch:	7034933 - Inspection Batch			Route:	Area 08 Monthly Driven			Date: 02/05/2024
3791631	Ra 4 = 1 x 4 bollard struck and leaning	02/05/2024	LON: 0.47338°, LAT: 51.76108° by ridley rd	HW: bollard damaged	Internal		Action Required	
Batch:	7029323 - Inspection Batch			Route:	adhoc route			Date: 08/04/2024
3785894	Ransa16=4x4 temp sign blown over on traffic island no lights on (esp08040102)	08/04/2024	Main road on junction with Roselawn Fields	HW: debris/deposit on highway	Internal		Committed	2365582

Effective: 20/03/2023 to 20/03/2025

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: footway defects (FWDF)

Site: MAIN ROAD (6601084)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: 6601084_1000 - B1008 //		Feature Type: PR1 Road			Area: Broomfield	
Batch: 7028491 - Inspection Batch		Route: Area 08 Monthly Driven				Date: 02/04/2024		
3785203	RANSA 8 = 2 x 4 cw eroded or sunk around gully 700mm x 400mm x 70mm	02/04/2024	Opposite J/W Roselawn Fields around a gully	HW: carriageway defect	Internal		Committed	2365331
Batch: 7027570 - Inspection Batch		Route: adhoc route				Date: 25/03/2024		
3784369	RANSA 150 RA8=4x2 2No damaged bollards on pedestrian refuge. Previous make safe TM missing	25/03/2024	Near jw Roselawn Fields	HW: bollard damaged	Internal		Committed	2365058
Batch: 7024024 - Inspection Batch		Route: Area 08 Monthly Driven				Date: 06/03/2024		
3780770	RANSA 4 = 1 x 4 cw eroded around surface cover 500mm x 300mm x 50mm	06/03/2024	LON: 0.47343°, LAT: 51.75536° at jw Gutters Lane	HW: carriageway defect	Internal		Action Required	
3780769	RANSA 4 = 1 x 4 cw eroded 1.5m x 300mm x 50mm	06/03/2024	LON: 0.47349°, LAT: 51.75553° at jw gutters lane	HW: carriageway defect	Internal		No Action Required	
3780768	RANSA 4 = 1 x 4 cw eroded 200mm x 200mm x 50mm	06/03/2024	LON: 0.47327°, LAT: 51.76246° outside the angel pub	HW: carriageway defect	Internal		Committed	2381916
3780767	RANSA 4 = 1 x 4 cw eroded 1m x 300mm x 50mm	06/03/2024	LON: 0.47324°, LAT: 51.76263° outside the angel pub	HW: carriageway defect	Internal		Committed	2381916
3780766	RANSA 4 = 1 x 4 cw eroded 1.5m x 400mm x 50mm	06/03/2024	LON: 0.47323°, LAT: 51.76274° outside the angel pub	HW: carriageway defect	Internal		Committed	2381916
3780765	RANSA 3 = 1 x 3 cw eroded around surface cover 600mm x 300mm x 50mm	06/03/2024	LON: 0.47338°, LAT: 51.77198° at jw court rd	HW: carriageway defect	Internal		Action Required	
3780764	RANSA 4 = 1 x 4 cw eroded or sunk around gully 700mm x 400mm x 50mm	06/03/2024	Opposite J/W Roselawn Fields around a gully	HW: carriageway defect	Internal		No Action Required	
Batch: 7020329 - Inspection Batch No actionable defects found		Route: Area 08 Monthly Driven				Date: 16/02/2024		
Batch: 7014178 - Inspection Batch No actionable defects found		Route: Area 08 Monthly Driven				Date: 19/01/2024		
Batch: 7012763 - Inspection Batch No actionable defects found		Route: Area 08 Annual Jan Walked				Date: 12/01/2024		
Batch: 7010127 - Inspection Batch No actionable defects found		Route: Area 08 Monthly Driven				Date: 28/12/2023		
Batch: 7001729 - Inspection Batch No actionable defects found		Route: Area 08 Monthly Driven				Date: 14/11/2023		
Batch: 6997421 - Inspection Batch No actionable defects found		Route: Area 08 Monthly Driven				Date: 25/10/2023		
Batch: 6991449 - Inspection Batch		Route: adhoc route				Date: 29/09/2023		
3744997	RA16 = 4 X 4 Damaged bollardS on centre traffic island	29/09/2023	Near the J/W RoseLawn Field	HW: bollard damaged	Internal		Committed	2355670

Effective: 20/03/2023 to 20/03/2025

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: footway defects (FWDF)

Site: MAIN ROAD (6601084)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: 6601084_1000 - B1008 //		Feature Type: PR1 Road			Area: Broomfield	
Batch: 6988693 - Inspection Batch No actionable defects found				Route: Area 08 Annual Sep Driven				Date: 14/09/2023
Batch: 6988363 - Inspection Batch				Route: Area 08 Monthly Driven				Date: 14/09/2023
3740664	RANSA 4 = 2 x 2, fw eroded, > 1.5m x 0.5m > 20mm	14/09/2023	opp ridley road	HW: footway defect	Internal		Action Required	
3740665	RANSA 4 = 2 x 2, fw eroded, > 3m x 0.3m > 20mm	14/09/2023	o/s broomfield village hall	HW: footway defect	Internal		Action Required	
Batch: 6978679 - Inspection Batch No actionable defects found				Route: Area 08 Monthly Driven				Date: 08/08/2023
Batch: 6976980 - Inspection Batch				Route: adhoc route				Date: 01/08/2023
3730214	RA16 = 4 x 4 C/W P/H 0.8m 0.3m x 160mm	01/08/2023	Between Butlers Farm bus layby and the centre island refuge opposite 385 around a gully	HW: carriageway defect	Internal		Committed	2352914
Batch: 6975493 - Inspection Batch No actionable defects found				Route: Area 08 Monthly Driven				Date: 25/07/2023
Batch: 6960706 - Inspection Batch				Route: Area 08 Monthly Driven				Date: 19/05/2023
3713146	RANSA6 = 3 x 2 C/W P/H 0.6m x 0.4m x >70mm around a gully	19/05/2023	Opposite J/W Roselawn Fields around a gully	HW: carriageway defect	Internal		No Action Required	
3713145	RA4 = 1 x 4 A triangle Traffic light Sign has faded	19/05/2023	LAMP COLUMN 28	HW: roadsign obscured or dirty	Internal		Action Required	
3713144	RA4 = 4 x 1 Damaged bollard on centre traffic island	19/05/2023	Near the J/W RoseLawn Field	HW: bollard damaged	Internal		No Action Required	
Batch: 6958561 - Inspection Batch				Route: adhoc route				Date: 13/05/2023
3711092	RANSA DLC13050215 clear oil and debris from carriageway following RTC	13/05/2023	Junc. w/ School Lane, o/s the library	HW: debris/deposit on highway	Internal		Committed	2347590
Batch: 6953763 - Inspection Batch				Route: Area 08 Monthly Driven				Date: 27/04/2023
3706435	RANSA4 = 1 x 4 C/W P/H 0.3m x 0.2m x >50mm	27/04/2023	Opposite Marsh Cottage	HW: carriageway defect	Internal		Action Required	
3706436	RANSA4 = 4 x 1 F/W Deterioration 1.6m x 1m >20mm	27/04/2023	Outside no 171	HW: footway defect	Internal		Action Required	
3706434	RA2 = 2 x 1 Bollard damaged	27/04/2023	Opposite no 174	HW: bollard damaged	Internal		Committed	2393914
Batch: 6952830 - Inspection Batch				Route: adhoc route				Date: 25/04/2023
3705376	Ransa dc25042130 clear up following rtc	25/04/2023	Near 90	HW: debris/deposit on highway	Internal		Committed	2346779

Effective: 20/03/2023 to 20/03/2025

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: footway defects (FWDF)

Site: MAIN ROAD (6601084)

Customer Services

Enquiry No.: 2924819	Logged by: CRM Connector	on: 11/06/2024 15:14
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Customer Selection=More than 2cm,I reported the state of this pavement on 25th February 2021. Ref 2699869. Since then the state of the pavement has deteriorated and there are anumber of serious trip hazards and areas where the surface has disappeared. I understand that it has been inspected regularly . I would be most interested to see those reports. Last week Virgin Media (Kelly Group) came and dug up a large percentage of this stretch of pavement . It has ben left in an absolutely discusting state. I would request that these issues are addressed as a matter of some urgency .		
Location: Pavement between Deverill Close and 236 Main Road		Contact:
Plot Number: 1,000.00	Feature Id - Location: 6601084_1000 - B1008 //	Feature Type: PR1 Road
Defect Number: 3834705		
Enquiry No.: 2921751	Logged by: CRM Connector	on: 28/05/2024 17:05
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Customer Selection=More than 2cm,2 holes - one on public pavement, the other just inside the entrance		
Location: Broomfield w3w lodge.couch.gallons Pavement entrance to Village Hall		Contact:
Plot Number: 1,000.00	Feature Id - Location: 6601084_1000 - B1008 //	Feature Type: PR1 Road
Job Number: 2379105 Defect Number: 3834702		
Enquiry No.: 2859642	Logged by: CRM Connector	on: 26/07/2023 15:48
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Customer Selection=More than 2cm,JLR caller states - surface broken and disrupted - uneven - holes approx 1m long 7.5-10 cms deep. 22/01/25 (GS): Customer called to say the pavement defect has got worse and needs inspecting again to assess.		
Location: Outside 258		Contact:
Plot Number: 1,000.00	Feature Id - Location: 6601084_1000 - B1008 //	Feature Type: PR1 Road
Defect Number: 3834706		
Enquiry No.: 2845951	Logged by: CRM Connector	on: 17/05/2023 16:22
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Customer Selection=More than 2cm,Caller States: The pavement along the road is uneven and sloppy . When pushing the wheelchair it makes it difficult and risky for the wheelchair users as they can easily trip and fall which will cause an injury. SJ		
Location: **150**Outside Bridgemarksh . SJ		Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: 6601084_1000 - B1008 //	Feature Type: PR1 Road		Area: Broomfield		
2319507	replace 2 TMP bollards on traffic island	Near junction of Roselawn Fields	HW: Street S3	works completed	03/08/2021	22/04/2024	Act. EH/1668300
2343767	Replace damaged TMP keep left bollard on centre island	Outside no 241	HW: Street S3	works completed	01/03/2023	08/06/2023	Act. EH/1657658
2345685	Reset gully & patch 1.6m surround	Opposite no 385 Main Road. At the end of the bus layby and before the Traffic island	HW: Street S3	works completed	04/04/2023	09/12/2025	Act. EH/1658830
2346779	Ransa dc25042130 clear up following rtc (HW: debris/deposit on highway)	Near 90	HW: Street S1	works completed	25/04/2023	25/04/2023	Act. EH/1658464
2347224	Footway patch across petrol station vehicle access	Outside Chelmsford Low Cost Service Station entrance	HW: Street S3	works completed	05/05/2023	09/10/2023	Act. EH/1665028

Effective: 20/03/2023 to 20/03/2025

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: footway defects (FWDF)

Site: MAIN ROAD (6601084)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: 6601084_1000 - B1008 //		Feature Type: PR1 Road		Area: Broomfield	
2347590	RANSA DLC13050215 clear oil and debris from carriageway following RTC (HW: debris/deposit on highway)	Junc. w/ School Lane, o/s the library	HW: Street S1	works completed	13/05/2023	13/05/2023	Act. EH/1659281
2352330	PH23 pothole defect patching	Various - see schedule	HW: Street S3	works completed	21/07/2023	12/10/2023	Act. EH/1664847
2352914	RA16 = 4 x 4 C/W P/H 0.8m 0.3m x 160mm (HW: carriageway defect)	Between Butlers Farm bus layby and the centre island refuge opposite 385 around a gully	HW: Street S1	works completed	01/08/2023	01/08/2023	Act. EH/1662592
2355670	RA16 = 4 X 4 Damaged bollardS on centre traffic island (HW: bollard damaged)	Near the J/W RoseLawn Field	HW: Street S1	works completed	29/09/2023	29/09/2023	Act. EH/1664785
2358452	Map16 asset risk level: Low (HW: blocked gully connection)		HW: Street S4	job raised	28/11/2023		
2365058	RANSA 150 RA8=4x2 2No damaged bollards on pedestrian refuge. Previous make safe TM missing (HW: bollard damaged)	Near jw Roselawn Fields	HW: Street S2 PR1/2	works completed	25/03/2024	26/03/2024	Act. EH/1673107
2365331	RANSA 8 = 2 x 4 cw eroded or sunk around gully 700mm x 400mm x 70mm (HW: carriageway defect)	Opposite J/W Roselawn Fields around a gully	HW: Street S2 PR1/2	works completed	02/04/2024	03/04/2024	Act. EH/1673368
2365345	MEML 24-25 - CW PATCHING AND GULLY RENEW	Opposite J/W Roselawn Fields around a gully	HW: S Follow up	works completed	03/04/2024	22/04/2024	Act. EH/1673566
2365582	Ransa16=4x4 temp sign blown over on traffic island no lights on (esp08040102) (HW: debris/deposit on highway)	Main road on junction with Roselawn Fields	HW: Street S1	works completed	08/04/2024	08/04/2024	Act. EH/1673625
2379105	MEML 24-25 1 no FW patch	Jc of Broomfield village hall	HW: Capital Scheme	works completed	15/11/2024	06/08/2025	Act. EH/1687573
2381613	RANSA 16 = 4 x 4 cw eroded 1.2m x 500mm x 150mm (HW: carriageway defect)	LON: 0.47349°, LAT: 51.75553° at jw gutters lane	HW: Street S1	works completed	23/12/2024	23/12/2024	Act. EH/1686687
2381916	MEML 24-25 Winter damage T07 work 3no total 3m2	LON: 0.47327°, LAT: 51.76246° outside the angel pub	HW: Capital Scheme	works completed	06/01/2025	17/01/2025	Act. EH/1687372
2383822	RANSA 8 = 2 x 4 keep left bollard missing (HW: bollard missing)	opp jw Roselawn Fields	HW: Street S2 PR1/2	works completed	03/02/2025	05/02/2025	Act. EH/1688523
2385533	Replace 2 TMP bollards	On traffic island opp jw Roselawn Fields	HW: S Follow up	works completed	04/03/2025	27/05/2025	Act. EH/1693683