

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Site: STRAIGHT ROAD (8901800)

Locality: COLCHESTER, ESSEX

Area: Colchester

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: 8901800_1000	- ZC79 // For further history see USRN 8901799			Feature Type: PR2 Road	Area: Colchester	
Batch:	7220756 - Inspection Batch			Route: Area 03 Mar/Jun/Sep/Dec Driven			Date: 03/06/2026	
4006167	RANSA 4 = 1 x 4, CW surface erosion 2500mm x 1000mm x >30mm	03/06/2026	LON: 0.8525193333625793, LAT: 51.88953399658203	HW: carriageway defect	Internal		Action Required	
Batch:	7205316 - Inspection Batch			Route: Area 03 Annual Mar Walked			Date: 27/03/2026	
3986123	RA12=3x4, cwph around sunken water fire hydrant cover, 0.9m x 0.8m x 80mm NSMM	27/03/2026	Outside 331	HW: carriageway defect	Internal		Committed	2406353
3986125	RA3=1x3, cwph, 4m x 0.8m x 50mm NSMM	27/03/2026	Outside 136	HW: carriageway defect	Internal		Action Required	
3986117	RA3=1x3, cw surface cracking, 6m x 0.9m x 10mm	27/03/2026	Outside 351, junction with Baden Powell drive	HW: carriageway defect	Internal		Action Required	
3986124	RA4=2x2, fw surface erosion, 3m x 2m x 30mm	27/03/2026	Outside 324	HW: footway defect	Internal		Action Required	
3986128	RA8=2x4, cwph, 1.8m x 0.8m x 70mm nsmm	27/03/2026	Outside 81	HW: carriageway defect	Internal		Committed	2406356
3986129	RA8=2x4, cwph, 3m x 1m x 70mm nsmm	27/03/2026	Outside 54	HW: carriageway defect	Internal		Committed	2406357
3986130	RA2=2x1, fwph, 1.5m 0.3m x 30mm	27/03/2026	Outside 46	HW: footway defect	Internal		Action Required	
3986120	RA4=1x4, cwph, 0.7m x 0.6m x 50mm NSMM	27/03/2026	Outside 371	HW: carriageway defect	Internal		Action Required	
3986132	RA4=1x4, cluster of potholes, 10m x 6m x 50mm at deepest nsmm	27/03/2026	Junction with London road	HW: carriageway defect	Internal		Committed	2402446
3986126	RA8=2x4, cwph, 1m x 0.7m x 70mm nsmm	27/03/2026	Outside 134	HW: carriageway defect	Internal		Committed	2406354
3986127	RA8=2x4, cwph, 1m x 0.7m x 70mm nsmm	27/03/2026	Outside 134	HW: carriageway defect	Internal		Committed	2406355
3986133	RA 4 = 1 x 4, CW surface erosion 25m x 2m x 20mm	27/03/2026	Outside 8, at bus stop bay LON: 0.8525956869125366, LAT: 51.8892936706543	HW: carriageway defect	Internal		Action Required	
3986121	RA3=1x3, fw surface sunk, 2m x 0.7m x 20mm	27/03/2026	Outside 362	HW: footway defect	Internal		Action Required	
3986119	RA4=1x4, cwph, 0.6m x 0.5m x 50mm NSMM	27/03/2026	Outside 354	HW: carriageway defect	Internal		Action Required	
3986122	RA6=2x3, fw surface cracked and raised through tree roots, 4m x 1m x 50mm	27/03/2026	Outside 342	HW: footway defect	Internal		Action Required	
3986131	RA6=3x2, fwph with surround surface erosion, 1m x 1m x 50mm at deepest	27/03/2026	Outside 42	HW: footway defect	Internal		Action Required	
3986118	RA4=1x4, cwph, 0.5m x 0.4m x 50mm NSMM	27/03/2026	Outside 354	HW: carriageway defect	Internal		Action Required	
3986134	RA6=2x3, cw sunk around water surface cover, 0.9m x 0.8m x 70mm NSMM	27/03/2026	Outside 344, junction with Baden Powell drive	HW: carriageway defect	Internal		Action Required	

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: 8901800_1000 - ZC79 // For further history see USRN 8901799			Feature Type: PR2 Road		Area: Colchester	
Batch: 7203268 - Inspection Batch			Route: adhoc route				Date: 18/03/2026	
3982618	RA6=3×2, roundabout and pedestrian crossing signs damaged and lying on footway	18/03/2026	Outside 133 on lamp column 27 - S9	HW: roadsign damaged	Internal		Action Required	
Batch: 7203224 - Inspection Batch			Route: adhoc route				Date: 18/03/2026	
3982498	RA4=1×4, cwph, 1m x 1m x 50mm	18/03/2026	Outside 8 Kingsmead Hall Woodland Drive, Lexden, CO3 9FE, England, United Kingdom	HW: carriageway defect	Internal		No Action Required	
Batch: 7203199 - Inspection Batch			Route: Area 03 Mar/Jun/Sep/Dec Driven				Date: 18/03/2026	
3982496	RANSA 4 = 1 x 4, CW surface erosion 800mm x 600mm x >30mm	18/03/2026	LON: 0.8543828725814819, LAT: 51.882938385009766	HW: carriageway defect	Internal		Committed	2407295
3982610	RANSA 4 = 1 x 4, CW surface erosion with cracking 900mm x 1700mm x >50mm	18/03/2026	LON: 0.8571053743362427, LAT: 51.87540817260742	HW: carriageway defect	Internal		Action Required	
3982477	RANSA 4 = 1 x 4, CW surface erosion 600mm x 400mm x >20mm	18/03/2026	LON: 0.8525956869125366, LAT: 51.8892936706543	HW: carriageway defect	Internal		No Action Required	
3982538	RANSA 4 = 1 x 4, CWPH 800mm x 450mm x >50mm	18/03/2026	LON: 0.8551054000854492, LAT: 51.880374908447266	HW: carriageway defect	Internal		Action Required	
3982472	RANSA 4 = 1 x 4, CWPH around water surface cover 800mm x 600mm x >50mm	18/03/2026	LON: 0.8537722826004028, LAT: 51.8851203918457	HW: carriageway defect	Internal		Action Required	
3982452	RANSA 4 = 1 x 4, CWPH around water surface cover 900mm x 800mm x >50mm	18/03/2026	LON: 0.8561286926269531, LAT: 51.876747131347656	HW: carriageway defect	Internal		Committed	2407295
3982506	RANSA 4 = 1 x 4, CWPH 800mm x 600mm x >50mm	18/03/2026	LON: 0.8530229330062866, LAT: 51.88779830932617	HW: carriageway defect	Internal		Action Required	
3982493	RANSA 4 = 1 x 4, CWPH 600mm x 400mm x >50mm	18/03/2026	LON: 0.8541843891143799, LAT: 51.8836555480957; DETAILS: On mini roundabout	HW: carriageway defect	Internal		Action Required	
Batch: 7199084 - Inspection Batch			Route: adhoc route				Date: 02/03/2026	
3976868	RA16=4×4, cwph, 0.9m x 0.7m x 100mm NSMM	02/03/2026	Junction with Hunters corner	HW: carriageway defect	Internal		Committed	2404414
Batch: 7198867 - Inspection Batch			Route: adhoc route				Date: 27/02/2026	
3976554	RA16=4×4, cwph, 0.6m x 0.5m x 100mm NSMM	27/02/2026	Outside 117	HW: carriageway defect	Internal		Committed	2404342
Batch: 7197420 - Inspection Batch			Route: adhoc route				Date: 24/02/2026	
3974528	RESOLVED RANSA 4 = 1 x 4, vegetation obscuring warning sign, >5.0m x >1.0m	24/02/2026	LON: 0.8550341129302979, LAT: 51.8806266784668; DETAILS: os 128	HW: overgrown vegetation (ext)	Internal		No Action Required	
Batch: 7197178 - Inspection Batch			Route: adhoc route				Date: 23/02/2026	
3974252	RANSA 150 RA12=3x4 cwdf at gully >1.2mx>0.9mx>80mm	23/02/2026	os 185. Op 142.	HW: carriageway defect	Internal		Committed	2403847

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: 8901800_1000 - ZC79 // For further history see USRN 8901799			Feature Type: PR2 Road		Area: Colchester	
Batch: 7196305 - Inspection Batch		Route: adhoc route			Date: 19/02/2026			
3973029	Ra8 = 2 x 4 CWPH 0.3m x 0.5m x 90mm nnms	19/02/2026	O/s 136	HW: carriageway defect	Internal		Committed	2403584
3973028	Ra8 = 2 x 4 CWPH 0.3m x 0.5m x 90mm nnms	19/02/2026	O/s 119	HW: carriageway defect	Internal		Committed	2403586
3973027	Ra8 = 2 x 4 CWPH by gully 0.4m x 0.4m x 90mm nnms	19/02/2026	O/s 142	HW: carriageway defect	Internal		Committed	2403585
Batch: 7195437 - Inspection Batch		Route: adhoc route			Date: 17/02/2026			
3971974	RANSA 4 = 1 x 4, CWPH 400mm x 300mm x >50mm	17/02/2026	LON: 0.8561109304428101, LAT: 51.87679672241211; DETAILS: O/s 291	HW: carriageway defect	Internal		Committed	2402446
Batch: 7195193 - Inspection Batch		Route: adhoc route			Date: 16/02/2026			
3971772	RANSA 4 = 1 x 4, CWPH 500mm x 800mm x >50mm	16/02/2026	LON: 0.8532645106315613, LAT: 51.88692092895508; DETAILS: O/S 76	HW: carriageway defect	Internal		Committed	2402446
Batch: 7195178 - Inspection Batch		Route: adhoc route			Date: 16/02/2026			
3971756	RANSA 4 = 1 x 4, CWPH 900mm x 800mm x >20mm	16/02/2026	LON: 0.8530305027961731, LAT: 51.88777160644531; DETAILS: O/S 50	HW: carriageway defect	Internal		Committed	2402446
Batch: 7194083 - Inspection Batch		Route: adhoc route			Date: 11/02/2026			
3970577	RANSA 4 = 1 x 4, cwph 950mm x 500mm x >50mm	11/02/2026	LON: 0.8551449179649353, LAT: 51.88023376464844	HW: carriageway defect	Internal		Committed	2402446
Batch: 7194081 - Inspection Batch		Route: adhoc route			Date: 11/02/2026			
3970575	RANSA 4 = 1 x 4, cwph 750mm x 450mm x >50mm	11/02/2026	LON: 0.8561186194419861, LAT: 51.876773834228516	HW: carriageway defect	Internal		Committed	2402446
Batch: 7194079 - Inspection Batch		Route: adhoc route			Date: 11/02/2026			
3970573	RANSA 2 = 1 x 2, footway erosion at kerb side 1050mm x 300mm x >20mm	11/02/2026	LON: 0.8582330942153931, LAT: 51.87462615966797	HW: carriageway defect	Internal		Committed	2402446
Batch: 7194078 - Inspection Batch		Route: adhoc route			Date: 11/02/2026			
3970572	RANSA4=1x4, cwph around sunken water cover, 0.6m x 0.6m x >50mm	11/02/2026	Outside 331	HW: carriageway defect	Internal		No Action Required	
Batch: 7185479 - Inspection Batch		Route: adhoc route			Date: 05/01/2026			
3959582	Ra8 = 2 x 4, breaking up around covers, 0.9m x 0.8m x 70mm	05/01/2026	LON: 0.8588452935218811, LAT: 51.87419891357422, os 332a	HW: carriageway defect	Internal		Committed	2400035
Batch: 7182720 - Inspection Batch		Route: adhoc route			Date: 13/12/2025			
3956121	RANSA dl13121230 make safe missing GY cover	13/12/2025	Nr sign for The Poplars. Opp. Heath Road	HW: surface cover missing	Internal		Committed	2399197
Batch: 7181404 - Inspection Batch		Route: Area 03 Mar/Jun/Sep/Dec Driven			Date: 09/12/2025			
3954689	RANSA 4 = 1 x 4, vegetation obscuring warning sign, >5.0m x >1.0m	09/12/2025	LON: 0.8550341129302979, LAT: 51.8806266784668; DETAILS: os 128	HW: overgrown vegetation (ext)	Internal		No Action Required	
3954705	RANSA 4 = 1 x 4, breaking up around covers 200mm x 100mm x >50mm	09/12/2025	LON: 0.8588452935218811, LAT: 51.87419891357422	HW: carriageway defect	Internal		No Action Required	

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: 8901800_1000 - ZC79 // For further history see USRN 8901799			Feature Type: PR2 Road		Area: Colchester	
Batch: 7169607 - Inspection Batch			Route: adhoc route				Date: 15/10/2025	
3939558	RA6=2×3, standing water collecting on Carriageway at zebra crossing by 30m x 6m x 50mm	15/10/2025	O/s 156	HW: Standing Water	Internal		Action Required	
Batch: 7162978 - Inspection Batch			Route: adhoc route				Date: 16/09/2025	
3931683	RA2=1×2, small amount of remains of red Cross painted on roundabout. 5% coverage remaining. RESOLVED. Updated by Louise Parker.	16/09/2025	At junction with James Carter road	HW: worn or missing road mark	Internal		No Action Required	
Batch: 7160379 - Inspection Batch			Route: Area 03 Mar/Jun/Sep/Dec Driven				Date: 03/09/2025	
3929491	RANSA 4 = 1 x 4, CWPH 900mm x 600mm x >30mm	03/09/2025	LON: 0.8569, LAT: 51.875525; DETAILS: Junction with James Carter road	HW: carriageway defect	Internal		Committed	2402446
3929483	RANSA 4 = 1 x 4, 50 % missing. Red crosses painted overcrossing zebra	03/09/2025	LON: 0.8541793823242188, LAT: 51.88357925415039	HW: worn or missing road mark	Internal		Action Required	
3929486	RANSA 4 = 1 x 4, 1050mm x 400mm x >20mm	03/09/2025	LON: 0.85353, LAT: 51.885977	HW: carriageway defect	Internal		Committed	2402446
3929484	RANSA 4 = 1 x 4, 50 % missing. Red cross painted over roundabout roundal	03/09/2025	LON: 0.854034423828125, LAT: 51.88409423828125; DETAILS: Junction with Claimont road	HW: worn or missing road mark	Internal		Action Required	
3929480	RANSA 3 = 1 x 3, 50 % missing. Red Cross painted over roundabout roundal	03/09/2025	LON: 0.85421222448349, LAT: 51.88345718383789; DETAILS: Roundabout junction with Ambrose avenue	HW: worn or missing road mark	Internal		Action Required	
3929492	RANSA 4 = 1 x 4, 650mm x 450mm x >30mm	03/09/2025	LON: 0.857954, LAT: 51.87479	HW: carriageway defect	Internal		Committed	2402446
3929487	RANSA 4 = 1 x 4, CWPH 550mm x 400mm x >40mm	03/09/2025	LON: 0.854211, LAT: 51.883574; DETAILS: Roundabout junction with Ambrose avenue	HW: carriageway defect	Internal		Committed	2402446

Customer Services

Enquiry No.: 4038799

Logged by:

on: 06/05/2026 14:29

Service: Maintenance

Subject: carriageway defects

Classification: fault reports

Desc.: Vehicle damage due to pothole

Location: INSURANCE CLAIM *** Outside 8 Kingsmead Hall Woodland Drive, Lexden, CO3 9FE

Contact:

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Customer Services

Enquiry No.: 4036101 Logged by: CRM Connector on: 18/04/2026 17:51

Service: Maintenance Subject: carriageway defects Classification: fault reports

Desc.: Customer Selection=Deeper than 5cm,This report relates to an already recorded carriageway defect (Ref: 3982498).

The pothole measured approximately 180 cm x 84 cm x 9.5 cm deep and caused damage to my vehicle on 9/03/2026 at ~13:30.

I understand the defect has since been repaired following my incident. I am submitting this report to obtain an enquiry/reference number required to proceed with a vehicle damage claim and to link my claim to the existing recorded defect.

This is not a new defect report.

Location: Outside 8 Kingsmead Hall, Woodland Drive, Lexden, CO3 9FE (What3words location: /// pots.wage.option) - same location as previously recorded defect Ref: 3982498

Contact:

Enquiry No.: 4034334 Logged by: CRM Connector on: 07/04/2026 16:30

Service: Maintenance Subject: carriageway defects Classification: fault reports

Desc.: Customer Selection=Around 4cm deep,The whole of straight road needs checking from lessen/London road traffic lights right upto dugard avenue. Some potholes have been filled but there is loads along the road and such a terrible ride. The amount of times I've hit them even though I tried to avoid them. Someone should walk the length and paint all pot holes! It's a terrible road. Please get someone to walk it all and look. Personally road need resurfacing.

Location: Straight road, colchester**Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Defect Number: 3982472

Enquiry No.: 4032495 Logged by: CRM Connector on: 26/03/2026 09:38

Service: Maintenance Subject: carriageway defects Classification: fault reports

Desc.: Customer Selection=Around 4cm deep,The pot holes are getting worse and have been there for a number of weeks.

Location: Two very large pot holes one between straight rd traffic lights and chaucer way in the middle of the lane. The other outside number 83 straight Road. There are numerous holes and uneven surface at the traffic lights on straight Road with the junction with London Road. The surface is extremely loose and pitted. Cars are swerving to avoid the pot holes and entering the opposite side of the road or mounting the pathway. This is dangerous and cannot be left any longer.

Contact:

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Job Number: 2406357 **Defect Number:** 3982506

Enquiry No.: 4031533 Logged by: CRM Connector on: 21/03/2026 00:04

Service: Maintenance Subject: carriageway defects Classification: fault reports

Desc.: Customer Selection=Yes, continue to report surface deterioration or uneven surfaces,Close to the kerb and around a water source(I think),getting worse day by day.

Location: Entrance to garden drive.**Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Defect Number: 3982472

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Customer Services

Enquiry No.: 4030107	Logged by: CRM Connector	on: 14/03/2026 00:18
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Yes, continue to report surface deterioration or uneven surfaces,You can't stop on a busy road and take photographs; it is too dangerous. When are you going to get this fixed? The roads are worse than those that existed in the former Eastern Block under Stalin.		
Location: Look, there are several large potholes on Straight Road. These are of a size that makes them very difficult to avoid if driving, unless one swerves into oncoming traffic. These need fixing now. Unless you address this quickly you will get complaints, road users will be endangered and people will be injured or killed.		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2402446	Defect Number: 3929486	
Enquiry No.: 4026580	Logged by: CRM Connector	on: 26/02/2026 20:56
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm,Pot hole has already been reported but is deteriorating rapidly due to weight of traffic using this road		
Location: Straight Road, Colchester, just south of its junction with Woodland Drive, on the southbound side of the road.		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2406611		
Enquiry No.: 4026578	Logged by: CRM Connector	on: 26/02/2026 20:47
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm,A pot hole approximately 45 cms by 45 cms and 20 cms deep		
Location: Straight Road, Colchester, approximately 4 metres North of its junction with Heath Road. On the South bound side of the road.		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2404414	Defect Number: 3976868	
Enquiry No.: 4024938	Logged by: CRM Connector	on: 21/02/2026 11:28
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm,Deep pothole just before a braking zone and in line with vehicle tyres. Dangerous to cyclists too.		
Location: On the left side of the road as you approach the junction. Hole is in line with vehicle tyres.		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2404414	Defect Number: 3976868	
Enquiry No.: 4024917	Logged by: CRM Connector	on: 21/02/2026 08:13
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm,Size beyond the width of pot hole, and length, and probably 20cm plus deep, Sufficient size that vehicles avoiding have to move across the whit lines. As a side matter, I have reported this in previous years and it has been repaired, poorly. If it was done properly then this has to reduce the likelihood of further failures.		
Location: **150** Pot hole exposing the drain cover by side of the pavement		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2403847	Defect Number: 3974252	

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Customer Services

Enquiry No.: 4024904	Logged by: CRM Connector	on: 21/02/2026 00:17
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Subsidence,Subsided road surface where marker placed		
Location: subsided road surface where marker placed before mini roundabout		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2406611	Defect Number: 3987534	
Enquiry No.: 4024903	Logged by: CRM Connector	on: 21/02/2026 00:16
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Subsidence, Large dip in the road surface causing passing cars to bounce as they go over. Entire road condition is unacceptable and needs urgent attention before an accident happens and someone gets hurt or killed.		
Location: Just before to heath road roundabout		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2406611	Defect Number: 3987534	
Enquiry No.: 4024901	Logged by: CRM Connector	on: 21/02/2026 00:12
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm, Large hole in middle of mini roundabout, causing cars to swerve to avoid and having just had to swerve to avoid the hole to left just before the roundabout causes a dangerous situation.		
Location: In centre of mini roundabout of heath road to straight road		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
	Defect Number: 3982493	
Enquiry No.: 4024900	Logged by: CRM Connector	on: 21/02/2026 00:10
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm, Degraded road surface just before mini roundabout several holes some quite deep in area		
Location: Several holes just before ambrose ave mini roundabout		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
	Defect Number: 3982538	
Enquiry No.: 4024899	Logged by: CRM Connector	on: 21/02/2026 00:09
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm, Deep pot hole left side of road. Causing cars to have to go on the wrong side of the road to avoid, coming dangerously close to other vehicles. Extremely dangerous when filled with rain water and becomes invisible, especially to cyclists.		
Location: Hole on left side of road surface		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2402446	Defect Number: 3929486	
Enquiry No.: 4024897	Logged by: CRM Connector	on: 21/02/2026 00:06
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm, Extremely deep hole in carriageway, causing vehicles to have to swerve to avoid. Urgent repair needed as current state is unacceptable.		
Location: Hole near centre of road jus past chaucer way		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2402446	Defect Number: 3971756	

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Customer Services

Enquiry No.: 4024896 **Logged by:** CRM Connector **on:** 21/02/2026 00:03
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Deeper than 5cm,Very deep pot hole just before roundabout, please fix urgently as there is a high chance of a cyclist or motorcyclist getting killed or seriously hurt here as the hole is invisible when full of water.
Location: Left side of road just before mini roundabout **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Job Number: 2404414 **Defect Number:** 3976868

Enquiry No.: 4023953 **Logged by:** CRM Connector **on:** 18/02/2026 09:51
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Deeper than 5cm,Pothole approx 75cm long, 30cm wide, 7.5cm deep. About the size of a tyre. Down to the concrete and exposing the metal of the side of the drain. Dangerous. Broke my shock absorber on 16/2/26.
Location: Opposite 142 Straight Road, just after the Ambrose Avenue mini roundabout as you drive towards London Road. Next to the drain.
What3words approx location ///cape.curving.spill **Contact:**

Enquiry No.: 4023756 **Logged by:** CRM Connector **on:** 17/02/2026 15:19
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=not selected,This issue has been getting worse and is now very dangerous. Previous attempt to fill it has failed and hole is increasing in size and depth at an alarming rate. Very dangerous now and hard to avoid. Previous repair stones all on pavement. Close proximity to primary school means many young children walk past here and if a car swerves to avoid this massive hole could cause accident. - Defect 3971756 has got worse
Location: Straight rd Lexden just before Chaucer way **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Job Number: 2402446 **Defect Number:** 3971756

Enquiry No.: 4023583 **Logged by:** CRM Connector **on:** 17/02/2026 10:08
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Deeper than 5cm,Several potholes causing issue for turning in or out of straight road.
Suggest a complete survey done of straight road from London Road Junction to Shrubend Road junction. Now has many deep potholes and where passed trench works have sunk badly.
Location: Junction of London Rd/Straight road. **Contact:**

Enquiry No.: 4023581 **Logged by:** CRM Connector **on:** 17/02/2026 10:00
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Surface around a cover,Dangerous deep pothole next to drain cover, approx 30cm deep..
Location: On straight Road , in direction of London Rd. Just passed ambrose ave junction on left. **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Defect Number: 3982538

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Customer Services

Enquiry No.: 4023422	Logged by: CRM Connector	on: 16/02/2026 17:27	Enquiry Ref: M25TP001675
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Customer Selection=Deeper than 5cm,The potholes are both nearly invisible at the moment as they are full of water. [REDACTED] was thrown off [REDACTED] bike. We are not sure of the extent of damage to the bike (definitely the tyre has gone) [REDACTED] However, the potential for this being far more serious is obvious - he could have landed in the path of a car. Fortunately [REDACTED] always wears a helmet . We shall understand the implications of his injuries once the assessment has been done. The first photo below is of the pothole near Heath Rd - you can see that it is almost invisible but is full of water. It is deep enough to throw a cyclist. The second one is the pothole near Clairmont Rd. They are both on Straight Rd. I would suggest that potholes are even more dangerous for cyclists than cars - you cannot always swerve to avoid them if cars are passing you, currently they are often full of water so almost invisible and the potential injuries from being thrown off your bike or into the path of a car could be fatal. ***150*** There are two very deep potholes on Straight Road , the one between Heath Rd junction and the zebra crossing caused an accident this morning where [REDACTED] was thrown from [REDACTED] bicycle. The other deep pothole is beyond the zebra crossing on the other side of the road near Clairmont Rd.			
Location: INSURANCE CLAIM - Between zebra crossing and Heath Road - Opposite number 123 - near kerb		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799		Feature Type: PR2 Road
Job Number: 2404414			
Enquiry No.: 4023406	Logged by: CRM Connector	on: 16/02/2026 16:58	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Customer Selection=not selected,Very large pothole, stones all over the road and houses. Also very deep. Cars are swerving to avoid this issue, posing a risk to other road users and to the children from the local schools who often walk down here. It's getting worse every day. - Defect 3971756 has got worse			
Location: Outside number 45 / 56		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799		Feature Type: PR2 Road
Defect Number: 3971756			
Enquiry No.: 4023380	Logged by: CRM Connector	on: 16/02/2026 16:07	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Customer Selection=Yes, report a large pothole with photos,Pothole in the road towards the centre line of the road. Unable to measure due to high traffic flow but photo is attached. Photo taken 16 February 2026.			
Location: 132 Straight Road, Colchester. CO3 9DL What three words is. frozen.fight.supper		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799		Feature Type: PR2 Road
Defect Number: 3970577			
Enquiry No.: 4022613	Logged by: CRM Connector	on: 13/02/2026 18:56	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Customer Selection=Deeper than 5cm,This pothole is about 50cm by 80cm and deeper than 15cm. It is very very large and cars traveling on Straight Road either risk getting it and damage the suspension or some are driving on the driveway or the incoming traffic side.			
Location: **MEMBER ENQUIRIES** On the road surface in front of 117 Straight Road		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799		Feature Type: PR2 Road
Job Number: 2404342			
Defect Number: 3976554			
Enquiry No.: 4022284	Logged by: CRM Connector	on: 12/02/2026 21:42	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Customer Selection=Deeper than 5cm,It's extremely large and make a horrible noise on car when hit is wet n dark			
Location: Drivers side of road left hand lane going towards mini roundabout on straight road		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799		Feature Type: PR2 Road
Defect Number: 3982538			

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Customer Services

Enquiry No.: 4022001 **Logged by:** CRM Connector **on:** 12/02/2026 10:19
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Deeper than 5cm,CALLER STATES: Square shaped, slight larger than a drainage gate. Looks to be 4-5inches, maybe more. :KD
Location: ***150*** Left of the facing away from Ambrose road. **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Defect Number: 3970577

Enquiry No.: 4021784 **Logged by:** CRM Connector **on:** 11/02/2026 16:04
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Around 4cm deep, Approx 60cm x 30cm UPDATED is now a couple of feet across, 4 inches deep. Forcing cars to drive to the other side of the road.. KD
Location: ***150*** Just past Gospel mission - few houses b4 junction with chaucer way **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Job Number: 2402446 **Defect Number:** 3971756

Enquiry No.: 4021576 **Logged by:** CRM Connector **on:** 11/02/2026 10:00
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Deeper than 5cm.,.
Location: Straight road has like 5 potholes from the top by the traffic lights to the dental practice **Contact:**

Enquiry No.: 4021394 **Logged by:** CRM Connector **on:** 10/02/2026 16:46
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Around 4cm deep,Pothole 1 metre long x half metres wide in driving line, closer to kerb side.
Location: pothole on straight road very close to junction of woodland drive **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Job Number: 2406611 **Defect Number:** 3987534

Enquiry No.: 4021375 **Logged by:** CRM Connector **on:** 10/02/2026 16:04
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=not selected,About a foot long and 5/6 inches deep. In the middle of the road - Defect 3781871 has got worse
Location: Near the church on straight road **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Job Number: 2402446 **Defect Number:** 3971756

Enquiry No.: 4020638 **Logged by:** CRM Connector **on:** 09/02/2026 01:42
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: ** Accessibility Enquiry ** Customer Selection=Deeper than 5cm,Post hole has a sharp face with more than 10cm depth as more stones are getting washed out. Position is a couple of feet out from the kerb. See photos.
Location: On Straight Road near the roundabout/junction with Clairmont Road **Contact:**

Enquiry No.: 4020409 **Logged by:** CRM Connector **on:** 08/02/2026 10:30
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Deeper than 5cm,In the middle of the lane. Been there a couple weeks but has been getting increasingly worse over these weeks. Very deep and very large now. Stones are flying from it when people drive over it
Location: Outside 45 straight road, on the other side of the road. **Contact:**

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Customer Services

Enquiry No.: 4019663	Logged by: CRM Connector	on: 05/02/2026 20:54
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm,Pothole deep enough to cause damage to car /motorbike /cycle, filled with water.		
Location: Outside 291 straight road. On left hand side of road. John carter rd to duggard ave direction		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Defect Number: 3970575		
Enquiry No.: 4019661	Logged by: CRM Connector	on: 05/02/2026 20:46
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm,Tarmac comes out, causing issues for car/ motorcycles,		
Location: London Rd to duggard ave direction. Outside 234/5 straight rd. On drivers side of rd towards middle.		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2402446		
Enquiry No.: 4019660	Logged by: CRM Connector	on: 05/02/2026 20:41
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm,Tarmac come out of this big ball size hole. Will cause damage to cars.		
Location: London Rd to duggard ave direction. Outside 232 straight rd. On drivers side of rd towards middle.		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2402446		
Enquiry No.: 4018644	Logged by: CRM Connector	on: 02/02/2026 16:07
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Yes, continue to report surface deterioration or uneven surfaces,Iron works loose road surface disintegrating		
Location: Roundabout junction straight Road Heath road		Contact:
Plot Number: 1,000.00	Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799	Feature Type: PR2 Road
Job Number: 2402446		
Enquiry No.: 4018580	Logged by: CRM Connector	on: 02/02/2026 14:10
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
Desc.: Customer Selection=Deeper than 5cm,Dear Essex Highways Team, I would like to formally report a large and worsening pothole on the public road adjacent to my driveway in Colchester. The pothole is substantial in size and depth and poses a clear hazard to road users, including cars, cyclists, and pedestrians crossing the road. Vehicles are forced to brake or swerve suddenly to avoid it, increasing the risk of collisions, vehicle damage, and injury. The defect also appears to be deteriorating further, particularly with regular traffic and wet weather. Given its location next to a residential driveway and pedestrian areas, this defect presents a genuine safety concern. I have attached photographs showing the size, depth, and position of the pothole to assist with your assessment. I would be grateful if this issue could be inspected as a priority and repaired as soon as possible to prevent accidents or further deterioration of the carriageway. Please confirm receipt of this report and advise on the anticipated inspection or repair timeframe. Thank you for your attention to this matter. Yours faithfully, [REDACTED]		
Location: **MEMBER ENQUIRIES** Outside 117 Straight Road driveway, very large and worsening pothole, the size of a football and deeper than 5cm		Contact:

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Customer Services

Enquiry No.: 4015525 **Logged by:** CRM Connector **on:** 22/01/2026 14:44
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Around 4cm deep,It's a pothole which is unavoidable I was driving to work in my new car which I haven't long bought I hit it on the way, then the next day I was driving again this time I tried to avoid it as it can cause damage and I hit the edge of the pothole knocking me into the curb meaning I damage my wheels therefore I am requesting compensation I have videos of the damage and pothole but I can't submit below
Location: There was a pothole which I couldn't avoid on the road and I am entitled to receive **Contact:** compensation as I've got damage on my car due to it

Enquiry No.: 4015057 **Logged by:** CRM Connector **on:** 20/01/2026 22:34
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Surface around a cover,Manhole has sunk and is now around 75mm below the road surface causing a huge jolt if traversed - now dangerous as traffic is avoiding the large hole and crossing towards traffic in the opposite direction - needs URGENT attention.

No photos - too dangerous on this busy road to take any

Location: Opposite the entrance to the church on the northbound carriageway side **Contact:**

Enquiry No.: 4013997 **Logged by:** CRM Connector **on:** 16/01/2026 18:56
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Around 4cm deep,Has appeared recently
Location: Pothole in the road near number 45 Straight Road. **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Job Number: 2402446

Enquiry No.: 4013616 **Logged by:** CRM Connector **on:** 15/01/2026 18:46
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Deeper than 5cm,Pot hole been here for months worsened by recent weather.
Location: Pot hole near white line on centre of road, straight road just before Ambrose avenue. **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Job Number: 2402446

Enquiry No.: 4013609 **Logged by:** CRM Connector **on:** 15/01/2026 18:35
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Deeper than 5cm,Multiple pot holes on junction, highly dangerous due to cars cutting corner to avoid them. Dangerous to motorcyclists who are likely to come off and be injured here. Please fix urgently.
Location: Multiple pot holes on T junction of straight road. **Contact:**

Enquiry No.: 4012598 **Logged by:** CRM Connector **on:** 12/01/2026 16:37
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Deeper than 5cm,Approximately 1/3metre wide, previously filled tarmac sinking. Left wheel goes down it.
Location: At the junction of Straight rd and Baden Powell drive. On straight rd carriageway facing shrub end end direction **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 8901800_1000 - ZC79 // For further history see USRN 8901799 **Feature Type:** PR2 Road
Job Number: 2402446

Enquiry No.: 4012594 **Logged by:** CRM Connector **on:** 12/01/2026 16:22
Service: Maintenance **Subject:** carriageway defects **Classification:** fault reports
Desc.: Customer Selection=Deeper than 5cm,On the left hand side of road, Appropriate 1/3 width of carriage way, looks like previously filled tarmac now disappearing.
Location: **MEMBER ENQUIRIES** Outside 113 straight rd, in direction towards Clairmont Rd mimi roundabout. **Contact:**

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Customer Services

Enquiry No.: 4012280 Logged by: CRM Connector on: 11/01/2026 15:17
 Service: Maintenance Subject: carriageway defects Classification: fault reports
 Desc.: Customer Selection=Surface around a cover,Manhole sinking and surrounding tarmac cracking away leaving pothole. Vehicles swerving.
 Location: Outside 111 straight road colchester, in direction from John carter rd to duggard avenue Contact:

Enquiry No.: 4011796 Logged by: CRM Connector on: 09/01/2026 08:28
 Service: Maintenance Subject: carriageway defects Classification: fault reports
 Desc.: Created from Defect 3929486
 Location: LON: 0.85353, LAT: 51.885977 Contact:

Plot Number: 1,000.00 Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799 Feature Type: PR2 Road
 Job Number: 2402446 Defect Number: 3929486

Enquiry No.: 4010355 Logged by: CRM Connector on: 27/12/2025 13:50
 Service: Maintenance Subject: carriageway defects Classification: fault reports
 Desc.: Customer Selection=not selected,Pot hole around metal work has deteriorated in past week. Metal work very raised. - Defect 3954705 has got worse
 Location: Outside 337a straight Road, Colchester. Contact:

Plot Number: 1,000.00 Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799 Feature Type: PR2 Road
 Job Number: 2400035 Defect Number: 3959582

Enquiry No.: 4008507 Logged by: CRM Connector on: 11/12/2025 13:05
 Service: Maintenance Subject: carriageway defects Classification: fault reports
 Desc.: Customer Selection=Deeper than 5cm,Pothole. A deep hole adjacent to what appears to be a stopcock box in the road.
 Location: Outside 329A Straight Road. Contact:

Plot Number: 1,000.00 Feature Id - Location: 8901800_1000 - ZC79 // For further history see USRN 8901799 Feature Type: PR2 Road
 Job Number: 2406353 Defect Number: 3986123

Enquiry No.: 4008163 Logged by: CRM Connector on: 09/12/2025 18:23
 Service: Maintenance Subject: carriageway defects Classification: fault reports
 Desc.: Customer Selection=Deeper than 5cm,The area around the drain is breaking down - it's deep and spreading towards the middle of the road. Vehicles need to head onto other side of road to avoid.
 Location: New deterioration Contact:
 Area around drain
 In road outside 332a Straight Road

Enquiry No.: 2995731 Logged by: CRM Connector on: 16/09/2025 09:10
 Service: Maintenance Subject: carriageway defects Classification: fault reports
 Desc.: Customer Selection=Deeper than 5cm,Been there nearly all year pretty big now.
 Location: Outside 292 Straight Rd. It is already reported under reference 2963257 and was supposed to be fixed with the other works which were taking place over the last 2 days. But it has not been fixed and the only road works left scheduled are Open Reach.
 It has been on your radar since February - please confirm when it will be fixed. Contact:

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Customer Services

Enquiry No.: 2995730

Logged by: CRM Connector

on: 16/09/2025 09:10

Service: Maintenance

Subject: carriageway defects

Classification: fault reports

Desc.: Customer Selection=Deeper than 5cm,Been there nearly all year pretty big now.

Location: Outside 292 Straight Rd. It is already reported under reference 2963257 and was supposed to be fixed with the other works which were taking place over the last 2 days. But it has not been fixed and the only road works left scheduled are Open Reach.

Contact:

It has been on your radar since February - please confirm when it will be fixed.

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: 8901800_1000 - ZC79 // For further history see USRN 8901799		Feature Type: PR2 Road		Area: Colchester	
2387697	Replace damaged PGR railing 3.0m.	O/s 80, junction with London road	HW: Street S3	Quality audit passed	09/04/2025	11/09/2025	Act. EH/1697713
2388745	MEML 25-26 CW Patching 11.3m2 + Gully renew, refit 1no sign face, turn sign round os 282	Outside 290,304 & 308. 282	HW: Street S3	works completed	01/05/2025	22/09/2025	Act. EH/1697682
2399197	RANSA d113121230 make safe missing GY cover (HW: surface cover missing)	Nr sign for The Poplars. Opp. Heath Road	HW: Street S1	works completed	13/12/2025	13/12/2025	Act. EH/1701646
2400035	Ra8 = 2 x 4, breaking up around covers, 0.9m x 0.8m x 70mm (HW: carriageway defect)	LON: 0.8588452935218811, LAT: 51.87419891357422, os 332a	HW: Street S2 PR1/2	works completed	05/01/2026	06/01/2026	Act. EH/1702301
2402446	MEML 26-27 CW Patching to 100mm - 65.43m2	Various locations from os no 45 to os no 359 - W3W ///stuck.amount.quite to ///scale.badly.tested	HW: Capital Scheme	works completed	06/02/2026	10/04/2026	Act. EH/1708373
2403584	Ra8 = 2 x 4 CWPH 0.3m x 0.5m x 90mm nnms (HW: carriageway defect)	O/s 136	HW: Street S2 PR1/2	works completed	19/02/2026	23/02/2026	Act. EH/1705457
2403585	Ra8 = 2 x 4 CWPH by gully 0.4m x 0.4m x 90mm nnms (HW: carriageway defect)	O/s 142	HW: Street S2 PR1/2	works completed	19/02/2026	23/02/2026	Act. EH/1705457
2403586	Ra8 = 2 x 4 CWPH 0.3m x 0.5m x 90mm nnms (HW: carriageway defect)	O/s 119	HW: Street S2 PR1/2	works completed	19/02/2026	23/02/2026	Act. EH/1705457
2403847	RANSA 150 RA12=3x4 cwdf at gully >1.2mx>0.9mx>80mm (HW: carriageway defect)	os 185. Op 142.	HW: Street S2 PR1/2	works completed	23/02/2026	25/02/2026	Act. EH/1705701
2404342	RA16=4x4, cwph, 0.6m x 0.5m x 100mm NSMM (HW: carriageway defect)	Outside 117	HW: Street S1	works completed	02/03/2026	02/03/2026	Act. EH/1706139
2404414	RA16=4x4, cwph, 0.9m x 0.7m x 100mm NSMM (HW: carriageway defect)	Junction with Hunters corner	HW: Street S1	works completed	02/03/2026	02/03/2026	Act. EH/1706221

Effective: 26/06/2025 to 26/06/2026

Service: Maintenance

Display Action Officer: No

Asset Number: Up to 1000.00

Subject: carriageway defects (CWDF)

Site: STRAIGHT ROAD (8901800)

Maintenance Management									
Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order		
	Asset: 1,000.00	Asset - Locn.: 8901800_1000 - ZC79 // For further history see USRN 8901799		Feature Type: PR2 Road		Area: Colchester			
2406353	RA12=3×4, cwph around sunken water fire hydrant cover, 0.9m x 0.8m x 80mm NSMM (HW: carriageway defect)	Outside 331	HW: Street S2 PR1/2	works completed	27/03/2026	31/03/2026	Act.	EH/1707827	
2406354	RA8=2×4, cwph, 1m x 0.7m x 70mm nsmm (HW: carriageway defect)	Outside 134	HW: Street S2 PR1/2	works completed	27/03/2026	31/03/2026	Act.	EH/1707827	
2406355	RA8=2×4, cwph, 1m x 0.7m x 70mm nsmm (HW: carriageway defect)	Outside 134	HW: Street S2 PR1/2	works completed	27/03/2026	31/03/2026	Act.	EH/1707827	
2406356	RA8=2×4, cwph, 1.8m x 0.8m x 70mm nsmm (HW: carriageway defect)	Outside 81	HW: Street S2 PR1/2	works completed	27/03/2026	31/03/2026	Act.	EH/1707827	
2406357	RA8=2×4, cwph, 3m x 1m x 70mm nsmm (HW: carriageway defect)	Outside 54	HW: Street S2 PR1/2	works completed	27/03/2026	31/03/2026	Act.	EH/1707827	
2406611	RANSA Ra12=3x4 cwdf >1.2mx>0.9mx>80mm (HW: carriageway defect)	Outside 8 Kingsmead Hall Woodland Drive, Lexden, CO3 9FE, England, United Kingdom	HW: Street S2 PR1/2	works completed	01/04/2026	02/04/2026	Act.	EH/1708031	
2407295	MEML 26-27 CW patching	os 96 & 291	HW: Capital Scheme	works completed	14/04/2026	21/04/2026	Act.	EH/1709134	