	Service: Maintenance n Officer: No			Subject: carriageway Site: COWDRAY			
Site: COW	DRAY AVENUE (8900501)		Locality: COLCHEST	ER, ESSEX		Area: Colchester	
Condition Su	irvey						
Defect No: Desc	cription	Log Date	Location	Defect Type	Class. Organisation	Status	Job No
Asset:	1,000.00 Asset - Locn.:	8900501_100	0 - A133 // For further history see USRN	8900500 Feature Type: PR1 R	bad	Area: Colcheste	r
Batch: 70	091173 - Inspection Batch		Route: ad	hoc route			Date: 12/11/2024
and s	ISA 4=1x4 white line zig zag markings stop line for pedestrian crossing 90% led in both directions	12/11/2024	Just as exiting the Albert RAB	HW: worn or missing road mark	Internal	Action Required	
Batch: 70	091162 - Inspection Batch		Route: ad	hoc route			Date: 12/11/2024
3853440 RA12 NSM	2 = 3 x 4, cwph, 0.9m x 0.7m x 80mn IM	12/11/2024	LON: 0.8963712, LAT: 51.8973618, opposite The Albert	HW: carriageway defect	Internal	Committed	2378792
Batch: 70	089987 - Inspection Batch		Route: Are	ea 03 Monthly Driven			Date: 07/11/2024
appro	ISA RA3=1x3, worn zig zag lining oaching pedestrian crossing traffic s by 50%	07/11/2024	Opposite The Albert	HW: worn or missing road mark	Internal	Action Required	
Batch: 70	Batch: 7080995 - Inspection Batch Route: adhoc route						Date: 09/10/2024
3842289 RES RAN >20n	ISA 4 = 1 x 4, 700mm x 650mm x	09/10/2024	LON: 0.906336, LAT: 51.897691	HW: carriageway defect	Internal	No Action Require	ed
Batch: 70	080994 - Inspection Batch		Route: ad	hoc route			Date: 09/10/2024
3842288 RAN >50n	ISA 4 = 1 x 4, 1150mm x 600mm x mm	09/10/2024	LON: 0.897306, LAT: 51.89745; DETAILS: O/S 27	HW: carriageway defect	Internal	Action Required	
Batch: 70	080989 - Inspection Batch		Route: ad	hoc route			Date: 09/10/2024
3842286 RAN >50n	ISA 3 = 1 x 3, 300mm x 200mm x mm	09/10/2024	LON: 0.907957, LAT: 51.897798	HW: carriageway defect	Internal	Action Required	
Batch: 70	080951 - Inspection Batch		Route: ad	hoc route			Date: 09/10/2024
3842262 RAN >50n	ISA 4 = 1 x 4, 400mm x 300mm x mm	09/10/2024	LON: 0.906836, LAT: 51.897817; DETAILS: O/S 156	HW: carriageway defect	Internal	Action Required	
	080950 - Inspection Batch actionable defects found		Route: Are	ea 03 Monthly Driven			Date: 09/10/2024
Batch: 70	075876 - Inspection Batch		Route: ad	hoc route			Date: 24/09/2024
	=1x4, cw surface erosion, rutted and ven, 10m x 3m x 50mm at deepest	24/09/2024	O/s 258	HW: carriageway defect	Internal	Action Required	
Batch: 70	075853 - Inspection Batch		Route: ad	hoc route			Date: 24/09/2024
	=3x2, traffic lights Obscured by tree etation, 3m x 2m x 6m in height	24/09/2024	At junction with Meander mews traffic lights	HW: overgrown vegetation (our)	Internal	Action Required	
Batch: 70	075843 - Inspection Batch		Route: ad	hoc route			Date: 24/09/2024
	2=3x4, cwph, 0.8mm x 0.8mm x m NSMM	24/09/2024	; DETAILS: At junction with traffic light to Sports cente	s HW: carriageway defect	Internal	Committed	2375481

Site History Report

Asset Number: 1000.00 to 1000.00

25/11/2024

Effective: 21/11/2021 to 21/11/2024

Page 1 of 23

Display Action Officer: No

Asset Number: 1000.00 to 1000.00 Subject: carriageway defects (CWDF) Site: COWDRAY AVENUE (8900501)

Defect No: De	escription	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00 Asset - Locr	n.: 8900501_100	0 - A133 // For further history see USRN 8	B900500 Feature Type: PR1 R	oad		Area: Colchester	
Batch:	7075553 - Inspection Batch		Route: Area	a 03 Annual Sep Walked			Date	: 24/09/2024
	UPLICATE ANSA 4 = 1 x 4,  1350mm x 550mm x 20mm	24/09/2024	LON: 0.90925, LAT: 51.897793	HW: carriageway defect	Internal		No Action Required	
3836147 RA	A 6 = 2 x 3, cluster of CWPH, 1850mr 00mm x >60mm	n x 23/09/2024	; DETAILS: On junction with Mason road	HW: carriageway defect	Internal		Action Required	
3836594 RA	A4 = 1 x 4, 200mm x 200mm x >50m	m 24/09/2024	LON: 0.907938, LAT: 51.897797	HW: carriageway defect	Internal		Action Required	
en	A4=2 $\times$ 2, overgrown tree vegetation ncroaching on fw by 8m x 1m x 6m in eight	24/09/2024	O/s 194	HW: overgrown vegetation (our)	Internal		Action Required	
3836596 RA	A12=3x4, Cwph around water surface over, 1m x 0.5m >80mm NSMM	24/09/2024	Lon 0.90951 Lat 51.89777 junction with Mason Road, Volvo garage	HW: carriageway defect	Internal		Committed	2375493
ob sig	A6=3x2, overgrown tree vegetation oscuring visibility for traffic lights ahead gn and directional signs, 30m x 4m x 8 height		O/s Rota House Cowdray Avenue, Parson's Heath, CO1 1YA heading east	HW: overgrown vegetation (our)	Internal		Action Required	
3836146 RA	A4 = 1 x 4, cwph, 0.8m x 0.3m x 50m SMM	m 23/09/2024	LON: 0.8963712, LAT: 51.8973618, opposite The Albert	HW: carriageway defect	Internal		No Action Required	
	A12=3x4, cw ph, 0.9m x 0.5m x 80mm SMM	1 24/09/2024	At jw entrance to Leisure Centre, westbound	HW: carriageway defect	Internal		Committed	2375492
en	A6=3×2, overgrown tree vegetation ncroaching on shared footway and cyc ne, 5m x 3m x 8m in height	24/09/2024 lle	O/s 61 Rouse Way, Parson's Heath, CO1 2TT, on approach to railway bridge heading east	HW: overgrown vegetation (our)	Internal		Action Required	
3836599 RA co	A12=3×4, cwph around water surface over exposing iron work, 0.5m x 0.5m 0mm NSMM	24/09/2024 x	O/s 8 Reed Walk and opposite dfs furniture store	HW: carriageway defect	Internal		Committed	2375491
Batch:	7075506 - Inspection Batch		Route: adho	Route: adhoc route			Date: 23/09/2024	
	A12=3x4 cw eroded, breaking out into ns, approx >2.1mx>0.3mx>80mm NSN		Opp The Range, adj remote footway	HW: carriageway defect	Internal		Committed	2375432
Batch:	7072185 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date	12/09/2024
	ANSA 4 = 1 x 4, 1050mm x 750mm x 20mm	12/09/2024	LON: 0.912494, LAT: 51.897214; DETAILS: O/s 270	HW: carriageway defect	Internal		Action Required	
3831707 RA	ANSA 4 = 1 x 4, 0mm x 0mm	11/09/2024	LON: 0.8963712, LAT: 51.8973618	HW: carriageway defect	Internal		No Action Required	
	ANSA 4 = 1 x 4, 900mm x 550mm x 20mm	11/09/2024	LON: 0.897271, LAT: 51.897449	HW: carriageway defect	Internal		Action Required	
Batch:	7066993 - Inspection Batch		Route: Area	a 03 Monthly Driven			Dates	: 23/08/2024
	ANSA 4 = 1 x 4, 1200mm x 500mm x 50mm	23/08/2024	LON: 0.9047051, LAT: 51.8975983; DETAILS: At junction with Mason road	HW: carriageway defect	Internal		Action Required	
	ANSA 4 = 1 x 4, 300mm x 700mm x 20mm	23/08/2024	LON: 0.908657, LAT: 51.897889	HW: carriageway defect	Internal		Action Required	
>5	ANSA 4 = 1 x 4, 700mm x 600mm x 50mm	23/08/2024	LON: 0.896344, LAT: 51.897415	HW: carriageway defect	Internal		Action Required	
	ANSA 4 = 1 x 4, 950mm x 600mm x 20mm	23/08/2024	LON: 0.897278, LAT: 51.897449	HW: carriageway defect	Internal		Action Required	

Display Action Officer: No

Asset Number: 1000.00 to 1000.00 Subject: carriageway defects (CWDF) Site: COWDRAY AVENUE (8900501)

efect No: Description	Log Date	Location	Defect Type	Class. Organisa	ation Status	Job No.
Asset: 1,000.00 Asset - Locn.:	8900501_100	0 - A133 // For further history see USRN	8900500 Feature Type: PR1 R	oad	Area: Colcheste	er
Batch: 7066993 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date: 23/08/2024
3826544 RANSA 4 = 1 x 4, 350mm x 200mm x >40mm	23/08/2024	LON: 0.907938, LAT: 51.897797	HW: carriageway defect	Internal	No Action Requir	ed
3826543 RANSA 4 = 1 x 4, 1350mm x 550mm x >20mm	23/08/2024	LON: 0.90925, LAT: 51.897793	HW: carriageway defect	Internal	No Action Requir	ed
3826545 RANSA 4 = 1 x 4, 700mm x 650mm x >20mm	23/08/2024	LON: 0.906336, LAT: 51.897691	HW: carriageway defect	Internal	No Action Requir	ed
Batch: 7051873 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date: 10/07/2024
3810291 RANSA 6 = 2 x 3, cluster of CWPH, 1850mm x 300mm x >60mm	10/07/2024	; DETAILS: On junction with Mason road	HW: carriageway defect	Internal	No Action Requir	ed
3810293 RANSA 4 = 1 x 4, 900mm x 300mm x >50mm	10/07/2024	; DETAILS: At junction with traffic lights to Sports cente	HW: carriageway defect	Internal	No Action Requir	ed
Batch: 7043667 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date: 12/06/2024
No actionable defects found						
Batch: 7039887 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date: 28/05/2024
3796536 RANSA RA4=1x4, Cwph, on outside lane, 0.5m x 0.3m x >50mm	28/05/2024	Opposite 170, Lon 0.91145 Lat 51.89745	HW: carriageway defect	Internal	Action Required	
Batch: 7035284 - Inspection Batch		Route: adh	oc route			Date: 05/05/2024
3791993 RANSA gang sent to make safe carriageway pothole	05/05/2024	COWDRAY AVENUE, COLCHESTER oppisite RAJ Bakery ,	HW: carriageway defect	Internal	Committed	2367118
Batch: 7035275 - Inspection Batch		Route: adh	oc route			Date: 03/05/2024
3791984 RANSA gang sent to make safe pothole	03/05/2024	COWDRAY AVENUE, COLCHESTER Near to the roundabout that meets St Andrews Avenue/Ipswich Road.	HW: carriageway defect	Internal	Committed	2367108
Batch: 7035035 - Inspection Batch		Route: adh	oc route			Date: 02/05/2024
3791794 RANSA gang sent to make safe failed gully cover	02/05/2024	COWDRAY AVENUE, COLCHESTER **150**Cowdray Avenue . SJ	HW: surface cover mis-aligned	Internal	Committed	2367035
Batch: 7031785 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date: 19/04/2024
No actionable defects found						
Batch: 7025316 - Inspection Batch		Route: adh	oc route			Date: 13/03/2024
3781993 RANSA SS13030134 job raised to make safe missing gully cover.	13/03/2024	Approx 75m from Albert RAB	HW: surface cover missing	Internal	Committed	2364302
Batch: 7025315 - Inspection Batch		Route: adh	oc route			Date: 13/03/2024
3781992 Map16 asset risk level: Medium	12/03/2024		HW: surface cover damaged	Internal	Action Required	
Batch: 7025314 - Inspection Batch		Route: adh	oc route			Date: 13/03/2024
3781991 Map16 asset risk level: Medium	12/03/2024		HW: surface cover damaged	Internal	Action Required	
Batch: 7024076 - Inspection Batch		Route: Area	a 03 Monthly Driven		·	Date: 06/03/2024
No actionable defects found			-			

Display Action Officer: No

Condition Survey						
Defect No: Description	Log Date	Location	Defect Type	Class. Organisation	n Status	Job No.
Asset: 1,000.00 Asset - Locn.:	8900501_100	0 - A133 // For further history see USRN	8900500 Feature Type: PR1 R	oad	Area: Colchester	
Batch: 7023739 - Inspection Batch		Route: adh	oc route			Date: 05/03/2024
3780538 RA8=2x4, cwph, 0.7m x >0.5m x 65mm	05/03/2024	Opposite Beefeater, Lon 0.89644 Lat 51.89736, near traffic light jw The Alber RAB		Internal	Committed	2363790
Batch: 7023724 - Inspection Batch		Route: adh	oc route			Date: 05/03/2024
3780515 RA6=2x3, cwph on centre line, 1m x 0.4m x 70mm NSMM RESOLVED	05/03/2024	Opposite junction with Cowdrey avenue service road and opposite lighting column 18	e HW: carriageway defect	Internal	No Action Require	d
Batch: 7022217 - Inspection Batch		Route: adh	oc route			Date: 26/02/2024
3779052 Map16 asset risk level: Medium	26/02/2024		HW: gully cover stuck	Internal	Action Required	
Batch: 7020814 - Inspection Batch		Route: adh	oc route			Date: 20/02/2024
3777255 RA6=2x3, standing water on cw, slow to clear. RESOLVED	20/02/2024	O/s 2, opposite Pets at home	HW: Standing Water	Internal	No Action Require	d
Batch: 7020412 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date: 20/02/2024
3776868 RANSA 6=2x3 cw ph >0.3mx>0.8x>50mm	18/02/2024	Opp entrance to Leisure Centre	HW: carriageway defect	Internal	Action Required	
3777233 RANSA 6=2x3 cw ph approx >1.6mx>1.2mx60mm RESOLVED	20/02/2024	LON: 0.91290 LAT: 51.89700, adj traffi light sign	cHW: carriageway defect	Internal	No Action Require	d
3776875 RANSA 4=1x4 cw ph approx >1.6mx>0.8mx>50mm	18/02/2024	On railway bridge, LON: 0.91695 LAT: 51.89333	HW: carriageway defect	Internal	Action Required	
3776870 RANSA 4=1x4 cw ph, broken out on horizontal joint, approx >0.2mx>0.9mx>50mm	18/02/2024	Near os 194, near adj to entrance to retail park	HW: carriageway defect	Internal	Action Required	
3777380 RANSA 6=2x3, cw ph approx >0.5mx>0.6mx>60mm	20/02/2024	Opposite Beefeater, Lon 0.89644 Lat 51.89736, near traffic light jw The Alber RAB	HW: carriageway defect t	Internal	No Action Require	d
3776871 RANSA 4=1x4 triangle warning Traffic Lights sign is 60% obscured with dirt	18/02/2024	Near entrance to Colne View Retail Park	HW: roadsign obscured or dirty	Internal	Committed	2372623
3777368 RÅNSA 4=1x4 cw ph approx >0.2mx>0.3mx>50mm	20/02/2024	Os Aqua Springs, at traffic lights, LON: 0.90539 LAT: 51:89762	HW: carriageway defect	Internal	Action Required	
3777254 RANSA 6=2x3 cw ph approx >1.0mx>0.9mx>60mm DUPLICATE	20/02/2024	Os 266 LON: 0.91204 LAT: 51.89701	HW: carriageway defect	Internal	No Action Require	d
3776863 RANSA 4=1x4 white line zig zag markings and stop line for pedestrian crossing 90% eroded	18/02/2024	Just as exiting the Albert RAB	HW: worn or missing road mark	Internal	No Action Require	d
3777296 RANSA 4=1x4 top half of directional road sign missing, rest of sign is 60% obscured by dirt	20/02/2024	Os Leisure Centre at start of dualled CW section, westbound	HW: roadsign damaged	Internal	Action Required	
3777359 RANSA 4=1x4 yellow box junction markings are 70% eroded RESOLVED	20/02/2024	jw entrance to Leisure Centre	HW: worn or missing road mark	Internal	No Action Require	d
3776869 RANSA 4=1x4 cw ph approx >0.25mx>0.25mx>50mm DUPLICATE	18/02/2024	opp Ic 42, LON: 0.90672 LAT: 51.8978	2 HW: carriageway defect	Internal	No Action Require	d
3777377 RANSA 4=1x4 cw eroded, breaking out into phs, approx >2.1mx>0.3mx>50mm	20/02/2024	Opp The Range, adj remote footway	HW: carriageway defect	Internal	No Action Require	d

Display Action Officer: No

Asset Number: 1000.00 to 1000.00 Subject: carriageway defects (CWDF) Site: COWDRAY AVENUE (8900501)

Defect No:	Description	Log Date	Location	Defect Type	Class. Organisation	Status	Job No.
Ass	et: 1,000.00 Asset - Locn.:	8900501_100	0 - A133 // For further history see USRN	8900500 Feature Type: PR1 R	oad	Area: Colchester	
Batc	:h: 7020412 - Inspection Batch		Route: Area	a 03 Monthly Driven		Date	20/02/2024
	RANSA 6=2x3 cw reinstatement breaking out approx >0.5mx>0.3mx>50mm, close to pedestrian crossing walking line	20/02/2024	Os Aqua Springs at traffic lights, LON: 0.90540 LAT: 51.89762	HW: carriageway defect	Internal	Action Required	
	RANSA 4=1x4 warning triangle Traffic Lights road sign is 80% obscured by dirt	20/02/2024	os Leisure centre 5 a side football pitches - opp Lookers Volvo dealer, LON: 0.90911 LAT: 51: 89778	HW: roadsign obscured or dirty	Internal	Committed	2372623
	RANSA 6=2x3 double cover in cw sunken and misaligned, cw broken out around it (don't know whose cover it is) approx >1.4m>0.6mx>50mm	20/02/2024	Opp entrance to retail park (Volvo), LON: 0.90956 LAT: 51.89776	HW: surface cover mis-aligned	Internal	Action Required	
	RANSA 4=4x1 2 x kerb gully covers misaligned, displaced, on verge, approx 0.7mx>0.4mx50mm	18/02/2024	approx opp 324, near adj pedestrian crossing island	HW: surface cover mis-aligned	Internal	Action Required	
	RANSA 6=2x3 2 x 2m sections of PGR struck and damaged at junction with RAB, approx >4.0mx>1.0mx>50mm	18/02/2024	jw Ipswich Road RAB	HW: ped guardrail damaged	Internal	Action Required	
3777358	RANSA 4=1x4 cw ph approx >0.3mx>0.65mx>50mm	20/02/2024	At jw entrance to Leisure Centre, westbound	HW: carriageway defect	Internal	No Action Required	
	RANSA 4=1x4 cw ph approx >0.2mx>0.5mx>50mm	18/02/2024	adj bus stop, opp 282	HW: carriageway defect	Internal	Action Required	
3776865	RESOLVED	18/02/2024	Os 42	HW: worn or missing road mark	Internal	No Action Required	
	RANSA 4=1x4 cw ph, broken out on horizontal joint, approx >0.1mx>0.6mx>50mm	18/02/2024	Just past opp jw Meander Mews	HW: carriageway defect	Internal	Action Required	
	RANSA 4=1x4 white line directional arrow markings and for right filter lane are 80% eroded	18/02/2024	Os Colne View Retail Park	HW: worn or missing road mark	Internal	Action Required	
	RANSA 6=2x3 cw eroded centre line approx >3.0mx>0.25mx>50mm	18/02/2024	Jw Mason Road	HW: carriageway defect	Internal	Action Required	
	RANSA 6=2x3 double surface cover sunken and misaligned, cw breaking up around it approx >1.2mx>0.8mx>70mm	20/02/2024	LON: 0.90938 LAT: 51.89777, opp entrance to retail park, Volvo garage	HW: surface cover mis-aligned	Internal	Action Required	
	RANSA 4=1x4 white line central hatchings, ahead arrow, right filter lane arrow and SLOW markings are 70% eroded	18/02/2024	os 38 prior to jw Catchpool Rd	HW: worn or missing road mark	Internal	Action Required	
	RANSA 6=2x3 cw breaking up around sunken and misaligned double cover in cw, approx >1.2m>0.6mx>50mm RESOLVED	20/02/2024	Opposite Volvo garage, LON: 0.90938 LAT: 51.89777	HW: carriageway defect	Internal	No Action Required	
	RANSA 4=1x4 white line lane arrow markings, straight ahead and right hand filter lane are 90% eroded	20/02/2024	Opp Colne View Retail Park, LON: 0.91018 LAT: 51.89769	HW: worn or missing road mark	Internal	Action Required	

Display Action Officer: No

**Condition Survey** 

efect No: Description	Log Date	Location	Defect Type	Class. Organisation	Status	Job No
Asset: 1,000.00 Asset - Locn.:	8900501_100	0 - A133 // For further history see USRN 8	B900500 Feature Type: PR1 R	oad	Area: Colchester	r
Batch: 7020412 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date: 20/02/2024
3776866 RANSA 4=1x4 yellow box junction markings on both sides of cw outside fire station are 80% eroded	18/02/2024	Os and opp Fire Station	HW: worn or missing road mark	Internal	Action Required	
3777277 RANSA 6=2x3 cw broken out around misaligned double cw surface cw approx >1.8mx>1.2mx>70mm	20/02/2024	O/s 8 Reed walk Lon 0.90958 Lat 51.89775	HW: carriageway defect	Internal	Action Required	
Batch: 7013297 - Inspection Batch No actionable defects found		Route: Area	a 03 Monthly Driven			Date: 16/01/2024
Batch: 7010048 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date: 27/12/2023
3766180 RANSA RA3=1x3, Cwph, 0.7m x 0.4m x >50mm	27/12/2023	O/s 266 Lon 0.91302 Lat 51.89694	HW: carriageway defect	Internal	No Action Require	ed
3766179 RANSA RA4=1x4, cwph, 1m x 0.8m x >50mm at deepest	27/12/2023	Opposite Beefeater, Lon 0.89644 Lat 51.89736	HW: carriageway defect	Internal	No Action Require	ed
3766178 RANSA RA6=2x3, Surface cover sunk, 1.2m x 0.8m x >70mm at deepest	27/12/2023	Lon 0.90937 Lat 51.89778	HW: surface cover mis-aligned	Internal	No Action Require	ed
3766177 RANSA RA4=1x4, Cwph around water surface cover, 0.7m x 0.5m >50mm	27/12/2023	Mason Road, Volvo garage	HW: carriageway defect	Internal	No Action Require	ed
3766176 RANSA RA6=2x3, Surface cover sunk, 1.2m x 0.8m x >70mm at deepest	27/12/2023	O/s 8 Reed walk Lon 0.90958 Lat 51.89775	HW: surface cover mis-aligned	Internal	No Action Require	ed
3766175 RANSA RA4=1x4, cwph, 1m x 0.8m x >50mm at deepest	27/12/2023	Lon 0.91290 Lat 51.89700	HW: carriageway defect	Internal	No Action Require	ed
Batch: 7000633 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date: 09/11/2023
No actionable defects found						
Batch: 6998792 - Inspection Batch		Route: adhe	oc route			Date: 01/11/2023
3755098 RA12=3×4, cwph, 0.8m x 0.6m x 80mm NSMM	01/11/2023	O/s 296, at start of bus stop bay	HW: carriageway defect	Internal	Committed	235699
Batch: 6994283 - Inspection Batch No actionable defects found		Route: Area	a 03 Monthly Driven			Date: 11/10/2023
Batch: 6987938 - Inspection Batch		Route: adh	oc route			Date: 12/09/2023
3740275 RA6=3×2, missing water drainage surface cover with debris causing blockage and flooding to industrial retail units.	2/09/2023			Internal	Action Required	
Batch: 6987920 - Inspection Batch		Route: Area	a 03 Annual Sep Walked			Date: 12/09/2023
No actionable defects found			-			
Batch: 6987131 - Inspection Batch		Route: adho	oc route			Date: 08/09/2023
No actionable defects found						
Batch: 6986415 - Inspection Batch		Route: Area	a 03 Monthly Driven			Date: 06/09/2023
3738905 RANSA RA4=1×4, Sunken double cover in cway, aprox 1.2m x 0.6m x >50mm NSMM	06/09/2023	Opposite Volvo garage, Lon 0.90933 Lat 51.89777	HW: surface cover mis-aligned	Internal	No Action Require	ed

Display Action Officer: No

Asset Number: 1000.00 to 1000.00 Subject: carriageway defects (CWDF) Site: COWDRAY AVENUE (8900501)

efect No: Desc	ription		Log Date	Location	Defec	t Type	Class.	Organisation	Status	Job No
Asset:	1,000.00	Asset - Locn.: 8	3900501_100	0 - A133 // For further history	see USRN 890050	00 Feature Type: PR1 F	Road		Area: Colcheste	er
Batch: 69	79997 - Inspection	Batch			Route: Area 03 M	onthly Driven				Date: 11/08/2023
No a	ctionable defects for	bund								
Batch: 69	72189 - Inspection	Batch			Route: Area 03 M	onthly Driven				Date: 11/07/2023
No a	ctionable defects fo	bund								
Batch: 69	66307 - Inspection	Batch			Route: Area 03 M	onthly Driven				Date: 15/06/2023
No a	ctionable defects fo	ound								
Batch: 69	60101 - Inspection	Batch			Route: Area 03 M	onthly Driven				Date: 17/05/2023
No a	ctionable defects fo	ound								
Batch: 69	55816 - Inspection	Batch			Route: adhoc rout	e				Date: 03/05/2023
3708513 RAN RTC		ear oil following an	03/05/2023	Near fire station	HW: d	debris/deposit on highway	Interna	I	Committed	2347148
Batch: 69	55402 - Inspection	Batch			Route: adhoc rout	e				Date: 03/05/2023
No a	ctionable defects fo	ound								
Batch: 69	49124 - Inspection	Batch			Route: Area 03 M	onthly Driven				Date: 13/04/2023
No a	ctionable defects fo	bund								
Batch: 69	44881 - Inspection	Batch			Route: Area 03 M	onthly Driven				Date: 22/03/2023
No a	ctionable defects fo	ound								
Batch: 69	42183 - Inspection	Batch			Route: adhoc rout	е				Date: 10/03/2023
	=2×4, cwph, appro> m NSMM	x. 0.5m x 0.4m x	10/03/2023	O/s 33	HW: d	carriageway defect	Interna	1	Committed	2344269
Batch: 69	39527 - Inspection	Batch			Route: adhoc rout	e				Date: 28/02/2023
3689585 Ram rtc	sa gang called to m	nake safe following	28/02/2023	Near calibre car sales	HW: d	debris/deposit on highway	Interna	I	Committed	2343723
Batch: 69	38642 - Inspection	Batch			Route: adhoc rout	e				Date: 21/02/2023
	ERSEDED =2x3, worn marking vs and right turn bo		21/02/2023	opposite entry to Lookers & Retail Park (westbound sid Meander Mews		vorn or missing road mark	Interna	I	Action Required	
Batch: 69	36811 - Inspection	Batch			Route: Area 03 M	onthly Driven				Date: 10/02/2023
No a	ctionable defects fo	ound								
Batch: 69	32981 - Inspection	Batch			Route: Area 03 M	onthly Driven				Date: 24/01/2023
	SA RA4=1×4, TEM ing x2	P BOLLARDS	24/01/2023	Outside 330, Lon 0.91439,	lat 51.89606 HW: t	pollard missing	Interna	I	Action Required	
Batch: 69	32017 - Inspection	Batch			Route: adhoc rout	e				Date: 19/01/2023
	5=4x4 10m x 1.8m s salting SA	ice covered FW	19/01/2023	Riverside leasure	HW: d	debris/deposit on highway	Interna	I	Committed	234156

Display Action Officer: No

**Condition Survey** 

Defect No: Description	Log Date	Location	I	Defect Type	Class.	Organisation	Status	Job No
Asset: 1,000.00 Asset - Loc	n.: 8900501_100	0 - A133 // For further histor	y see USRN 8	000500 Feature Type: PR1 R	Road		Area: Colches	ster
Batch: 6931565 - Inspection Batch			Route: adhoo	c route				Date: 17/01/2023
3680873 SUPERSEDED RA12=3x4, cwph, approx. 1.2m x 0.8m 80mm, NSMM	17/01/2023 x	Opp 10	ł	HW: carriageway defect	Internal		Committed	234142
Batch: 6928546 - Inspection Batch			Route: adhoo	c route				Date: 29/12/2022
3677903 Ransa Make safe pothole in carriagewa DP29122115	ay 29/12/2022	Between Fire Station and RAB	The Albert	HW: carriageway defect	Internal		Committed	234052
Batch: 6927598 - Inspection Batch			Route: adhoo	c route				Date: 20/12/2022
3677171 RANSA RA4=1×4, tmp bollard damage and lying on traffic island	ed 20/12/2022	Outside 324, Lon 0.91433	Lat 51.89612	HW: bollard damaged	Internal		Committed	234351
Batch: 6927182 - Inspection Batch			Route: Area	03 Monthly Driven				Date: 16/12/2022
3676792 RA12=3x4, cwph, 1m x 0.6m x 80mm NSMM	16/12/2022	Outside 10	ł	HW: carriageway defect	Internal		Committed	234007
3676791 RA4=1x4, cwph with cracking across f width of cw, 7.6m x 0.3m x 60mm NSM		Outside 4	ł	HW: carriageway defect	Internal		Committed	234579
Batch: 6922504 - Inspection Batch			Route: adhoo	c route				Date: 27/11/2022
3673285 Ransa Clear oil and debris from carriageway following RTC DP271112	27/11/2022 30	Outside Leisure World	ł	HW: debris/deposit on highway	Internal		Committed	233920
Batch: 6921577 - Inspection Batch			Route: Area	03 Monthly Driven				Date: 23/11/2022
No actionable defects found								
Batch: 6912303 - Inspection Batch			Route: Area	03 Monthly Driven				Date: 19/10/2022
No actionable defects found								
Batch: 6905654 - Inspection Batch			Route: Area	03 Annual Sep Walked				Date: 23/09/2022
No actionable defects found								
Batch: 6904832 - Inspection Batch			Route: Area	03 Monthly Driven				Date: 20/09/2022
No actionable defects found								
Batch: 6897371 - Inspection Batch			Route: Area	03 Monthly Driven				Date: 17/08/2022
No actionable defects found								
Batch: 6886276 - Inspection Batch			Route: adhoo	c route				Date: 17/07/2022
3640929 Ransa gang called to clear up debris following rtc	17/07/2022	Outside fire station	ł	HW: debris/deposit on highway	Internal		Committed	233351
Batch: 6885275 - Inspection Batch			Route: Area	03 Monthly Driven				Date: 11/07/2022
No actionable defects found								
Batch: 6882668 - Inspection Batch			Route: Area	03 Monthly Driven				Date: 27/06/2022
No actionable defects found								
Batch: 6877253 - Inspection Batch			Route: adhoo	route				Date: 31/05/2022
3633893 RA12=3×4, temporary diversion sign w circle requires realignment on a frame.	ith 31/05/2022	On bridge along Cowdrey heading east, 50m from Ip roundabout		HW: Traffic Management	Internal		Committed	233165

**Condition Survey** 

Effective: 21/11/2021 to 21/11/2024 Service: Maintenance

Display Action Officer: No

efect No: Description		Log Date	Location		Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,000.00	Asset - Locn.:	8900501_100	0 - A133 // For further history	see USRN	8900500 Feature Type: PR1 R	oad		Area: Colcheste	er
Batch: 6874319 - Inspect	ion Batch			Route: Are	a 03 Monthly Driven				Date: 20/05/2022
No actionable defect	s found				-				
Batch: 6868854 - Inspect	on Batch			Route: Are	a 03 Monthly Driven				Date: 27/04/2022
No actionable defect	s found								
Batch: 6863845 - Inspect				Route: adh	oc route				Date: 25/03/2022
3624572 Ransa gang sent to RTC	lear debris following	25/03/2022	Cowdray avenue junction w	vith Mason	HW: debris/deposit on highway	Internal		Committed	2329113
Batch: 6862701 - Inspect No actionable defect				Route: Are	a 03 Monthly Driven				Date: 18/03/2022
Batch: 6861245 - adhoc				Route: adh	oc route				Date: 11/03/2022
3623011 Blocked Connection		11/03/2022	Carriageway		HW: blocked gully connection	Internal		Action Required	- 4.01 11/00/2022
3623010 Blocked Connection		11/03/2022	Carriageway		HW: blocked gully connection	Internal		Action Required	
3622945 Blocked Connection		11/03/2022	Carriageway		HW: blocked gully connection	Internal		Action Required	
3622944 Stuck Lid		11/03/2022	Carriageway		HW: surface cover damaged	Internal		Action Required	
Batch: 6856614 - Inspect	ion Batch		* *	Route: Are	a 03 Monthly Driven				Date: 16/02/2022
No actionable defect					,				
Batch: 6852771 - Inspect	ion Batch			Route: adh	oc route				Date: 31/01/2022
3617293 RA16=4×4, pedestria sections, fallen and t 40m in length, 3m in sections leaning due	locking fw, approx. height. Remaining	31/01/2022	On railway bridge		HW: ped guardrail damaged	Internal		Committed	2326453
Batch: 6849524 - Inspect				Route: Are	a 03 Monthly Driven				Date: 14/01/2022
No actionable defect	s found								
Batch: 6845971 - Inspect	on Batch			Route: Are	a 03 Monthly Driven				Date: 17/12/2021
No actionable defect	s found								
Batch: 6843299 - Inspect	on Batch			Route: adh	oc route				Date: 03/12/2021
3611378 RA16=4x4 0.9m x 0.	5m x 100mm CWPH	03/12/2021	Opp 10		HW: carriageway defect	Internal		Committed	2324313
Batch: 6843295 - Inspect	on Batch			Route: adh	oc route				Date: 03/12/2021
3611369 RA4=2x2 approx 80r faded by 60%	n x 2.0m Chevrons	03/12/2021	Os Colne Valley retail park		HW: worn or missing road mark	Internal		Action Required	
ustomer Services									
Enquiry No.: 2950139	Logge	d by: CRM C	onnector		on: 21/11/2024 18:00				
Service: Maintenance		bject: carriage	eway defects ( ot hole. About 2ft long 10" wic		on: fault reports				

Site History Report

	Asset Number:         1000.00 to         1000.00
Service: Mainte	
Display Action Officer: No	Site: COWDRAY AVENUE (8900501)
Customer Services	
Enquiry No.: 2948472	Logged by: CRM Connector on: 08/11/2024 21:56
Service: Maintenance	Subject: carriageway defects Classification: fault reports
	on=Deeper than 5cm, The pothole is quite deep. The car on the left-hand lane will have to swerve to avoid it. It is dangerous. Please put this as a high priority.
Location: Nasty pothole loc Bank Ave.	ated next to the traffic light in the left-hand lane towards Colne Contact:
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For further history see USRN 8900500 Feature Type: PR1 Road
Job Number: 2378792	Defect Number: 3853440
Enquiry No.: 2947889	Logged by: CRM Connector on: 05/11/2024 08:52
Service: Maintenance	Subject: carriageway defects Classification: fault reports
	on=Around 4cm deep,Bad pothole where I heard my wheel trim crash in the hole. A cyclist will be thrown from bike if they hit this.
Location: Just before the ro	bundabout on left side near kerb Contact:
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For further history see USRN 8900500 Feature Type: PR1 Road
Job Number: 2378792	Defect Number: 3853440
Enquiry No.: 2944757	Logged by: CRM Connector on: 13/10/2024 19:18
Service: Maintenance	Subject: carriageway defects Classification: fault reports
Desc.: Customer Selecti	on=Deeper than 5cm,Deep pot hole
Location: Deep pot hole	Contact:
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For further history see USRN 8900500 Feature Type: PR1 Road
Job Number: 2378792	Defect Number: 3853440
Enquiry No.: 2940834	Logged by: CRM Connector on: 17/09/2024 21:34
Service: Maintenance	Subject: carriageway defects Classification: fault reports
Desc.: Customer Selecti it, scraping the bo	on=Deeper than 5cm,Pothole has caused significant damage to my car due to the depth. Has scraped paintwork. Depth on the left hand side is deeper and causes cars to sink into ottom and sides.
	after the exit of the retail park or as you're driving past it. Pothole <b>Contact:</b> ficant damage to my car due to the depth. Has scraped paintwork.
Enquiry No.: 2939482	Logged by: CRM Connector on: 08/09/2024 20:06
Service: Maintenance	Subject: carriageway defects Classification: fault reports
	on=Deeper than 5cm, It is deep enough to cause cars to have to swerve to avoid meaning cars on the right lane do not expect a last minute swerve and can cause a collision. It is
Location: The pothole is in	the left lane before they merge. It is located by the traffic lights Contact: n is where Leisure world cars come out to turn right.
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For further history see USRN 8900500 Feature Type: PR1 Road
Job Number: 2375481	Defect Number: 3836540
Enquiry No.: 2932701	Logged by: CRM Connector on: 24/07/2024 14:23
Service: Maintenance	Subject: carriageway defects Classification: fault reports
	on=Deeper than 5cm,RM CALLER STATES: Large crack in road, caller has fallen with pram. Injury caused / damage caused.
Location: **150** **INSUR/	ANCE CLAIM** O/S 326 Cowdray Avenue, Colchester Contact:

Display Action Officer: No

Customer Services			
Enquiry No.: 2930956 Service: Maintenance Desc.: Created from Defe	Logged by: CRM Connector Subject: carriageway defects	on: 15/07/2024 1 Classification: fault reports	2:57
	rage, LON: 0.90938 LAT: 51.89777	Contact:	
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For Defect Number: 3777285	further history see USRN 8900500	Feature Type: PR1 Road
Enquiry No.: 2930953 Service: Maintenance Desc.: Created from Defe		on: 15/07/2024 1 Classification: fault reports	2:54
	rage, LON: 0.90938 LAT: 51.89777	Contact:	
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For Defect Number: 3777285	further history see USRN 8900500	Feature Type: PR1 Road
	Logged by: CRM Connector Subject: carriageway defects n=Deeper than 5cm,this is just past the fire station on t fficult to avoid will cause car damage	on: 16/06/2024 1 Classification: fault reports that side of the road ie same side as Contact:	
danger to cyclists.	Logged by: CRM Connector Subject: carriageway defects n=Deeper than 5cm,Deep pothole on the service road	2 .	6:22
Location: At the exit of colne		Contact:	
sharp edges for ve Location: **150**surface aro	Logged by: CRM Connector Subject: carriageway defects n=Surface around a cover,Caller states areas around r hicles. Exposed metal fins from cover sticking out by 7 und the manhole covers on approx 5 covers on cowdra ed in between sports centre and colne view retail centre	cm, and approx 20 cm gap around e ay avenue <b>Contact:</b>	service covers) breaking away leaving exposed metal, tarmac crumbling away leaving
Plot Number: 1,000.00 Job Number: 2375493	Feature Id - Location: 8900501_1000 - A133 // For Defect Number: 3836596		Feature Type: PR1 Road
Cowdray Avenue.			9:06 is, is getting bigger, impossible to avoid when turning right from Mason Road onto
	side of Cowdray Avenue, across the turning for Mason		0.40
through. Subsurfac	Logged by: CRM Connector Subject: carriageway defects n=Around 4cm deep,(SC) caller states large pothole at the has come away. / from the roundabout, on the left hand side over the ra		9:48 <i>r</i> ide, about 4 inches deep but feels is a danger as held up an ambulance trying to get
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For Defect Number: 3776875	further history see USRN 8900500	Feature Type: PR1 Road

Display Action Officer: No

Enquiry No.: 2917540	Logged by: CRM Connector on: 08/05/2024 09:35
Service: Maintenance	Subject: carriageway defects Classification: fault reports
Desc.: Customer Select	tion=Deeper than 5cm,Large pothole, several feet long and very deep. Real danger to cyclists and motorists.
	und, at the end of the concrete barrier at the side of the road. Just <b>Contact:</b> bends to the right and goes downhill.
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For further history see USRN 8900500 Feature Type: PR1 Road Defect Number: 3776875
Enquiry No.: 2916802	Logged by: CRM Connector on: 04/05/2024 04:43
Service: Maintenance	Subject: carriageway defects Classification: fault reports
	y Ave: Pothole on left side just after where road goes two lanes into one,London bound direction.
Location:	Contact:
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For further history see USRN 8900500 Feature Type: PR1 Road
Job Number: 2375432	Defect Number: 3836087
Enquiry No.: 2916801	Logged by: CRM Connector on: 04/05/2024 04:43
Service: Maintenance	Subject: carriageway defects Classification: fault reports
Desc.: Large deep ruts:	Large deep ruts on Cowdray Ave,London bound direction,where road goes into two lanes
Location:	Contact:
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For further history see USRN 8900500 Feature Type: PR1 Road Defect Number: 3836583
Enquiry No.: 2916755	Logged by: Redacted on: 03/05/2024 17:27
Service: Maintenance	Subject: carriageway defects Classification: fault reports
even made safe.	
Location: Near to the roun	dabout that meets St Andrews Avenue/Ipswich Road. Contact:
Plot Number: 1,000.00 Job Number: 2367108	Feature Id - Location: 8900501_1000 - A133 // For further history see USRN 8900500 Feature Type: PR1 Road Defect Number: 3791984
Enquiry No.: 2916680	Logged by: CRM Connector on: 03/05/2024 14:10
Service: Maintenance	Subject: carriageway defects Classification: fault reports
Better location d	
the manhole cov	e roundabout that meets St Andrews Avenue/Ipswich Road. Where <b>Contact:</b> rer was filled in last night on 2916522. The pothole is as you enter e from the roundabout heading west about 5/10 metres from
Enquiry No.: 2916522	Logged by: CRM Connector on: 02/05/2024 16:29
Service: Maintenance	Subject: carriageway defects Classification: fault reports
Desc.: Customer Select Location: **150**Cowdray	tion=Surface around a cover,Caller States: The manhole cover is deteriorating , It's about 10cm deep and the whole surface is broken up with sharp edges . SJ Avenue . SJ Contact:

Display Action Officer: No

Enguiry No.: 2911648	Logged by: CRM Connector	<b>on:</b> 05/04/2024 17:48	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
	tion=Deeper than 5cm,medium sized pothole		
Location: Junction of maso		Contact:	
Turning left out o	of mason road.		
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For Defect Number: 3836147	iurther history see USRN 8900500 Feature	e Type: PR1 Road
Enquiry No.: 2908636	Logged by: CRM Connector	on: 20/03/2024 04:45	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: New Deep Potho	ble: Deep pothole/crack in lane 1 at traffic lights for Leisu	e World,London bound direction	
Location:		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For	further history see USRN 8900500 Feature	e Type: PR1 Road
Enquiry No.: 2906237	Logged by: CRM Connector	on: 09/03/2024 10:59	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
	tion=Around 4cm deep,Vertical rectangle pothole is deep		provide photos due to peak traffic times.
traffic lights befo Cowdray Avenue	e, Colchester, Essex, left hand side pot hole, at junction/p re joining roundabout near Albert Pub/ Premier Inn Colch e. Driving towards Colchester Town Center, from The Rai Idi off Cowdray Avenue.	iester,	
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For	further history see USRN 8900500 Feature	e Type: PR1 Road
Job Number: 2378792	Defect Number: 3853440		
Enquiry No.: 2905113	Logged by: CRM Connector	on: 05/03/2024 08:02	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Customer Select	tion=Deeper than 5cm,the pothole is around 50cm Squar	e on the outside line and without swerving, ca	rs will go into it.
I went through th	is at around 07:00 on the 5th of march and have now go	t a cracked alloy and has caused alot of disrur	ntion
	ht hand lane there is a big pothole	Contact:	
Enquiry No.: 2904268	Logged by: CRM Connector	on: 01/03/2024 12:21	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
	tion=Deeper than 5cm,JLR caller states - Pothole approx		mage - already marked as defect on map
	CLAIM** - Opposite Albert PH - adjacent to zig zag marki		
Plot Number: 1,000.00 Job Number: 2363790	Feature Id - Location: 8900501_1000 - A133 // For Defect Number: 3780538	iurther history see USRN 8900500 Feature	e Type: PR1 Road
Enquiry No.: 2902686	Logged by: CRM Connector	on: 24/02/2024 20:11	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
	tion=Deeper than 5cm, This pothole has been there for ap		
Location: This pothole is n	ot easily recognised at night and difficult to avoid at busy	times. Contact:	
It is a danger to	cars and cyclists alike		
Plot Number: 1,000.00	Feature Id - Location: 8900501_1000 - A133 // For	further history see USRN 8900500 Feature	e Type: PR1 Road

25/11/	/2024
--------	-------

Effe	ective: 21/11/2021 to 21/11/2024	Asset Number: 1000.00 to 1000.00		
Se	ervice: Maintenance	Subject: carriageway defects (CWDF)		
Display Action C	Officer: No	Site: COWDRAY AVENUE (8900501)		
Customer Serv	ices			
Enquiry No.: 290	Logged by: CRM Connector	on: 22/02/2024 11:40		
Service: Mai	intenance Subject: carriageway defects	Classification: fault reports		
Desc.: Cus	stomer Selection=Deeper than 5cm,Unsafe to stop as this is a major car	rriageway but estimate pothole is at least 20cm Wide and 30cm long - estimated depth 10 cm		
You	HAVE to swerve to avoid the pothole which is a road safety risk			
	It large and deep pothole that people have to swerve around to avoid hi	itting it Contact:		
Plot Number: 1,00	00.00 Feature Id - Location: 8900501_1000 - A133 // For fu	In ther history see USRN 8900500 Feature Type: PR1 Road		
Job Number: 236	<b>Defect Number:</b> 3780538			
Enquiry No.: 290	1951 Logged by: CRM Connector	on: 22/02/2024 04:42		
Service: Mai		Classification: fault reports		
Desc.: 18 i con	inch pothole on west bound side opposite the Albert pub near to the peo sequently it is getting worse daily. Some vehicles have had to swerve in	destrian crossing: The pothole is in an awkward position on the kerb side and is difficult to avoid for large vehicles, nto the right hand lane approaching the pedestrian crossing to miss the pothole.		
Location:		Contact:		
Enquiry No.: 290	1057 Logged by: CRM Connector	on: 18/02/2024 17:15		
Service: Mai	intenance Subject: carriageway defects	Classification: fault reports Enquiry Ref: M23TP002366		
	stomer Selection=Deeper than 5cm,Large pothole directly in normal path			
	SURANCE CLAIM - Approx. Lon 0.91302 Lat 51.89694, adjacent to 130y ming sign for traffic lights on left and exit from local road on right.	yd Contact:		
Plot Number: 1,00	00.00 Feature Id - Location: 8900501_1000 - A133 // For fu Defect Number: 3780515	Irther history see USRN 8900500 Feature Type: PR1 Road		
Enquiry No.: 289	9263 Logged by: CRM Connector	on: 10/02/2024 20:43		
Service: Mai		Classification: fault reports		
	stomer Selection=Deeper than 5cm,deep pothole - maybe 1 foot deep			
Location: at the	he exit of colne view retail park as it turns left into the service road	Contact:		
Enquiry No.: 289	18933 Logged by: CRM Connector	on: 09/02/2024 10:29		
Service: Mai		Classification: fault reports		
Desc.: Cus		affic light where drivers on the left lane are having to drive towards the right side of the left lane to avoid the bad road,		
Location: On	the left side of the left lane by the traffic light.	Contact:		
Enquiry No.: 289	18910 Logged by: CRM Connector	on: 09/02/2024 09:56		
Service: Mai		Classification: fault reports		
		a few yards before the traffic lights as you come to the Albert pub/restaurant roundabout		
Location: IT'S	AT THE END OF COWDRAY AVENUE JUST BEFORE THE LIGHTS HER SIDE OF THE ALBERT BEEFEATER PUB/RESTAURANT			
Plot Number: 1,00	00.00 Feature Id - Location: 8900501_1000 - A133 // For fu	In ther history see USRN 8900500 Feature Type: PR1 Road		
Job Number: 236				
Enquiry No.: 289	10688 Logged by: CRM Connector	on: 08/01/2024 21:00		
Service: Mai		Classification: fault reports		
		anging from 40 to 60 mm deep. Located in the middle of the westbound side of the main road.		
Location: App	proximately in line with number 272, on the westbound side of Cowdray , the service road)			

Service: Maintenan Display Action Officer: No	l to 21/11/2024 ce	Asset Number: 1000.00 to 1000.00 Subject: carriageway defects Site: COWDRAY AVENU	s (CWDF)
ustomer Services			
Enquiry No.: 2887734 Service: Maintenance Desc.: Customer Selection=/ Location: westbound lane at pe	Logged by: CRM Connector Subject: carriageway defects Around 4cm deep,small deep pothole destrian lights outside albert pub	on: 01/01/2024 16:05 Classification: fault reports Contact:	
Enquiry No.: 2887733 Service: Maintenance	Logged by: CRM Connector Subject: carriageway defects Around 4cm deep,pothole in middle of junction	on: 01/01/2024 16:01 Classification: fault reports Contact:	
slightly on a bend and	I the speed limit is 40MPH me onto cowdray avenue from Ipswich road rounda	on: 13/12/2023 21:04 Classification: fault reports If you want to miss it you have to drive into the oncoming traf pout slightly Contact:	ffic lane. Which is deemed unsafe and dangerous as it's
slightly on a bend and	I the speed limit is 40MPH me onto cowdray avenue from Ipswich road rounda	on: 13/12/2023 21:04 Classification: fault reports If you want to miss it you have to drive into the oncoming traf pout slightly Contact:	ffic lane. Which is deemed unsafe and dangerous as it's
lane and potentially in		on: 07/11/2023 11:23 Classification: fault reports ou don't want to hit it so you either have to risk going to the left fter about 1-2 weeks and is then left for months. It surely can n the Contact:	
clearly many people n Location: INSURANCE CLAIM carriageway heading any other in the vicinit		so than ues on this	Enquiry Ref: M23TP001119 around the bottom. I have not noticed this before, however

Effective: 21/11/2021 Service: Maintenand Display Action Officer: No		
Customer Services		
	Logged by: CRM Connector       on: 24/09/2023 04:42         Subject: carriageway defects       Classification: fault reports         ay floods Cowdray Avenue: For years, the road has flooded badly every time there is moderate rain and remains flooded for some time after to the extent of covering a several inches of water.	) an 8 fo
There is a kind of perfo	prated kerb along the southern edge of the carriageway that should provide good drainage, but appears to be blocked.	
	r may not) connect to the ditch running to the Colne which is adjacent to the public footpath - the ditch seems relatively clear but the outlet from the drain (?) has a lot sts the drain run may well be partially obstructed.	ot of
	that the drains were designed in a way that does not work, but I don't think our civil engineers are incompetent so I'm assuming the drain is connected and that it runs owever, if the basic maintenance is missed, then the drains could easily block. What is the problem please? Contact:	ns on a
Plot Number: 1,000.00 Fe	eature Id - Location: 8900501_1000 - A133 // For further history see USRN 8900500 Feature Type: PR1 Road Defect Number: 3777255	
	Logged by: CRM Connector       on: 23/05/2023 16:05         Subject: carriageway defects       Classification: fault reports         ubsidence, The hole on the inside of the roundabout and if there is traffic in the inside line it is impossible to miss the deep hole which is likely to cause damage to a very water drain has broken up leaving a large hole.       Contact:	vehicle
•	Logged by:       Redacted       on: 24/04/2023 16:51         Subject:       carriageway defects       Classification: fault reports         g defects have deteriorated at this location       Constant:       Constant:	
Location: **MEMBER ENQUIRIE	ES** cycle lane o/s 22-28 Contact: Logged by: CRM Connector on: 12/04/2023 18:19	
Location: There are several pot h	Subject: carriageway defects       Classification: fault reports         eeper than 5cm, Several potholes plus around manhole cover       Classification: fault reports         noles as you approach cowdray retail park heading towards       Contact:         nd a manhole road is breaking up       Contact:	
Enquiry No.: 2830809	Logged by: CRM Connector on: 15/03/2023 21:33	
Location: Along this road are mo With good materials th	Subject: carriageway defects       Classification: fault reports         oor reinstatements,Deep holes can cause damage to the cars I drive looking for the potholes as they could ruin my car         re than one pothole they need to be fixed properly       Contact:         e Roman built roads many years ago and are still good today.         een filled in and a few months later need attention around the over the lights	
Enquiry No.: 2827842	Logged by: CRM Connector on: 05/03/2023 18:40	
my phone and am hap	Subject: carriageway defects Classification: fault reports eeper than 5cm,i do not know exactly how long it has been there, you can see veins coming from the hole which would indicate it is spreading. i have a very good pho py to email to you but not sure how to add to this message.	hoto on
first set of lights there i think is reference 2776	bad roundabout, heading towards leisure world, before thehow <b>Contact:</b> is a layby, just close to the layby there is a drain cover which i is884, the hole is towards the right of lane close to the drain, it is entry sign, near the BT depot	

Customer Services			
to shake, but all th	he houses 3-4 along on either side. I've decided to repo	on: 03/03/2023 21:44 Classification: fault reports othole has emerged and is enlarging as the days of rt it now as it is becoming unbearable, waking my	go by. When large vehicles hit the pothole it's causes not only my house neighbours and I in the night as lorries strike it, and without sounded too
	cident waiting to happen. d carriage way outside number 33 Cowdray Avenue	Contact:	
Plot Number: 1,000.00 Job Number: 2344269	Feature Id - Location: 8900501_1000 - A133 // For Defect Number: 3692423	further history see USRN 8900500 Feature Typ	pe: PR1 Road
	Logged by: CRM Connector Subject: carriageway defects on=Deeper than 5cm,CALLER STATES (RH): Large po ation, on the leane heading towards the North Station ro		d, damaged callers car.
tyre.	Logged by: CRM Connector Subject: carriageway defects GE due to pothole. Customer Selection=Deeper than 5c IM. Outside 33 cowdray Avenue colchester on a carria		Enquiry Ref: M22TP001245 been very badly filled in with tarmac but reporting this as it popped my
Plot Number: 1,000.00 Job Number: 2341423	Feature Id - Location: 8900501_1000 - A133 // For Defect Number: 3680873	further history see USRN 8900500 Feature Typ	pe: PR1 Road
Enquiry No.: 2817960 Service: Maintenance Desc.: Customer Selectic	Logged by: CRM Connector Subject: carriageway defects on=Deeper than 5cm,Deep	on: 18/01/2023 22:16 Classification: fault reports	
Location: On left travelling to		Contact:	
Enquiry No.: 2816160 Service: Maintenance Desc.: Customer Selection	Logged by: CRM Connector Subject: carriageway defects on=Deeper than 5cm,Deep urgent pot hole you must plo	on: 14/01/2023 13:36 Classification: fault reports ease fill!	
Location: Deep urgent pot h	ole you must please fill!	Contact:	
Enquiry No.: 2811898 Service: Maintenance Desc.: Deep pothole.: On larger deep pothol		on: 31/12/2022 04:42 Classification: fault reports Station Rd from the direction of the fire station in I	ane 1 to the near side approximately 20 metres from the roundabout is a
Location:		Contact:	
Enquiry No.: 2811862 Service: Maintenance Desc.: Customer Selectic	Logged by: CRM Connector Subject: carriageway defects on=Deeper than 5cm,Fucking big	on: 30/12/2022 19:52 Classification: fault reports	
	e fire station going towards the town	Contact:	
Location: Cannot tell you wh	Logged by: CRM Connector Subject: carriageway defects on=Around 4cm deep,Quite deep and difficult to avoid a nich house but opposite the Albert beefeater about 200 ot much worse in the last few days		

Site History Report

Asset Number: 1000.00 to 1000.00

Subject: carriageway defects (CWDF)

Site: COWDRAY AVENUE (8900501)

Effective: 21/11/2021 to 21/11/2024 Service: Maintenance

Display Action Officer: No

Effective: 21/11/2021 to 21/11/202 Service: Maintenance	4	Asset Number: 1000.00 to 1000.00 Subject: carriageway defects (CWDF)	
Display Action Officer: No		Site: COWDRAY AVENUE (8900501)	
Customer Services			
Service: Maintenance Desc.: Customer Selection=Deeper than 5	cm, New deep pot holes appearing - repaired previously	on: 27/12/2022 16:45 ation: fault reports y - tarmac has now popped out! Needs urgent repairs please. ntact:	
Service: Maintenance Desc.: Customer Selection=Deeper than 5	cm, New deep pot holes appearing - repaired previously	on: 27/12/2022 16:44 ation: fault reports y - tarmac has now popped out! Needs urgent repairs please. ntact:	
Service: Maintenance	rom the road works (which have been in place for month	on: 07/11/2022 17:29 ation: fault reports hs) are piled up in the middle of the road. ntact:	
Service: Maintenance Desc.: Title=Surface around a cover,As ab Location: It's when you are near the newish h Donald's. I drove along the road an manhole of some sort in the actual to lift up at an angle. If you hit that i	pove not sure exact spot you would have to go slow and	on: 05/11/2022 20:55 ation: fault reports I look or walk the side walk to see it just concerned. ntact:	
Service: Maintenance	has been spilt over the road covering one whole lane an	on: 20/07/2022 15:29 ation: fault reports and is about 15-20m long ntact:	
Service: Maintenance	ave been here for months and now getting pushed to the	on: 19/07/2022 16:10 ation: fault reports e side and driven over ntact:	
Service: Maintenance Desc.: Title=Cracking,Potholes, cracks an	d traffic calming measures for motor vehicles make this	on: 13/06/2022 11:48 ation: fault reports s stretch of road incredibly uncomfortable, sometimes unsafe and overall wholly unsuitable for cyclists. sue of the traffic calming bumps (which should definitely remain in place to keep motor vehicle speeds low	ow,
There is a wide grass verge along t been done on the other stretches o	f Cowdray Avenue. Not only would this create a more of venue side road, but particularly where the cycle <b>Com</b>	build be better to widen the path and convert it to a shared footpath/cycle lane with a dividing line, as has comfortable ride for cyclists, it would reduce conflict between cyclists and cars on this stretch of road.	3

Enquiry No.: 2776884	Logged by: CRM Connector	on: 13/05/2022 04:42
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
-	ght my front tyre on my car now burst it due to	
Location:		Contact:
Enquiry No.: 2759718	Logged by: CRM Connector	on: 28/01/2022 08:31
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
	" pothole where whole surface ( concrete"is fa	
Location: O/s 270A on concrete "second to main highway	dary" road running directly in front of houses 8	& parallel Contact:
Enquiry No.: 2759379	Logged by: CRM Connector	<b>on:</b> 26/01/2022 09:45
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
	x 1.5 m long concrete paving breaking up and	•
Location: Access road outside retail park	Cowdary Avenue - Colchester	Contact:
Enquiry No.: 2757765	Logged by: CRM Connector	<b>on:</b> 16/01/2022 16:54
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
	rface is broken to the extent that at the edge i	
	the entrance to Lookers and the exit from the	e retail Contact:
park.		
Enquiry No.: 2754432	Logged by: CRM Connector	on: 19/12/2021 00:24
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
		ppy. It is not my concern or problem that specific pothole was not as serious as other issues. The issue was that due to for 2 hours and 40 minutes and I had to replace a blown tyre. This cost me in total (£125). I have been informed by an MP
		and therefore I want to take this further rather than everyone's complaints just being fobbed off. Thank you. Please can you
	reply to rather than an email address that is	
	eply that you dodged by saying that I couldn't	
the email that you emailed me here. REF NO: 2752943	from. Giving me option other than sending it	t though
Enquiry No.: 2752943	Logged by: CRM Connector	on: 07/12/2021 00:15
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
	e roughly 70/80mm deep. Causing damage to the majestic. Left lane if the dual lanes. On the	
December I bit this pothole the	at has clearly been there for some time. It made	e 3rd of Contact:
	I had to miss a day at work whilst sitting in my	
	reakdown company for 2 and a half hours. It a	
	nd left a bulge and a slow puncture in it. Due t	
	vn and want to take this further. Thank you. Th	
	ut and I have a receipt for my tyre that I had to	
Enquiry No.: 2752629	Logged by: CRM Connector	on: 03/12/2021 15:29
Service: Maintenance	Subject: carriageway defects	Classification: fault reports
	Aller states there is a pothole at this location t a week ago and burst a car tyre	that is approx 40CM round and unsure of how deep as they hit it in the dark. the caller is unsure of how long its been like
Location: **INSURANCE CLAIM** near		Contact:

# 25/11/2024

Display Action Officer: No

**Customer Services** 

Effective: 21/11/2021 to 21/11/2024

Service: Maintenance

**Site History Report** 

Asset Number: 1000.00 to 1000.00

Subject: carriageway defects (CWDF)

Site: COWDRAY AVENUE (8900501)

	Effective: 21/11/2021 to :	21/11/2024		nber: 1000.00 to 1000.00			
	Service: Maintenance Subject: carriageway defects (CWDF)						
Display Action	on Officer: No			Site: COWDRAY AVENUE (890	0501)		
Customer S	ervices						
Enquiry No.:		Logged by: CRM Connector	<b>on:</b> 03/12/2021				
	Maintenance	Subject: carriageway defects	Classification: fault reports				
		rge pothole, not aware of how long it's been there		often. I hit the pothole around 10.2	25pm, it was not o	clear to see in the	dark
Location:	Cowdray Avenue, already	reported as defect number 3607824	Contact:				
Enquiry No.:		Logged by: CRM Connector	on: 30/11/2021				
	Maintenance	Subject: carriageway defects	Classification: fault reports				
Desc.:	Title=Deeper than 5cm,la	ge pot hole in the centre of the 2 lanes going towa	rds the Albert put and premier in	in hotel.			
Location:	shown in the picture this of This had incurred fees for in between 2 lanes A133 l cowdray avenue, before y	le following a lorry, as i done this i hit the hole which aused a hole in my tyre. I have today had to have a new tyre (I have the invoice but unfortunately it to neading towards colne bank avenue Colchester on ou get to the hotel on the right side of the road.	a new tyre put on. wont let me attach to this email.		y had a full new s	set for around 2mo	nths) to pop as
	Roughly, 51°53'50.7"N 0°						
Enquiry No.:		Logged by: CRM Connector	on: 27/11/2021				
	Maintenance	Subject: carriageway defects	Classification: fault reports				
Desc.:	cyclists.	is very deep and hard to avoid. I have gone over the	his pothole several times now ar	id it is in a dangerous spot and co	buid damage som	leones wheel or po	se a real nazard to
		rgently as it has been there several weeks. Unfortu	unately your site is telling me that	t if it is dangerous then it can only	v be reported by	telephone but only	in office hours.
		able system, so I am going to report it here too.			,	,	
Location:		Albert roundabout on Cowdray avenue, colcheste	er, on the Contact:				
		h station road. It is very deep and hard to avoid. I h					
		veral times now and it is in a dangerous spot and c	ould				
	damage someones wheel	or pose a real hazard to cyclists. rgently as it has been there several weeks. Unfortu	motoly.				
	your site is telling me that	if it is dangerous then it can only be reported by te	lenhone				
	but only in office hours, w	hich is clearly not a suitable system, so I am going	to				
	report it here too	, , , , , , ,					
Enquiry No.:	2750877	Logged by: CRM Connector	on: 21/11/2021	20:33			
• •	Maintenance	Subject: carriageway defects	Classification: fault reports				
Desc.:	Title=Around 4cm deep,P	othole in westbound Lane 1 offside wheel track					
Location:	Near the Albert Pub (appr	ox 100m to the east)	Contact:				
Maintenanc	e Management						
Job No. Des	cription	Location	Priority	Job Status	Entered	Completion	Works Order
Ass	et: 1,000.00	Asset - Locn.: 8900501_1000 - A133 // For furthe	r history see USRN 8900500	Feature Type: PR1 Road		Area: Colchester	
2211360 Grou	und Investigation bore hole	s A133 Cowdray Ave junction with	HW: Capital Sch		22/07/2016	04/08/2016 Est.	EH/1558108
2221366 Che	ck harras fencing and	Ipswich Road Roundabout Cowdray Avenue Bridge	HW/- P4 2008 ST	RATEGY works completed	16/01/2017	07/02/2023 Act.	EH/1564924
	bags.		1100.1 4 2000 01		10/01/2017	01,02,2020 Adi.	

HW: Capital Scheme

HW: S Follow up

Works Order

Effective: 21/11/2021 to 21/11/2024 Service: Maintenance

Display Action Officer: No

Maintenance Management

Asset Number: 1000.00 to 1000.00 Subject: carriageway defects (CWDF) Site: COWDRAY AVENUE (8900501)

Job Status

job committed

job raised

works completed

Feature Type: PR1 Road

Entered

Completion

22/10/2019 01/11/2019 Est.

Area: Colchester

07/02/2018 30/03/2018 Est. EH/1582017

25/02/2021 20/01/2023 Act. EH/1634252

Job No.	Description		Location		Priority
	Asset:	1,000.00	sset - Locn.: 8900501_1000 - A1	133 // For further history see L	JSRN 8900500
	View retail p turning HGV dropped ped	erb line for Colne ark to deflect the le S, 2) Reconstruct lestrian crossing wit g, 3) Relocate traffic	·		HW: Capital Sc
2287371		vey works on enue Service Road	Cowdray Avenue Service Road, Colchester (In front of Aldi supe market)		HW: Street S4
2312620	S follow up - 100mm - 18	c/way patching .6m2	os 25 - on inside lane by LC 73		HW: S Follow u

2319719 Installation of new 670-30 and	Cowdray Ave Service Road j
833 signs back-to-back with new	A133 Cowdray Ave.
835 sign on new post on	

655 Signs back-to-back with new	A 133 Cowuray Ave.
835 sign on new post on	

existing, includes excavation and removal of previously existing post base and concrete foundation. Replacement of 557-3 sign sub plates with new plates on northwestern verge, and replacement of 670-30 sign

833 signs back-to-back with new	A133 Cowdray Ave.
835 sign on new post on	
opposite verge (eastern) to those	

319719 Installation of new 670-30 and	Cowdray Ave Service Road j/w
833 signs back-to-back with new	A133 Cowdray Ave.
835 sign on new post on	

y Ave Service Road j/w owdray Ave.	HW: Street S4	works completed	06/08/2021 10/01/2022 Act. EH/1640791

with new sign on southwestern								
verge.								
2324313 RA16=4x4 0.9m x 0.5m x	Opp 10	HW: Street S1	works completed	03/12/2021	03/12/2021	Act.	EH/1639978	
100mm CWPH (HW:								
carriageway defect)								
2326453 RA16=4×4, pedestrian safety	On railway bridge	HW: Street S1	works completed	31/01/2022	31/01/2022	Act.	EH/1641707	
guard rail x4 sections, fallen and								
blocking fw, approx. 40m in								
length, 3m in height. Remaining								
sections leaning due to high								
winds. (HW: ped guardrail								
damaged)								
2327731 Ra1=1×1, faded directional arrow	O/s McDonald's, before lights by	HW: Street S4	works completed	25/02/2022	23/02/2022	Act.	EH/1642900	
on cway, aprox 50% (HM/; worn	leisure centre							

on cway, aprox 50% (HW: worn or missing road mark)	leisure centre			
2329113 Ransa gang sent to clear debris following RTC (HW:	Cowdray avenue junction with Mason road	HW: Street S1	works completed	25/03/2022 25/03/2022 Act. EH/1644005
debris/deposit on highway) 2331657 RA12=3x4, temporary diversion sign with circle requires realignment on a frame. (HW: Traffic Management)	On bridge along Cowdrey avenue heading east, 50m from Ipswich road roundabout	HW: Street S2 PR1/2	works completed	31/05/2022 31/05/2022 Act. EH/1646163

Display Action Officer: No

#### Asset Number: 1000.00 to 1000.00 Subject: carriageway defects (CWDF) Site: COWDRAY AVENUE (8900501)

Maintenance Management

ob No.	Description		Location	Priority	Job Status	Entered	Completion	Works Order
	Asset:	1,000.00 A	sset - Locn.: 8900501_1000 - A133 // For further history see	USRN 8900500 Feature	Type: PR1 Road		Area: Colchester	
	debris follow	called to clear up ing rtc (HW: sit on highway)	Outside fire station	HW: Street S1	works completed	17/07/2022	18/07/2022 Act.	EH/1647521
	carriageway DP27111230	oil and debris from following RTC 0 (HW: sit on highway)	Outside Leisure World	HW: Street S1	works completed	27/11/2022	27/11/2022 Act.	EH/1651969
2340079		cwph, 1m x 0.6m x M (HW: carriageway	Outside 10	HW: Street S2 PR1/2	works completed	16/12/2022	20/12/2022 Act.	EH/1652709
		e safe pothole in DP29122115 (HW: defect)	Between Fire Station and The Albert RAB	HW: Street S1	works completed	29/12/2022	29/12/2022 Act.	EH/1652996
		cwph, approx. 1.2m m, NSMM (HW:	Орр 10 к	HW: Street S2 PR1/2			19/01/2023 Act.	
	covered FW	0m x 1.8m ice needs salting /: debris/deposit on	Riverside leasure	HW: Street S1	works completed	19/01/2023	19/01/2023 Act.	EH/1653915
2343519	Renew 1No	TMP bollard	Outside 324, Lon 0.91433 Lat 51.89612	HW: Street S3	works completed	22/02/2023	21/02/2023 Act.	EH/1655549
		(HW: debris/deposit	e Near calibre car sales	HW: Street S1	works completed	28/02/2023	28/02/2023 Act.	EH/1655674
2344104	2023/24 Cyc	leway Scheme	Premier Inn - 42 and near to Tenpin Bowling	HW: Capital Scheme	works completed	08/03/2023	30/05/2023 Act.	EH/1663381
		wph, approx. 0.5m x n NSMM (HW: defect)	O/s 33	HW: Street S2 PR1/2	works completed	10/03/2023	14/03/2023 Act.	EH/1656149
2345793	CW patching	g to 100mm 6.12m2	Opp 10	HW: S Follow up	works completed	05/04/2023	12/05/2023 Act.	EH/1658679
	following an	g sent to clear oil RTC (HW: sit on highway)	Near fire station	HW: Street S1	works completed	03/05/2023	03/05/2023 Act.	EH/1658972
		cwph, 0.8m x 0.6m x M (HW: carriageway	CO/s 296, at start of bus stop bay	HW: Street S2 PR1/2	works completed	01/11/2023	02/11/2023 Act.	EH/1665985
	SWAS Work	ding in vicinity of	Cowdray Avenue Colcheser	HW: Capital Scheme	works completed	04/03/2024	20/09/2024 Act.	
2363790			Opposite Beefeater, Lon 0.89644 Lat 51.89736, near traffic light jw The Albert RAB	HW: Street S2 PR1/2	works completed	05/03/2024	07/03/2024 Act.	EH/1672133

Display Action Officer: No

Asset Number: 1000.00 to 1000.00 Subject: carriageway defects (CWDF) Site: COWDRAY AVENUE (8900501)

Maintenance Management

Job No.	Descriptio	n	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset:	1,000.00	Asset - Locn.: 8900501_1000 - A133 // For fur	her history see USRN 8900500 Feature	re Type: PR1 Road		Area: Colchester	
2364302	to make sa	13030134 job raised fe missing gully cove ce cover missing)		HW: Street S1	made safe	13/03/2024	13/03/2024 Act.	EH/1672520
2367035	5 RANSA ga	ng sent to make safe cover (HW: surface	COWDRAY AVENUE, COLCHESTER **150**Cowdray Avenue . SJ	HW: Street S1	made safe	02/05/2024	02/05/2024 Act.	EH/1674925
2367108		ng sent to make safe N: carriageway	<ul> <li>COWDRAY AVENUE,</li> <li>COLCHESTER</li> <li>Near to the roundabout that</li> <li>meets St Andrews</li> <li>Avenue/Ipswich Road.</li> </ul>	HW: Street S1	works completed	03/05/2024	03/05/2024 Act.	EH/1674966
2367118		ng sent to make safe y pothole (HW: y defect)	COWDRAY AVENUE, COLCHESTER oppisite RAJ Bakery ,	HW: Street S1	works completed	05/05/2024	05/05/2024 Act.	EH/1674975
2372623	3 Clean sign	and plate	Near entrance to Colne View Retail Park	HW: Street S3	works completed	04/08/2024	15/08/2024 Act.	EH/1679797
2375432	out into phe >2.1mx>0.3	cw eroded, breaking s, approx 3mx>80mm NSMM ageway defect)	Opp The Range, adj remote footway	HW: Street S2 PR1/2	works completed	23/09/2024	24/09/2024 Act.	EH/1681787
2375481		, cwph, 0.8mm x 0mm NSMM (HW: y defect)	; DETAILS: At junction with traffic lights to Sports cente	HW: Street S2 PR1/2	works completed	24/09/2024	26/09/2024 Act.	EH/1681844
2375491	surface cov work, 0.5m	, cwph around water /er exposing iron x 0.5m x 80mm V: carriageway defect	O/s 8 Reed Walk and opposite dfs furniture store t)	HW: Street S2 PR1/2	works completed	24/09/2024	26/09/2024 Act.	EH/1681860
2375492		, cw ph, 0.9m x 0.5m /IM (HW: carriageway	x At jw entrance to Leisure Centre, / westbound	HW: Street S2 PR1/2	works completed	24/09/2024	26/09/2024 Act.	EH/1681860
2375493			Lon 0.90951 Lat 51.89777 junction with Mason Road, Volvo garage	HW: Street S2 PR1/2	made safe	24/09/2024	26/09/2024 Act.	EH/1681860
2378792		4, cwph, 0.9m x nm NSMM (HW: y defect)	LON: 0.8963712, LAT: 51.8973618, opposite The Albert	HW: Street S2 PR1/2	made safe	12/11/2024	14/11/2024 Act.	EH/1684417