

Defect Number	3679368
Description	RA 8=2×4 CW PH 1.5mx0.6mx85mm
Defect Type Name	HW: carriageway defect
Feature Site Code	3901010
Logged Date	10 Jan 2023 11:01
Notes	Imported Defect via Connector
Location	Between Glazenwood Cottage and Perry Green Farm
Supersedes Defect Number	
Documents	

Attachment



Attachment



Attachment



Attachment





Job DescriptionRA 8=2×4 CW PH 1.5mx0.6mx85mm (HW: carriageway defect)

Job LocationBetween Glazenwood Cottage and Perry Green Farm

Documents

Attachment



Job 2340974  
Coordinates: 51.87027, 0.62151  
Taken by WZHALSTEAD4 on 11 Jan 2023 07:46

Attachment



Attachment



Job 2340974  
Coordinates: 51.87029, 0.62148  
Taken by WZHALSTEAD4 on 11 Jan 2023 08:25