

Effective: 16/08/2021 to 27/03/2023
Subject: carriageway defects (CWDF)
Site: HOLLIES ROAD (3901010)

Service: Maintenance
Display Action Officer: No

Site: HOLLIES ROAD (3901010)

Locality: BRADWELL, ESSEX

Area: Bradwell

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00007969 - ZU4431 //	Feature Type: Local Road		Area: Bradwell		
Batch:	6937438 - Ad Hoc Inspection Batch			Route:	adhoc route		Date:	15/02/2023
3687046	CW PH 1.5mx0.6mx85mm	15/02/2023	Between Glazenwood Cottage and Perry Green Farm	HW: carriageway defect	Internal		Action Required	
Batch:	6930170 - Inspection Batch			Route:	adhoc route		Date:	10/01/2023
3679368	RA 8=2x4 CW PH 1.5mx0.6mx85mm	10/01/2023	Between Glazenwood Cottage and Perry Green Farm	HW: carriageway defect	Internal		Committed	2340974
Batch:	6912989 - Inspection Batch			Route:	adhoc route		Date:	24/10/2022
3664637		24/10/2022		HW: Provision of TM	Internal		Committed	2337575
Batch:	6901373 - Ad Hoc Inspection Batch			Route:	adhoc route		Date:	02/09/2022
3654445	CW PH 1.8mx2mx180mm	02/09/2022	Opposite J/W LinkRoad	HW: carriageway defect	Internal		Action Required	
Batch:	6896333 - Inspection Batch			Route:	Area 05 Annual Aug Driven		Date:	15/08/2022
	No actionable defects found							
Batch:	6896316 - Inspection Batch			Route:	adhoc route		Date:	15/08/2022
3649832	RA16 =4x4 CW PH 1.8mx2mx180mm	15/08/2022	Opposite J/W LinkRoad	HW: carriageway defect	Internal		Committed	2334835
Batch:	6895556 - Ad Hoc Inspection Batch			Route:	adhoc route		Date:	11/08/2022
3649208	RANSA - pothole - CW breaking out 6.1m x 0.6m	11/08/2022	Nr Corner Bungalow	HW: carriageway defect	Internal		Committed	2334685
Batch:	6895554 - Ad Hoc Inspection Batch			Route:	adhoc route		Date:	11/08/2022
3649205	RANSA - edge pothole 3.1 x 0.8m	11/08/2022	Opposite Glazenwood Road	HW: carriageway defect	Internal		Committed	2334685
Batch:	6895553 - Ad Hoc Inspection Batch			Route:	adhoc route		Date:	11/08/2022
3649204	RANSA - edge pothole 3.1 x 0.8m	11/08/2022	Opposite Glazenwood Road	HW: carriageway defect	Internal		Committed	2334685
Batch:	6850268 - Inspection Batch			Route:	adhoc route		Date:	19/01/2022
3615635	RA4=1x4 CW PH 0.9mx0.6Mx55mm	19/01/2022	O /S The Nook	HW: carriageway defect	Internal		Committed	2334685
Batch:	6839601 - Inspection Batch			Route:	adhoc route		Date:	15/11/2021
3609139	RA4=1x4 CW PH 0.9mx0.45Mx50mm	15/11/2021	O /S The Nook	HW: carriageway defect	Internal		No Action Required	
Batch:	6834405 - Inspection Batch			Route:	adhoc route		Date:	25/10/2021
3606144	RA 4 = 1 x 4 C'way sunk due to wheel tracking. 3.00M x 2.50M x 60MM	25/10/2021	Adjacent to quarry entrance.	HW: carriageway defect	Internal		Committed	2334685
Batch:	6819434 - Inspection Batch			Route:	Area 05 Annual Aug Driven		Date:	16/08/2021
3597259	RA 8=2x4 CW PH 2.8mx0.7mx90m	16/08/2021	Between The Bungalows and The Nook	HW: carriageway defect	Internal		Committed	2320002
3597258	RA 16=4x4 CW PH 1.3mx1mx170mm	16/08/2021	O/S The Nook	HW: carriageway defect	Internal		Committed	2319993

Effective: 16/08/2021 to 27/03/2023
Subject: carriageway defects (CWDF)
Site: HOLLIES ROAD (3901010)

Service: Maintenance
Display Action Officer: No

Customer Services

Enquiry No.: 2806574	Logged by: CRM Connector	on: 24/11/2022 10:39	Enquiry Ref: M22TP000730
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Customer Selection=Around 4cm deep,Pothole in the driving line which is about 600mm wide and 4" deep and 1m long			
Location: Hollies Road near the passing spot		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 00007969 - ZU4431 //		Feature Type: Local Road
Job Number: 2340974	Defect Number: 3679368		
Enquiry No.: 2789355	Logged by: CRM Connector	on: 04/08/2022 16:18	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Title=Deeper than 5cm,JLR caller states 30 cms deep at deepest x 1 metre x 1 metre across			
Location: At the T junction where Links and Hillies Road meet at edge of carriageway		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 00007969 - ZU4431 //		Feature Type: Local Road
Job Number: 2334835	Defect Number: 3649832		
Enquiry No.: 2757305	Logged by: CRM Connector	on: 13/01/2022 10:41	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Title=Deeper than 5cm,RM CALLER STAES: Large pot hole in line with wheels.			
Location: Hollies Road, Away form A120, 200-300 yards.		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 00007969 - ZU4431 //		Feature Type: Local Road
Job Number: 2334685	Defect Number: 3615635		
Enquiry No.: 2748698	Logged by: CRM Connector	on: 07/11/2021 13:07	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Title=Deeper than 5cm,Large pot hole in narrow lane that you cannot avoid going down if a car is coming the other way, it was also obscured by leaves. It broke the suspension on my car.			
Location: About 1/4 of a mile down hollies lane from the A120 Bradwell end		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 00007969 - ZU4431 //		Feature Type: Local Road
Job Number: 2334685	Defect Number: 3615635		
Enquiry No.: 2742664	Logged by: CRM Connector	on: 02/10/2021 15:29	
Service: Maintenance	Subject: carriageway defects	Classification: fault reports	
Desc.: Title=Subsidence,With heavy plant traffic passing the public highway there is substantial dips created in the road causing a danger to motorists and cyclists.			
Location: Hollies Road, Bradwell where the quarry traffic passed the public highway		Contact:	
Plot Number: 1,000.00	Feature Id - Location: 00007969 - ZU4431 //		Feature Type: Local Road
Job Number: 2334685	Defect Number: 3606144		

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1,000.00	Asset - Locn.: 00007969 - ZU4431 //		Feature Type: Local Road		Area: Bradwell	
2286907	Replace fingerpost as per design	J/W Sheepscoate Lane	HW: Street S3	Quality audit passed	14/10/2019	11/10/2021	Act. EH/1636186
2308048	CW patching, repairs to verge.	Various locations.	HW: S Follow up	job raised	25/11/2020		
2319993	RA 16=4x4 CW PH	O/S The Nook	HW: Street S1	works completed	16/08/2021	16/08/2021	Act. EH/1636613
	1.3mx1mx170mm (HW: carriageway defect)						
2320002	Make safe carriageway edge defect with cold lay materials	Between The Bungalows and The Nook	HW: Street S2	works completed	16/08/2021	17/08/2021	Act. EH/1636624
	2.8m x 0.7m x 90mm						

Effective: 16/08/2021 to 27/03/2023
Subject: carriageway defects (CWDF)
Site: HOLLIES ROAD (3901010)

Service: Maintenance
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: 00007969 - ZU4431 //		Feature Type: Local Road		Area: Bradwell	
2334685	MLPP - Patch CW 24.58sqm in 9 number patches - also in Patch No 3 - replace GY C&F with 600mm GY C&F and adjust level.	See schedule	HW: Street S3	works completed	11/08/2022	24/10/2022	Act. EH/1650477
2334835	RA16 =4x4 CW PH 1.8mx2mx180mm (HW: carriageway defect)	Opposite J/W LinkRoad	HW: Street S2 PR1/2	works completed	15/08/2022	16/08/2022	Act. EH/1648313
2337575	HW: Provision of TM		Provision of TM	works completed	24/10/2022	24/10/2022	Act. EH/1650479
2340974	RA 8=2x4 CW PH 1.5mx0.6mx85mm (HW: carriageway defect)	Between Glazenwood Cottage and Perry Green Farm	HW: Street S2 Local	works completed	10/01/2023	11/01/2023	Act. EH/1653407