

Effective: 07/06/2024 to 18/03/2025
 Enquiry Number: 2967970 to 2967970
 Display Action Officer: No

Insp. Batch No.: Up to 7073501
 Job Number: 2386255 to 2386255
 Site: HOLLOW ROAD (3901012)

Site: HOLLOW ROAD (3901012)

Locality: KELVEDON, ESSEX

Area: Kelvedon

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|-----------------------------------|-----------------------------------------------------------------------------------------------|----------------|-----------------------------------------------------------------------------------------------------|---------------------------------------|----------|----------------|--------------------|---------|
| Asset: | 1,000.00 | Asset - Locn.: | 3901012_1000 - ZC188 // | Feature Type: PR2 Road | | Area: Kelvedon | | |
| Batch: 7073501 - Inspection Batch | | | | Route: Area 21 Mar/Jun/Sep/Dec Driven | | | Date: 17/03/2025 | |
| 3883233 | RA12=3x4. Breaking up at edge. 1.4m x 0.4m x 120mm | 14/03/2025 | Between Lingwoods & The Plantation | HW: carriageway defect | Internal | | Committed | 2386215 |
| 3883763 | RANSA 2 = 2 x 1, Breaking up at edge. 0.4m x 0.3m x 60mm 2200mm x 1000mm x >50mm | 17/03/2025 | LON: 0.6715231, LAT: 51.8406029 | HW: carriageway defect | Internal | | Action Required | |
| 3883478 | RA9=3x3. Breaking up near verge edge. 0.6m x 0.4m x 90mm. NSMM | 14/03/2025 | Right side from Kelvedon to Silverend just after blind bend from Felix Place. O/S Cotcroft Cottage. | HW: carriageway defect | Internal | | Committed | 2386255 |
| 3883480 | RANSA 6 = 2 x 3, Breaking up at edge. 0.3m x 0.1m x 70mm 1550mm x 750mm x >50mm | 14/03/2025 | LON: 0.6815968, LAT: 51.8374481 | HW: carriageway defect | Internal | | Action Required | |
| 3883762 | RANSA 2 = 2 x 1, 1250mm x 400mm x >40mm | 17/03/2025 | LON: 0.67157, LAT: 51.840577 | HW: carriageway defect | Internal | | Action Required | |
| 3883767 | RANSA 2 = 1 x 2, Breaking up at edge. 0.2m x 0.2m x 50mm 1850mm x 1200mm x >50mm | 17/03/2025 | LON: 0.6765147, LAT: 51.8386726 | HW: carriageway defect | Internal | | Action Required | |
| 3883216 | RA2=2x1. Breaking up in centre. 0.6m x 0.4m x 60mm | 14/03/2025 | Between Lingwoods and the plantation | HW: carriageway defect | Internal | | Action Required | |
| 3883482 | RANSA 6 = 2 x 3, Breaking up at edge. 0.3m x 0.1m x 70mm 750mm x 800mm x >50mm | 14/03/2025 | LON: 0.6817178, LAT: 51.8374023 | HW: carriageway defect | Internal | | Action Required | |
| 3883768 | RANSA 2 = 1 x 2, Breaking up at edge. 1.0m x 0.2m x 50mm 4350mm x 1750mm x >50mm | 17/03/2025 | LON: 0.68652, LAT: 51.8373489 | HW: carriageway defect | Internal | | Action Required | |
| 3883765 | RANSA 4 = 1 x 4, 6950mm x 1800mm x >30mm. DUPLICATE | 17/03/2025 | LON: 0.676349, LAT: 51.838748 | HW: carriageway defect | Internal | | No Action Required | |
| 3883481 | RANSA 6 = 2 x 3, Breaking up at edge. 0.3m x 0.1m x 70mm 850mm x 750mm x >50mm | 14/03/2025 | LON: 0.681681, LAT: 51.8374138 | HW: carriageway defect | Internal | | Action Required | |
| 3883764 | RANSA 4 = 1 x 4, Breaking up at edge, 1200mm x 300mm x 50mm | 17/03/2025 | LON: 0.676349, LAT: 51.838748 | HW: carriageway defect | Internal | | Action Required | |
| 3883479 | RA8=2x4. Breaking up at edge. 0.8m x 0.4m x 80mm. NSMM | 14/03/2025 | Opp Cotcroft Cottage | HW: carriageway defect | Internal | | Committed | 2386256 |
| 3833444 | RANSA 4 = 1 x 4, 6950mm x 1800mm x >30mm | 13/09/2024 | LON: 0.676349, LAT: 51.838748 | HW: carriageway defect | Internal | | No Action Required | |
| Batch: 7062742 - Inspection Batch | | | | Route: Area 21 Mar/Jun/Sep/Dec Driven | | | Date: 13/08/2024 | |
| 3822277 | RANSA 4 = 1 x 4, no lorries sign damaged, faded 50%, twisted and leaning into bush, 0mm x 0mm | 13/08/2024 | LON: 0.675441, LAT: 51.8393707; DETAILS: os farm track to garden house | HW: roadsign damaged | Internal | | Action Required | |
| 3822278 | RANSA 4 = 1 x 4, no lorries sign damaged, faded 50%, twisted and leaning into bush, 0mm x 0mm | 13/08/2024 | LON: 0.675441, LAT: 51.8393707; DETAILS: os farm track to garden house | HW: roadsign damaged | Internal | | Action Required | |

Effective: 07/06/2024 to 18/03/2025
 Enquiry Number: 2967970 to 2967970
 Display Action Officer: No

Insp. Batch No.: Up to 7073501
 Job Number: 2386255 to 2386255
 Site: HOLLOW ROAD (3901012)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|------------|----------------------------------------------------------------------------|----------------|-----------------------------------------------------------------------------------------------------|--------------------------------|----------|--------------|--------------------|------------|
| Asset: | 1,000.00 | Asset - Locn.: | 3901012_1000 - ZC188 // | Feature Type: | PR2 Road | | Area: | Kelvedon |
| Batch: | 7062742 - Inspection Batch | | Route: | Area 21 Mar/Jun/Sep/Dec Driven | | | Date: | 13/08/2024 |
| 3822273 | RANSA 4 = 1 x 4, no lorries sign faded 50% | 13/08/2024 | LON: 0.675441, LAT: 51.8393707; DETAILS: os farm track to garden house | HW: roadsign damaged | Internal | | Action Required | |
| 3822264 | RANSA 2 = 1 x 2, cw eroded, 1000mm x 350mm x >50mm | 13/08/2024 | LON: 0.687304, LAT: 51.8370895; DETAILS: os driveway to plantation house | HW: carriageway defect | Internal | | Action Required | |
| 3822243 | RANSA 4 = 1 x 4, 30mph/national speed limit sign damaged leaning into bush | 13/08/2024 | LON: 0.6878329, LAT: 51.8368835 approx 40m from lingwoods house | HW: roadsign damaged | Internal | | Action Required | |
| Batch: | 7044016 - Inspection Batch | | Route: | adhoc route | | | Date: | 13/06/2024 |
| 3801069 | RA6=3x2. Breaking up at verge edge. 1.2m x 0.2m x 80mm. | 13/06/2024 | Left side from Kelvedon to Silverend. Past Felix Place. O/S Cotcroft Cottage. | HW: carriageway defect | Internal | | Action Required | |
| Batch: | 7042356 - Inspection Batch | | Route: | adhoc route | | | Date: | 07/06/2024 |
| 3799154 | RA6=3x2. Breaking up at verge edge. 1.2m x 0.2m x 80mm. | 07/06/2024 | Left side from Kelvedon to Silverend. Past Felix Place. O/S Cotcroft Cottage. | HW: carriageway defect | Internal | | No Action Required | |
| Batch: | 7042349 - Inspection Batch | | Route: | adhoc route | | | Date: | 07/06/2024 |
| 3799148 | RA6=3x2. Breaking up near verge edge. 0.8m x 0.2m x 70mm. | 07/06/2024 | After blind bend from Felix Place left side from Kelvedon to Silverend. O/S rear Cotcroft Cottage. | HW: carriageway defect | Internal | | Action Required | |
| Batch: | 7042348 - Inspection Batch | | Route: | adhoc route | | | Date: | 07/06/2024 |
| 3799147 | RA4=1x4. Breaking up near verge edge. 5.0m x 0.1m x 50mm. | 07/06/2024 | After blind bend on left hand side. Kelvedon to Silverend. O/S back of Cotcroft cottage. | HW: carriageway defect | Internal | | Action Required | |
| Batch: | 7042343 - Inspection Batch | | Route: | adhoc route | | | Date: | 07/06/2024 |
| 3799142 | RA16=4x4. CWPB Breaking up near verge edge. 1.7m x 0.7m x 100mm. | 07/06/2024 | Left side from Kelvedon to Silverend, approximately 30m before blind bend. | HW: carriageway defect | Internal | | Committed | 2368778 |
| Batch: | 7042325 - Inspection Batch | | Route: | adhoc route | | | Date: | 07/06/2024 |
| 3799126 | RA4=1x4. Breaking up near stone wall. 0.6m x 0.3m x 50mm. | 07/06/2024 | O/S Felix Place. Adj to stone wall. | HW: carriageway defect | Internal | | Action Required | |
| Batch: | 7042324 - Inspection Batch | | Route: | adhoc route | | | Date: | 07/06/2024 |
| 3799125 | RA6=3x2. Breaking up next to stone wall. 0.9m x 0.3m x 70mm | 07/06/2024 | O/S Felix Place | HW: carriageway defect | Internal | | Action Required | |
| Batch: | 7042320 - Inspection Batch | | Route: | adhoc route | | | Date: | 07/06/2024 |
| 3799122 | RA6=2x3. Breaking up near verge edge. 0.6m x 0.4m x 70mm | 07/06/2024 | Right side from Kelvedon to Silverend just after blind bend from Felix Place. O/S Cotcroft Cottage. | HW: carriageway defect | Internal | | No Action Required | |
| Batch: | 7042315 - Inspection Batch | | Route: | adhoc route | | | Date: | 07/06/2024 |
| 3799118 | RA8=2x4. Breaking up near verge edge. 4.0m x 0.5m x 90mm at deepest point. | 07/06/2024 | Left hand side from Kelvedon to Silverend, after blind bend from Felix Place. | HW: carriageway defect | Internal | | Committed | 2368774 |

Effective: 07/06/2024 to 18/03/2025

Insp. Batch No.: Up to 7073501

Enquiry Number: 2967970 to 2967970

Job Number: 2386255 to 2386255

Display Action Officer: No

Site: HOLLOW ROAD (3901012)

Customer Services

Enquiry No.: 2967970

Logged by: CRM Connector

on: 14/03/2025 15:45

Service: Maintenance

Subject: carriageway defects

Classification: fault reports

Enquiry Ref: M24TP001856

Desc.: Customer Selection=Deeper than 5cm,A large pothole which is in the driving line as you exit the sharp left hand bend

Location: INSURANCE CLAIM - Pothole on Hollow Road as you head towards Kelvedon, the pothole is on the hill as you exit the sharp left hand bend. This section of road has poor visibility due to lack of natural light which is blocked by the overgrown foliage.

Contact:

Plot Number: 1,000.00

Feature Id - Location: 3901012_1000 - ZC188 //

Feature Type: PR2 Road

Job Number: 2386255

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|---------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|---------------------|------------------------|------------|----------------|-----------------|
| | Asset: 1,000.00 | Asset - Locn.: 3901012_1000 - ZC188 // | | Feature Type: PR2 Road | | Area: Kelvedon | |
| 2386255 | RA9=3x3. Breaking up near verge edge. 0.6m x 0.4m x 90mm. NSMM (HW: carriageway defect) | Right side from Kelvedon to Silverend just after blind bend from Felix Place. O/S Cotcroft Cottage. | HW: Street S2 PR1/2 | made safe | 14/03/2025 | 18/03/2025 | Act. EH/1690835 |