

**Effective:** 01/01/2025 to 30/05/2025  
**Work Ref. Like:** 1001397383  
**Site:** LONDON ROAD (39901107)

**Organisation:** Cadent Gas Ltd (0010501)  
**Display Action Officer:** No

**Site:** LONDON ROAD (39901107)

**Locality:** CLACTON ON SEA, ESSEX

**Area:** Great Clacton

### Street Works Inspections

**Organisation:** Cadent Gas Ltd (0010501)

**Works Ref:** 1001397383

<b>Group No:</b> 24	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 23/05/2025 07:26:07	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site					
<b>Defect Notes:</b> Works in progress operatives on site					
<b>Group No:</b> 23	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 23/05/2025 07:23:20	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Defect Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Group No:</b> 22	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 22/05/2025 08:01:57	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site					
<b>Defect Notes:</b> Works in progress operatives on site					
<b>Group No:</b> 21	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 22/05/2025 08:00:56	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Defect Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Group No:</b> 20	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 20/05/2025 09:28:09	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site					
<b>Defect Notes:</b> Works in progress operatives on site					
<b>Group No:</b> 19	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 20/05/2025 09:24:06	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Defect Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					

**Effective:** 01/01/2025 to 30/05/2025  
**Work Ref. Like:** 1001397383  
**Site:** LONDON ROAD (39901107)

**Organisation:** Cadent Gas Ltd (0010501)  
**Display Action Officer:** No

### Street Works Inspections

**Organisation:** Cadent Gas Ltd (0010501)

**Works Ref:** 1001397383

<b>Group No:</b> 18	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 15/05/2025 11:00:24	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Defect Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Group No:</b> 17	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 15/05/2025 10:59:46	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Defect Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Group No:</b> 16	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 13/05/2025 15:28:35	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> No	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> 665345	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress no operatives on site					
<b>Defect Notes:</b> Works in progress no operatives on site					
<b>Group No:</b> 15	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 13/05/2025 15:20:17	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Failed (Lower Risk/Non Dangerous)	<b>Site Informed:</b> No	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> 665345		<b>Defect No:</b> 665345	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress no operatives on site, Barriers not secured onto compound, discarded Road narrows sign by lamp post, Barriers rectified by Inspector and signage now in compound					
<b>Defect Notes:</b> Works in progress no operatives on site, Barriers not secured onto compound, discarded Road narrows sign by lamp post, Barriers rectified by Inspector and signage now in compound					
<b>Group No:</b> 14	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 12/05/2025 12:24:29	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Defect Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Group No:</b> 13	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 12/05/2025 12:20:35	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Defect Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					

**Effective:** 01/01/2025 to 30/05/2025  
**Work Ref. Like:** 1001397383  
**Site:** LONDON ROAD (39901107)

**Organisation:** Cadent Gas Ltd (0010501)  
**Display Action Officer:** No

### Street Works Inspections

**Organisation:** Cadent Gas Ltd (0010501)

**Works Ref:** 1001397383

<b>Group No:</b> 12	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 09/05/2025 09:21:16	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Defect Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Group No:</b> 11	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 09/05/2025 09:18:54	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Defect Notes:</b> Works in progress operatives on site, as per agreement with Ben Runham ,in conjunction with 1001397386					
<b>Group No:</b> 10	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 07/05/2025 11:45:15	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, Reinstatement of excavations in place.					
<b>Defect Notes:</b> Works in progress operatives on site, Reinstatement of excavations in place.					
<b>Group No:</b> 9	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 07/05/2025 11:44:25	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, Reinstatement of excavations in place.					
<b>Defect Notes:</b> Works in progress operatives on site, Reinstatement of excavations in place.					
<b>Group No:</b> 8	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 06/05/2025 11:33:03	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> 664954	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site					
<b>Defect Notes:</b> Works in progress operatives on site					
<b>Group No:</b> 7	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 06/05/2025 11:31:16	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Failed (Lower Risk/Non Dangerous)	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> 664954		<b>Defect No:</b> 664954	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, Barriers not secured properly around Open excavations					
<b>Defect Notes:</b> Works in progress operatives on site, Barriers not secured properly around Open excavations					

**Effective:** 01/01/2025 to 30/05/2025  
**Work Ref. Like:** 1001397383  
**Site:** LONDON ROAD (39901107)

**Organisation:** Cadent Gas Ltd (0010501)  
**Display Action Officer:** No

### Street Works Inspections

**Organisation:** Cadent Gas Ltd (0010501)

**Works Ref:** 1001397383

<b>Group No:</b> 6	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 01/05/2025 13:41:57	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> 664810	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress only TM operatives on site					
<b>Defect Notes:</b> Works in progress only TM operatives on site					
<b>Group No:</b> 5	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 01/05/2025 13:40:03	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Failed (Lower Risk/Non Dangerous)	<b>Site Informed:</b> No	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> 664810		<b>Defect No:</b> 664810	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress only TM operatives on site, Open barriers, barriers not secured correctly, Directional Arrows missing, taper cones missing. Sideways cones missing					
<b>Defect Notes:</b> Works in progress only TM operatives on site, Open barriers, barriers not secured correctly, Directional Arrows missing, taper cones missing. Sideways cones missing					
<b>Group No:</b> 4	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 25/04/2025 09:06:20	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site					
<b>Defect Notes:</b> Works in progress operatives on site					
<b>Group No:</b> 3	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 25/04/2025 09:05:32	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Routine - Live site		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site					
<b>Defect Notes:</b> Works in progress operatives on site					
<b>Group No:</b> 2	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 23/04/2025 11:17:24	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Permit Conditions		<b>Outcome:</b> Non-Compliant (with Conditions)	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> 664381		<b>Defect No:</b> 664381	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress only one TM operative maintaining closure . Two required as per you permit conditions					
<b>Defect Notes:</b> Works in progress only one TM operative maintaining closure . Two required as per you permit conditions					
<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Essex County Council - Work Promoter	<b>Inspected:</b> 23/04/2025 11:15:09	<b>Sampled:</b> No	<b>Sampled Site No:</b>
<b>Category:</b> Category A		<b>Outcome:</b> Passed	<b>Site Informed:</b> Yes	<b>Sign./Light./Guard. Inadequacy:</b> No	
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Location:</b> Outside 128, Actual Depth: 0.9	<b>Position:</b> Verge	<b>Site Post Code:</b>
		<b>Tel:</b>			
<b>Insp. Notes:</b> Works in progress operatives on site, Site could do more more cones on sideways these are being delivered asap					
<b>Defect Notes:</b> Works in progress operatives on site, Site could do more more cones on sideways these are being delivered asap					

Effective: 01/01/2025 to 30/05/2025

Work Ref. Like: 1001397383

Site: LONDON ROAD (39901107)

Organisation: Cadent Gas Ltd (0010501)

Display Action Officer: No

Street Works Notices

Organisation: Cadent Gas Ltd (0010501)

Works Ref: 1001397383

Notice Type: Inspection Auto Acknowledged

Work Status: In Progress

Work Type: EToN 4+: Major

Version: 21

Start: 21/04/2025 07:24:00

Issued: 29/05/2025 16:30:23

Est. End: 30/05/2025

Work Desc: MAINS REPLACEMENT PERMIT TO ABANDON 440M OF CI MAIN AND REPLACE IT WITH 440M OF PE MAIN AND REPLACE 40 SERVICES.

Footway closure: Pedestrian walkway will be provided

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside 128, Actual Depth: 0.9	Verge	Up to 1.5 Metres of Cover	1.10	1.00	A Permanent Reinstatement	02/05/2025		02/05/2025	27/05/2025
2	Outside 128, Actual Depth: 0.9	Footway	Up to 1.5 Metres of Cover	1.90	1.40	A Permanent Reinstatement	02/05/2025		02/05/2025	
3	Outside 130, Actual Depth: 0.9	Verge	Up to 1.5 Metres of Cover	0.90	0.90	A Permanent Reinstatement	02/05/2025		02/05/2025	
4	Outside 132, Actual Depth: 1.1	Verge	Up to 1.5 Metres of Cover	1.00	0.80	A Permanent Reinstatement	02/05/2025		02/05/2025	
5	Outside 134, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	1.20	0.90	A Permanent Reinstatement	02/05/2025		02/05/2025	
6	Outside 134, Actual Depth: 1	Verge	Up to 1.5 Metres of Cover	2.00	0.60	A Permanent Reinstatement	02/05/2025		02/05/2025	
7	Opposite Opposite 115, Actual Depth: 0.9	Verge	Up to 1.5 Metres of Cover	1.60	0.60	A Permanent Reinstatement	02/05/2025		02/05/2025	
8	Outside Next to lamp column j12 near roundabout, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	4.50	1.60	A Permanent Reinstatement	07/05/2025		07/05/2025	
9	Outside Next to lamp column j12 near roundabout, Actual Depth: 1	Carriageway	Up to 1.5 Metres of Cover	2.90	0.80	A Permanent Reinstatement	07/05/2025		07/05/2025	
10	Outside 136, Actual Depth: 0.9	Footway	Up to 1.5 Metres of Cover	1.30	1.20	A Permanent Reinstatement	07/05/2025		07/05/2025	
11	Outside 136, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	1.20	1.00	A Permanent Reinstatement	07/05/2025		07/05/2025	
12	Outside 136, Actual Depth: 0.9	Footway	Up to 1.5 Metres of Cover	1.50	0.90	A Permanent Reinstatement	07/05/2025		07/05/2025	
13	Opposite Opposite 115, Actual Depth: 0.9	Footway	Up to 1.5 Metres of Cover	1.60	1.00	A Permanent Reinstatement	07/05/2025		07/05/2025	
14	Opposite Opposite 115, Actual Depth: 0.7	Carriageway	Up to 1.5 Metres of Cover	3.50	0.70	A Permanent Reinstatement	07/05/2025		07/05/2025	
15	Outside 134, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	1.90	0.40	A Permanent Reinstatement	07/05/2025		07/05/2025	
16	Outside 132, Actual Depth: 0.95	Footway	Up to 1.5 Metres of Cover	2.00	0.90	A Permanent Reinstatement	07/05/2025		07/05/2025	
17	Outside 132, Actual Depth: 1.1	Carriageway	Up to 1.5 Metres of Cover	1.30	1.00	A Permanent Reinstatement	07/05/2025		07/05/2025	
18	Outside 130, Actual Depth: 0.9	Footway	Up to 1.5 Metres of Cover	1.60	0.90	A Permanent Reinstatement	07/05/2025		07/05/2025	