


Date 29 Sep 2022 10:16
 USRN 2002562
 Inspection Batch Number 6907007

Documents

Image



Inspection Batch Description Inspection Batch
 Inspection Batch Inspection Route Name Area 14 Annual Aug Walked

Defects

Conditions

Observation Type Name	Grade Code	Notes
Carriageway Excellent	000	
Carriageway Good	000	
Carriageway Fair	000	
Carriageway Requires Improvemt	000	
cycleway condition	NA	
surface state	DRY	Walked JAND
Footway Presence	2	
Footway Excellent	000	
Footway Good	040	
Footway Fair	040	Tarmac is cracking
Footway Requires Improvement	020	


Observation Type Name	Grade Code	Notes
Re-inspection required	NA	
Reduced inspection	NA	

Feature Site Central Site Name NETHER MAYNE
Feature Site Central Site Area Description Basildon
Plot Number 1004

Date 21 Apr 2021 11:05
USRN 2002562
Inspection Batch Number 6791216

Documents

Image



Inspection Batch Description Inspection Batch
Inspection Batch Inspection Route Name Area 26 Monthly Walked

Defects

Conditions

Observation Type Name	Grade Code	Notes
Carriageway Good	000	
Carriageway Fair	000	
Carriageway Requires Improvemt	000	
cycleway condition	NA	
surface state	DRY	
Footway Presence	2	
Footway Excellent	000	
Footway Good	040	
Footway Fair	040	Tarmac is cracking

Observation Type Name	Grade Code	Notes
Footway Requires Improvement	020	
Reduced inspection	RI	
Re-inspection required	NA	
Carriageway Excellent	000	

Feature Site Central Site Name NETHER MAYNE
Feature Site Central Site Area Description Basildon
Plot Number 1004

Date 17 Mar 2021 10:33
USRN 2002562
Inspection Batch Number 6782243

Documents

Image



Image



Inspection Batch Description Inspection Batch
Inspection Batch Inspection Route Name Area 26 Monthly Walked

Defects

Conditions

Observation Type Name	Grade Code	Notes
Carriageway Excellent	000	
Carriageway Good	000	
Carriageway Fair	000	
Carriageway Requires Improvemnt	000	
cycleway condition	NA	
Footway Presence	2	
Footway Excellent	000	
Footway Good	040	
Footway Fair	040	Tarmac is cracking
Footway Requires Improvement	020	
Reduced inspection	RI	
Re-inspection required	NA	
surface state	DRY	

Feature Site Central Site Name NETHER MAYNE
Feature Site Central Site Area Description Basildon
Plot Number 1004

Date 10 Jun 2021 14:50
USRN 2002562
Inspection Batch Number 6804996

Documents

Image



Inspection Batch Description

Inspection Batch

Inspection Batch Inspection Route Name

Area 26 Monthly Walked

Defects

Conditions

Observation Type Name	Grade Code	Notes
Carriageway Good	000	
Carriageway Fair	000	
Carriageway Requires Improvemnt	000	
cycleway condition	NA	
surface state	DRY	
Footway Presence	2	
Footway Excellent	000	
Footway Good	040	
Footway Fair	040	Tarmac is cracking
Footway Requires Improvement	020	
Reduced inspection	RI	
Re-inspection required	NA	
Carriageway Excellent	000	

Feature Site Central Site Name

NETHER MAYNE

Feature Site Central Site Area Description

Basildon

Plot Number

1004

Date

02 Sep 2021 14:11

USRN

2002562

Inspection Batch Number

6824078

Image



Image



Inspection Batch Description

Inspection Batch

Inspection Batch Inspection Route Name

Area 14 Annual Aug Walked

Defects

Conditions

Observation Type Name	Grade Code	Notes
Carriageway Excellent	000	
Carriageway Good	000	
Carriageway Fair	000	
Carriageway Requires Improvemnt	000	
cycleway condition	NA	

Observation Type Name	Grade Code	Notes
Footway Presence	2	
Footway Excellent	000	
Footway Good	040	
Footway Fair	040	Tarmac is cracking
Footway Requires Improvement	020	
Reduced inspection	RI	
Re-inspection required	NA	
surface state	DRY	Walked JAND

Feature Site Central Site Name NETHER MAYNE
Feature Site Central Site Area Description Basildon
Plot Number 1004

Date 18 Jan 2021 13:09
USRN 2002562
Inspection Batch Number 6768723
Documents

Image



Image

Inspection Batch Description Inspection Batch
Inspection Batch Inspection Route Name Area 26 Monthly Walked

Defects**Conditions**

Observation Type Name	Grade Code	Notes
Carriageway Excellent	000	
Carriageway Good	000	
Carriageway Fair	000	
Carriageway Requires Improvem	000	
cycleway condition	NA	
Footway Presence	2	
Footway Excellent	000	
Footway Good	040	
Footway Fair	040	Tarmac is cracking
Footway Requires Improvement	020	
Reduced inspection	RI	
Re-inspection required	NA	
surface state	DRY	Walked JAND

Feature Site Central Site Name NETHER MAYNE
Feature Site Central Site Area Description Basildon
Plot Number 1004

Date 12 May 2021 15:12
USRN 2002562
Inspection Batch Number 6797684

Documents

Image



Inspection Batch Description Inspection Batch
Inspection Batch Inspection Route Name Area 26 Monthly Walked

Defects

Conditions

Observation Type Name	Grade Code	Notes
Carriageway Good	000	
Carriageway Fair	000	
Carriageway Requires Improvemt	000	
cycleway condition	NA	
surface state	DRY	
Footway Presence	2	
Footway Excellent	000	
Footway Good	040	
Footway Fair	040	Tarmac is cracking
Footway Requires Improvement	020	
Reduced inspection	RI	
Re-inspection required	NA	
Carriageway Excellent	000	

Feature Site Central Site Name NETHER MAYNE
Feature Site Central Site Area Description Basildon
Plot Number 1004

Date 12 Feb 2021 14:28
USRN 2002562
Inspection Batch Number 6774383

Image



Image



Inspection Batch Description

Inspection Batch

Inspection Batch Inspection Route Name

Area 26 Monthly Walked

Defects

Conditions

Observation Type Name	Grade Code	Notes
Carriageway Good	000	
Carriageway Fair	000	
Carriageway Requires Improvemt	000	
cycleway condition	NA	
surface state	DRY	Walked JAND

Observation Type Name	Grade Code	Notes
Footway Presence	2	
Footway Excellent	000	
Footway Good	040	
Footway Fair	040	Tarmac is cracking
Footway Requires Improvement	020	
Reduced inspection	RI	
Re-inspection required	NA	
Carriageway Excellent	000	

Feature Site Central Site Name NETHER MAYNE

Feature Site Central Site Area Description Basildon

Plot Number 1004