

Effective: 11/12/2025 to 16/12/2025
Site: KINGS PARADE (39901013)

Display Action Officer: No

Site: KINGS PARADE (39901013)

Locality: HOLLAND ON SEA, ESSEX

Area: Great Clacton

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	39901013_1000 - ZU874 //	Feature Type:	PR2 Road		Area:	Great Clacton
Batch:	7183233 - Inspection Batch			Route:	adhoc route		Date:	16/12/2025
3957013	RANSA gang sent to make safe TMP bollard following a collision	16/12/2025	KINGS PARADE, HOLLAND ON SEA Traffic island at j/w York Road	HW: bollard damaged	Internal		Committed	2399455
Batch:	7182082 - Inspection Batch			Route:	Area 01 Annual Nov Walked		Date:	11/12/2025
3955434	RESOLVED RA4=1x4 1.0m x 0.6m x upto 60mm CW breaking up	11/12/2025	Os 31	HW: carriageway defect	Internal		No Action Required	
3955463	Ra4=1x4 fw sunk 1.0mx1.0m40mm	11/12/2025	LC 52	HW: footway defect	Internal		Action Required	
3955436	RESOLVED RA6=3x2, holing behind kerbs, 1.1x0.9x70mm, superseded.	11/12/2025	O/s 41	HW: footway defect	Internal		No Action Required	
3955437	RESOLVED Ra3=3x1, fway eroding, 1.0m x 0.2m x 20mm	11/12/2025	Os 41/43	HW: footway defect	Internal		No Action Required	
3955438	RESOLVED RA2=1x2, Low kerbs and ponding, 3.3m.	11/12/2025	O/s 43	HW: kerb mis-aligned	Internal		No Action Required	
3955447	Ra8=4x2 fwdf 0.9mx0.9mx130mm	11/12/2025	Os 133	HW: footway defect	Internal		Committed	2399093
3955440	RA9=3=3 fwdf 1.2mx0.5mx120mm	11/12/2025	Os 79	HW: footway defect	Internal		Committed	2399087
3955441	Ra8=4x2 Verge sunk 1.8mx1.8mx500mm	11/12/2025	Os 79	HW: verge damaged	Internal		Committed	2399088
3955442	Ra8=4x2 fwdf sink hole ar back 1.2mx0.5mx300mm	11/12/2025	Os 85	HW: footway defect	Internal		Committed	2399089
3955443	Rs8=4x2 4x holes in verge over area 2.2mx1.8mx500mm	11/12/2025	Os 85	HW: verge damaged	Internal		Committed	2399090
3955444	Ra8=4x2 fw void 0.8mx0.4mx400mm	11/12/2025	Os Kings Court	HW: footway defect	Internal		Committed	2399091
3955445	Ra8=4x2 TMP missing	11/12/2025	Os York Road car park	HW: bollard missing	Internal		Committed	2399092
3955446	RESOLVED Ra4=2x2 0.8x0.4xupto35mm f/w sunk round water box	11/12/2025	O/s121	HW: footway defect	Internal		No Action Required	
3955439	RESOLVED Ra2=1x2 5mx0.4x20mm f/w breaking out kerb edge	11/12/2025	O/s45	HW: footway defect	Internal		No Action Required	
3955448	RESOLVED Ra2=2x1, edge of vx eroding, 1.1m x 0.2m x 30mm	11/12/2025	Os 137	HW: footway defect	Internal		No Action Required	
3955449	Ra8=2x4 fwdf at bt cover 1.0mx0.2mx40mm	11/12/2025	By lc 32	HW: footway defect	Internal		Committed	2399094
3955450	RESOLVED RANSA RA4=1x4 >0.2m x >0.2m x > 50mm CW breaking up along kerb edge	11/12/2025	Os Medusa Court	HW: carriageway defect	Internal		No Action Required	
3955451	RESOLVED RA4=2x2, f/w surface subsiding, sunk, 0.9m x0.45m x 50mm, dbm	11/12/2025	O/s 65 Cliff Rd	HW: footway defect	Internal		No Action Required	
3955452	RESOLVED RA4=4x1, fway holing along kerb edge of va, 2.7m x 0.5m x 50mm	11/12/2025	O/s 161	HW: footway defect	Internal		No Action Required	
3955453	RESOLVED RA4=4x1, surface breaking out behind kerbs, 1.0m x 0.3m x upto 50mm.	11/12/2025	O/s 163 on vx	HW: footway defect	Internal		No Action Required	
3955454	Ra4=1x4 fw surface erosion 9.0mx1.4mxup to 25mm	11/12/2025	Os 177	HW: footway defect	Internal		Action Required	
3955455	Ra6=3x2 cw raised 0.9mx0.5mx80mm	11/12/2025	Os 179	HW: carriageway defect	Internal		Action Required	

Effective: 11/12/2025 to 16/12/2025
Site: KINGS PARADE (39901013)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	39901013_1000 - ZU874 //	Feature Type:	PR2 Road		Area:	Great Clacton
Batch:	7182082 - Inspection Batch		Route:	Area 01 Annual Nov Walked			Date:	11/12/2025
3955456	Ra4=1x4 cwdf at edge of patch 0.9mx0.3mxup to 50mm	11/12/2025	Op Village Green. near LC 4	HW: carriageway defect	Internal		Action Required	
3955457	Ra4=1x4 missing Parking sign	11/12/2025	Os 205	HW: parking partnership defect	Internal		No Action Required	
3955458	RESOLVED RA1=1x1, verge eroded around base of lamp column 46	11/12/2025	O/s 207	HW: verge damaged	Internal		No Action Required	
3955459	Ra1=1x1 1 kerb sunk 0.9mx0.1mx20mm	11/12/2025	Os 211	HW: kerb mis-aligned	Internal		Action Required	
3955460	Ra9=3x3 cw raised 3.3mx0.4mx100mm	11/12/2025	Os 215	HW: carriageway defect	Internal		Committed	2399095
3955461	Ra9=3x3 cw raised 4.5mx0.4mx90mm	11/12/2025	Os 217	HW: carriageway defect	Internal		Committed	2399096
3955462	Ra4=2x2 fwdf 2.7mx0.8mxup to 35mm	11/12/2025	Os 223	HW: footway defect	Internal		Action Required	
3955435	Ra2=2x1 kerb chipped 0.2mx0.1mx50mm	11/12/2025	Os 37	HW: kerb damaged	Internal		Action Required	
3955464	RESOLVED RA4=1x4 1.2m x 0.5m x upto 60mm CW breaking up in old patch	11/12/2025	Os Vinyard Cou	HW: carriageway defect	Internal		No Action Required	
3955433	RESOLVED RA4=1x4 1.1m x 0.6m x upto 60mm CW breaking up	11/12/2025	Os 27	HW: carriageway defect	Internal		No Action Required	

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order	
Asset:	1,000.00	Asset - Locn.:	39901013_1000 - ZU874 //	Feature Type:	PR2 Road		Area:	Great Clacton
2312859	CLACTON CAR PARK SIGNS. Sign replacement.	In footway.	change default	job held	02/03/2021			
2321445	Remove 2 No stump of old 180mm sign posts after P2 make safe.	Opposite The Esplanade jct	HW: S Follow up	job authorised	21/09/2021			
2399087	RA9=3=3 fwdf 1.2mx0.5mx120mm (HW: footway defect)	Os 79	HW: Street S2 Local	works completed	11/12/2025	12/12/2025	Act. EH/1701537	
2399088	Ra8=4x2 Verge sunk 1.8mx1.8mx500mm (HW: verge damaged)	Os 79	HW: Street S2 Local	works completed	11/12/2025	17/12/2025	Act. EH/1701537	
2399089	Ra8=4x2 fwdf sink hole ar back 1.2mx0.5mx300mm (HW: footway defect)	Os 85	HW: Street S2 Local	works completed	11/12/2025	12/12/2025	Act. EH/1701537	
2399090	Rs8=4x2 4x holes in verge over area 2.2mx1.8mx500mm (HW: verge damaged)	Os 85	HW: Street S2 Local	works completed	11/12/2025	17/12/2025	Act. EH/1701537	
2399091	Ra8=4x2 fw void 0.8mx0.4mx400mm (HW: footway defect)	Os Kings Court	HW: Street S2 Local	works completed	11/12/2025	15/12/2025	Act. EH/1701537	
2399092	Ra8=4x2 TMP missing (HW: bollard missing)	Os York Road car park	HW: Street S2 PR1/2	works completed	11/12/2025	12/12/2025	Act. EH/1701537	
2399093	Ra8=4x2 fwdf 0.9mx0.9mx130mm (HW: footway defect)	Os 133	HW: Street S2 Local	works completed	11/12/2025	18/12/2025	Act. EH/1701537	
2399094	Ra8=2x4 fwdf at bt cover 1.0mx0.2mx40mm (HW: footway defect)	By lc 32	HW: Street S2 Local	made safe	11/12/2025	18/12/2025	Act. EH/1701537	

Effective: 11/12/2025 to 16/12/2025
 Site: KINGS PARADE (39901013)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: 39901013_1000 - ZU874 //		Feature Type: PR2 Road		Area: Great Clacton	
2399095	Ra9=3x3 cw raised 3.3mx0.4mx100mm (HW: carriageway defect)	Os 215	HW: Street S2 PR1/2	works completed	11/12/2025	15/12/2025	Act. EH/1701537
2399096	Ra9=3x3 cw raised 4.5mx0.4mx90mm (HW: carriageway defect)	Os 217	HW: Street S2 PR1/2	works completed	11/12/2025	15/12/2025	Act. EH/1701537
2399391	CW Patching to 100mm - 14.74m2 & Renew 10.6m Double yellow lining	Os 215 & 217 - W3W //origin.rings.bench	HW: S Follow up	Passed to supervisor	16/12/2025		
2399455	RANSA gang sent to make safe TMP bollard following a collision (HW: bollard damaged)	KINGS PARADE, HOLLAND ON SEA Traffic island at j/w York Road	HW: Street S1	works completed	16/12/2025	16/12/2025	Act. EH/1701755